

**Project ID** : 8520-01-05**Title** : HAYWARD - CLAM LAKE**Region** : NORTHWEST**Route** : STH 077**Sub Title** : USH 63 TO CTH K**County** : SAWYER**Soils and Pavements**

Soils - General		
✓	Soils Report **	Preliminary report only for Cold In-Place Recycle project.
	Select subgrade required	Within mapped area for inclusion. Not req'd for CIR projects.
	Type and quality of available material	
	Predominant soil type	Silty Loam
	Design Group Index	14
	Soil Support Value	3.9
Soils - Roadway Conditions		
✓	Potential frost susceptible soils	No known frost heaves at this time. Need input from Maintenance.
	Marsh excavation	Marshes excavated as part of 1993 project.
	Bedrock or outcrops to be encountered	
	Slope stability issues	
	--->Cut sections	
	--->Fill sections	
	High water table	
	Springs/seeps	
	Underdrain problems	
	Excavation below subgrade	
	Floating road core/corduroy	
	Desirable grade line location	
	Two stage soil investigation required	
	Preliminary grade line review required	
	Final grade line review required	
Soils - Borings		
	Soil borings required	
	--->At cut to fill transition	
	--->In cut sections	
	Structure borings required	
Soil Comments		

Cold in-place recycle project will require pavement cores and possibly Ground Penetrating Radar work. Project 8530-05-71 plan pavement thickness is 5" HMA over 12" CABC.

Last updated by KING, ORVILLE D on 01/14/2019

Pavements - General		
<input checked="" type="checkbox"/>	Pavement Design Report **	
<input type="checkbox"/>	Life cycle cost analysis required	
<input type="checkbox"/>	PSI,IRI,PCI Data Year	
<input type="checkbox"/>	Pavement Condition Index (PCI)	Min: Max:
<input type="checkbox"/>	International Roughness Index (IRI)	Min: Max:
<input type="checkbox"/>	Pavement Serviceability Index (PSI)	Min: Max:
Pavement Distress - PC Concrete		
<input type="checkbox"/>	Raveled transverse joints and cracks	
<input type="checkbox"/>	Raveled longitudinal joints and cracks	
<input type="checkbox"/>	Cracked slabs with movement	
<input type="checkbox"/>	Joint faulting	
<input type="checkbox"/>	Surface spall	
Pavement Distress - Asphaltic		
<input type="checkbox"/>	Transverse cracking	
<input type="checkbox"/>	Block cracking	
<input type="checkbox"/>	Alligator cracking	
<input type="checkbox"/>	Raveled surface	
<input type="checkbox"/>	Raveled edge	
Pavements - Evaluation/History		
<input type="checkbox"/>	Existing pavement structure	
<input type="checkbox"/>	Existing pavement condition	
<input type="checkbox"/>	Year of original construction	
<input type="checkbox"/>	Year(s) resurfaced/rehabilitated	
<input type="checkbox"/>	Year(s) rut filled	
<input type="checkbox"/>	Asphaltic Concrete Pavement (ACP)	approximate number of cores at foot intervals
<input type="checkbox"/>	ACP thickness/verification & condition (not recycling cores)	approximate number of cores (at specific locations)
<input type="checkbox"/>	Portland Cement Concrete (PCC) pavement	approximate number of cores at foot intervals
<input type="checkbox"/>	PCC pavement depth verification & joint study (not pay cores)	approximate number of cores (at specific locations)
Pavement - Alternatives		
<input type="checkbox"/>	Alternative Rehab Strategies (include life expectancy and approximate cost per mile)	
No Pavement - Alternatives		
Preliminary proposed alternative		

1/28/19 DCH: This project was changed to a 3.25" mill and overlay (4 MT 58-34V) due to the concerns with the run off the road crashes. Add about 500 tons of Asphaltic Surface for Misc Repairs. 12/7/18 DCH. 8400 AADT. Asbuilt shows 5" HMA over 7" pulverize over base, 14.5% trucks, 1,900,000 esals. Propose No premill (assuming it is allowed), 2.75" HMA (5 MT 58-34V), 4" CIR. If a premill is required, I may recommend a 3.25" mill and overlay. 1000 CY of CIR base repair. Expected life is 12 - 15 yrs.

Pavement Comments**Last updated by HARINGS, DEVIN C on 01/31/2019**