REHABILITATION STRUCTURE SURVEY REPORT
--



Wisconsin Department of Transportation DT1696 4/2017

igtriangleq Grade Separation	Stream Crossing	Culvert
------------------------------	-----------------	---------

□ Railroad □ Retaining Wall □ Noise Barrier

Sign Structure Other:

For guidance see: http://wisconsindot.gov/Pages/doing-bus/eng-consultants/cnslt-rsrces/strct/survey.aspx

Design Project ID	Construction Project ID	Highway (Project Na	ime)			
1196-05-07	1196-05-77	USH 53 NB	USH 53 NB			
Final Plan Due Date	Preliminary Plan Due Date	🛛 Town 🗌 Villag	Town Village City			
4/1/2019	3/01/2019	Dovre				
PS&E Date	Letting Date	County				
5/1/2019	11/12/2019	Barron				
Structure Number	· · · · · · · · · · · · · · · · · · ·	Section	Town		Range	
B-03-0015		26 T32N R10W		R10W		
Station	Latitude: 45Deg 13'17" N	YES INO Structure Located on National Highway System				
130+34	Longitude: 91Deg 34'51"W					
For Survey and CADD Files Horizontal Coordinate System: Barron County. Vertical Datum: NAVD 88		Traffic Forecast Data				
		Design Year	Average Daily Traffic (ADT)	Roadway Design Spe		
Feature On USH 53 NB		Feature On 2014	5550	70MPH	Principal Arterial	
Feature Under Carlson School Drive		Feature Under 1988	ar 3220 55MPH ASSUMED			
Region Contact: Brendan D	Consultant Contact: Jarrod Starren					
(Area Code) Telephone Numb	(Area Code) Telephone Number(s): (715) 720-6261					
Email: brendan.dirkes@d	Email: jstarren@sehinc.com					

Work To Be Performed

				Field Information Required Item Number (see Pages 2–4)
	A.	Structural Repair		· • · · ·
\boxtimes	В.	Overlay		1–3, 10–22, 26–28, 32, 34
		🖾 Concrete Overlay	Asphalt Overlay	
		Polymer Modified Asphalt Overlay	Thin Bonded Polymer Overlay	
		□ Other:		
	C.	New Bearings		3, 8, 9, 22
\boxtimes	D.	New Railings		15–17, 20–23
	Е.	Curb and Sidewalk Repair		2, 3, 16, 22, 23
	F.	Abutment Repair		2, 3, 12, 16
	G.	Pier Repair		2, 3, 12, 16
	Η.	New Deck		1–6, 9, 10, 13–28, 32–34
	١.	Widening		1–28, 30, 32–35
\boxtimes	J.	Joint Repair		2, 3, 8, 16, 19, 22
	K.	Surface Repair		2, 3, 22
	L.	Raising Bridge		3, 6, 9, 16, 20–24
	M.	Slope Stabilization		1–3, 30
	N.	Scour Repair		1, 2 or 3, 16, 19, 21, 27, 29, 31–35
	О.	Painting		16, 22, 24
	Ρ.	Other:		

Field Information Required

If no structure number exists provide the following: Small County Map on which the location of proposed structure is shown in red and any highway relocation in green. In addition, provide Location Map of scale not less than 1" = 2000' showing the structure location and number.

- 1. Most recent inspection report, brief history of bridge construction date, and description of repairs with dates.
- 2. Outline deficient areas on existing structure plan or drawing.
- 3. Photographs of details requiring repairs or modifications, such as: bearings, x-frames, joints, etc. Photograph all deficient areas. Clearly label all photographs.
- □ 4. Provide proposed typical section for roadway and structure showing dimensions and cross slopes.
- □ 5. Survey beam seat or girder elevations at both sides of bridge at all substructure units.
- 6. Provide cross-section elevations at 10 foot intervals extending across the structure and a minimum of 100 feet beyond each end. Sections should be normal to centerline and show elevations at centerline roadway and gutter line. Take elevations along joints and at floor drains.
- □ 7. Show and identify starting stationing on bridge.
- 8. Record measurement, temperature of the structure, and date taken for each of the following:
 - (a) Joint opening measured normal to joint at centerline of roadway and both curb lines.
 - (b) Clearance between girder ends at piers.
 - (c) Distance from front face of abutment backwall to closest point of girder end measured parallel to girder.
 - (d) Temperature of structure determined by averaging top and under deck (if accessible) readings.
- ☑ 9. Fixed and expansion bearings condition and orientation.
- ⊠10. Number and width of proposed pours including construction staging sequence.
- \boxtimes 11. Location of existing construction joints in the deck.
- ⊠12. Estimated Quantities:

Preparation, Decks, Type 1	Sq. Yd. <u>85</u>	
Preparation, Decks, Type 2	Sq. Yd. <u>40</u>	
Full Depth Deck Repair	Sq. Yd. <u>10</u>	Galvanic Anodes? <u>No</u>
Concrete Surface Repair Superstructure	Sq. Ft. <u>N/A</u>	Galvanic Anodes? <u>No</u>
Concrete Surface Repair Substructure	Sq. Ft. <u>1</u>	Galvanic Anodes? <u>No</u>
Curb Repair	LF. <u>N/A</u>	Galvanic Anodes? <u>No</u>

- ⊠13. Sufficiency number: <u>96.8</u> (obtain from HSI Bridge Inventory System)
- ☑ 14. Appraisal and Condition Rating

		Deck Condition	Superstructure Condition	Substructure Condition	Load Capacity Appraisal	Structural EVAL Appraisal	
_	Current	6	6	7	5	6	

□ 15. Load Ratings

	Inventory	Operational
Current Calculated Date: 6/18/2013	HS 18	HS 31
After Completed by Bridge Designer		

☑ 16. Utilities on/near Structure. (WisDOT policy is to avoid placing utilities on the structure.) □ Yes ⊠ No

	Туре	Owner and Contact I	nformation		Size	Opening at Abutment	Weight	Pressure
	•	dge railing deficient lo If Yes – Replac	? cement Rail Type: in kir	nd (Sloped	Face Parap	et Type A) on	ly on wings	
	18. Drains to be: □ Raised	□ Closed	Downspouted	□ New				
		ined on bridge durii Io If Yes – Include	•					
	20. Will guard rail ⊠ Yes □ N		corners? South corners	S				
		e performed elimina lo If No – Explain	ate all deficiencies?					
		aste (asbestos) to b lo If Yes – Explai						
\boxtimes	23. Wing location	(s) for surface drair	anchors: N/A					
	24. Painting? ☐ Yes ☐ No If Yes – Explain on Page 4 (all, part, railing, color system, containment, bid items)							
		vay width: <i>(new decl</i> valk clear width: I	÷	Ft. ht: Ft	t.			
\boxtimes	26. Maximum incr	ease in grade line	elevation <u>0</u> In.					
\boxtimes	27. Benchmark de	escription to be sho	wn					
\boxtimes	28. Desired final of	cross slopes on brid	lge <u>0.02</u> Ft./Ft.					
	 29. Underwater Inspection Report including: Streambed Cross Section With Pier, Footing and Seal Elevations Pier Elevation Drawings Pier Layout Hydrographic Survey 							
	30. Slope stabiliza		ty: CY. CY.					
		lated Mats (for Sco (for Scour)	or proposed scour repa ur)CY. CY. CY.	ir.				

CY.

Extra Heavy Riprap

- 32. Report submitted with Preliminary Plan requires no CADD file submittal (See ESubmittal instructions).
- □ 33. Report submitted for development of Preliminary Plan to structure design engineer requires CADD file (if available) submittal and Report submittal to Soils Engineer if project involves foundation modifications.
- 34. Coordinate with structure design engineer **before** going into the field if existing structure has no available plans, if staged construction is planned, or if there are adjoining/adjacent structures that will remain in place.
- □ 35. If project involves substructure widening coordinate with structure and/or hydraulic design engineer to determine if information on the separation and/or stream crossing SSR will be required.

Additional Information

Elaborate on other concerns such as: DNR, Local, Utility Conflicts, Aesthetics, Railing Type and Staged Construction. Please be as detailed and specific as possible.

Work to be performed consists of the following: Concrete overlay which entails removing the old overlay, replace all four top section of wing parapets and replace in kind with Sloped Face Parapet Type A and new beamguard anchorage, replace south joint strip seal with new strip seal joint, repair J-rail, miscellaneous concrete surface repair as determined in field.

Bridge will be open to traffic while construction takes place. Traffic will be maintained on the structure during construction by reducing traffic to one lane during each stage. The concrete overlay will require two pours with the first pour being 18 feet wide, and the second 22 feet wide.

Deficient areas consist of the deck and existig parapet.

Fixed at both piers and north abutment, expansion joint at south abutment.

Construction joint 18' east from inside of parapet or 22' west from inside of parapet at crown.

No utilities are known to exist on the bridge.

No drains on existing bridge deck.

The beam guard at the south end of the structure will be reconstructed to current standards. The terminals at the concrete parapet will be constructed new anchorages.

Asbestos reports are in the process of being completed by a WisDOT subconsultant.