





SELECT AS-BUILT DRAWINGS

BENCH MARK			
NO	STATION	LOCATION	ELEV
15	295 E + 75	18' N PINE 163' LT	108715


PROJECT : 0	SHEET : NUMBER	TOTAL SHEETS
1197-6-72		
FEDERAL PROJECT - DESIGNATION	21	225
DPF 08-4(41)		




PROFILE GRADES U-S-H "53"



PROFILE GRADES U-S-H "8"




TYPICAL SECTION THRU U-S-H "8"



ELEVATION

ELEVATION
NORMAL TO REB & WB LANES U-S-H "8"





No.	Date	Rev.	Top	By
STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS				
STRUCTURE B-3-37				
U-S-H "53" OVER U-S-H "8"				
From BARRON		To TH. STANLEY		
Iss on Sep	A A B H O 1969	Drawn	H S D O	Check Date 1969
Designed by	C D W	Lead Engineer	RWA	Permitted By
Approved	W A Kline		3-3-72	RLP
(Chief Bridge Engineer)		Dra		
GENERAL PLAN			SHEET 1 OF 18	
			X46904	

1197-6-72
DPF 08-4 (41) 31 225

BILL OF BARS


DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT OF BAR
THE FIRST DIGIT OF THE MARK INDICATES THE BAR SIZE

MARK	NO REQ'D	LENGTH	BENT	LOCATION
S501	213	4'-0"		SLAB TOP AND BOTTOM TRANS
S502	230	35'-7"		SLAB TOP AND BOTTOM LONGIT
S503	10	3'-0"		TOP LONGIT SYM ABOUT + OF PIER
S504	484	4'-9"		RAIL PARAPET LEAF
S505	464	5'-0"		"
S506	2	1'-8"		"
S507	47	2'-6"		"
S508	2	1'-4"		"
S509	10	2'-11"		"




NOTES

1. CONCRETE IN ANY SPAN SHALL BE PLACED WITHIN FOUR HOURS OF THE TIME THAT CONCRETE WAS PLACED OVER AN ADJACENT PIER
2. PLACE TRANSVERSE BAR STEEL ON SKEW
3. BOTTOM TRANSVERSE BARS IN SLAB SHALL BE SUPPORTED BY CONTINUOUS BAR CHAIRS OR ON ADJACENT TO EACH CIRCULAR AND BY INDIVIDUAL BAR CHAIRS PLACED AT 3'-0" CTRS. AT APPROXIMATELY THE 1/3 POINTS BETWEEN PIERS
4. TOP LONGITUDINAL BAR STEEL SHALL BE SUPPORTED BY CONTINUOUS BAR CHAIRS AT APPROXIMATELY 4'-0" CTRS
5. THE VERTICAL FACE OF THE RAIL PARAPET IS TO BE MAINTAINED AT ALL POINTS OF BEARING




SECTION S1




PART SECTION THRU SLAB

NOTE TO DETERMINE THE INTERIOR OF SLAB STEEL HAS BEEN ERECTED ELEVATIONS OF THE TOP FLANGES OR TOP OF SPlice PLATES, WHICHEVER APPLIES, SHALL BE TAKEN AT CENTERLINE OF BEARINGS, CENTERLINE OF FIELD SPICES AND AT EIGHT POINTS OF EACH SPAN WHICH ARE MORE THAN SIX FEET FROM A FIELD SPICE. THESE ELEVATIONS, SUBTRACTED FROM THE GRADE ELEVATIONS, ADJUSTED FOR DEADLOAD DEFLECTION OF THE CONCRETE, MINUS THE SLAB DEPTH, PLUS THE STEEL THICKNESS TO BOTTOM OF TOP FLANGE EQUALS THE RAUNCH DEPTH.



East parapet has crack at top for 20 feet, approx.
20 SF Concrete Surface Repair.



No.	Date	Revision	By
STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS			
STRUCTURE B-3-37			
Drawn By	Checked	By	RLP
969	LN F		
SUPERSTRUCTURE			SHEET 11 OF 18
X46914			

ASBESTOS REPORT



3159 VOYAGER DRIVE
GREEN BAY, WI 54311
920.455.8200 PHONE

Bridge Asbestos Inspection Report

WisDOT Project ID: 1196-04-02

Structure Number: B-03-037

Structure Name: USH 53 SB over USH 8

City/County: Town of Stanley, Barron County, Wisconsin

GEI project Number: 1901822

Date Inspected: April 4, 2019

Inspected by: Kyle C. Sandmire

Asbestos Inspector License Number: All- 217616

Consultant Company: GEI Consultants, Inc.

Summary:

An asbestos inspection of Structure B-03-037 was conducted on April 4, 2019 by Kyle Sandmire, Asbestos Inspector License No. All-217616. Asbestos-containing material (ACM) **IS NOT** present on this structure.

The inspection to identify and collect samples of potential asbestos-containing material (ACM) was completed following WisDOT standard sampling procedures for bridge inspections found in FDM 21-35-45.

No Asbestos-containing material has been found in Structure B-03-037. Standard Special Provision (STSP) 107-127 shall be included in the plans. The contractor will be responsible for completion of the Notification of Demolition and/or Renovation (DNR form 4500-113) if required. A copy of the inspection report is available from the region office.

Sample #	Sample Description	Sample Location	Method and Analytical Results	Category I or II non-friable or No ACM	Total Amount of Material on Structure
B-03-037-1A	Silver paint	Steel plates between bridge spans and abutment and on bridge spans	PLM, non-detect	No ACM	N/A
B-03-037-1B	Silver paint	Steel plates between bridge spans and abutment and on bridge spans	PLM, non-detect	No ACM	N/A
B-03-037-1C	Silver paint	Steel plates between bridge spans and abutment and on bridge spans	PLM, non-detect	No ACM	N/A
B-03-037-2A	Black/gray expansion material	Between bridge deck joints	PLM, non-detect	No ACM	N/A

B-03-037-2B	Black/gray expansion material	Between bridge deck joints	PLM, non-detect	No ACM	N/A
B-03-037-2C	Black/gray expansion material	Between bridge deck joints	PLM, non-detect	No ACM	N/A
B-03-037-3A	Black tar	Portions of the south bridge deck	PLM, non-detect	No ACM	N/A
B-03-037-3B	Black tar	Portions of the south bridge deck	PLM, non-detect	No ACM	N/A
B-03-037-3C	Black tar	Portions of the south bridge deck	PLM, non-detect	No ACM	N/A

If you have any questions, please contact us at (920) 455-8200.

GEI CONSULTANTS, INC.



Kyle C. Sandmire
Environmental Scientist



Paul M. Garvey
Senior Scientist

Attachments:


B-03-037 Report Table

B-03-037 Map

B-03-037 Photo Log

B-03-037 Bulk Asbestos Sample Analysis Summary

B-03-037 Bulk Asbestos Sample Chain of Custody



GEI
 Consultants
 3159 Voyager Drive
 Green Bay, WI 54311
 920.455.8200


WisDOT Project 1196-04-02
 Structure B-03-037
 USH 53 (SB)
 over USH 8
 Barron County

DESIGNED BY	KCS	4/10/2019
DRAWN BY	KCS	4/10/2019
APPROVED BY	PMG	4/10/2019
SCALE	1 inch = 500 feet	
FIGURE NO.	B-03-037	


PHOTOGRAPHIC LOG


PHOTOGRAPH NO: 1	
DIRECTION: SE	
DESCRIPTION: Looking southeast at B-03-037.	

PHOTOGRAPH NO: 2	
DIRECTION: E	
DESCRIPTION: Looking west at B-03-037.	

PHOTOGRAPH NO: 3	
DIRECTION: SW	
DESCRIPTION: View of the bridge identification plate.	

PHOTOGRAPH NO: 4	
DIRECTION: NW	
DESCRIPTION: View of the silver paint on span beams and on steel plates between the spans and abutments. The silver paint is not ACM.	

PHOTOGRAPH NO: 5	
DIRECTION: Down	
DESCRIPTION: View of the black/gray expansion material on the bridge deck joints. The black/gray expansion material is not ACM.	

PHOTOGRAPH NO: 6	
DIRECTION: Down	
DESCRIPTION: View of the black tar on the south bridge deck wall joints. The black tar is not ACM.	



Environmental Hazards Services, L.L.C.

7469 Whitepine Rd

Richmond, VA 23237

Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 19-04-02060

Client: GEI Consultants Inc
3159 Voyager Dr.
Green Bay, WI 54311

Received Date: 04/12/2019

Analyzed Date: 04/15/2019

Reported Date: 04/16/2019

Project/Test Address: B-03-037; USH 53 SB Over USH 8; Town of Stanley, WI

Client Number:

200598

Fax Number:

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
19-04-02060-001	B-3-37-1A	--	Gray Paint; Brown Brittle; Inhomogeneous	NAD	100% Non-Fibrous
19-04-02060-002	B-3-37-1B	--	Gray Paint; Brown Brittle; Inhomogeneous	NAD	100% Non-Fibrous
19-04-02060-003	B-3-37-1C	--	Gray Paint; Brown Brittle; Inhomogeneous	NAD	100% Non-Fibrous
19-04-02060-004	B-3-37-2A	--	Gray Adhesive; Black Paint; Inhomogeneous	NAD	100% Non-Fibrous
19-04-02060-005	B-3-37-2B	--	Gray Adhesive; Black Paint; Inhomogeneous	NAD	100% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 200598

Report Number: 19-04-02060

Project/Test Address: B-03-037; USH 53 SB Over USH 8; Town
of Stanley, WI

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
19-04-02060-006	B-3-37-2C	--	Gray Adhesive; Black Paint; Inhomogeneous	NAD	100% Non-Fibrous
19-04-02060-007	B-3-37-3A	--	Black Tar; Homogeneous	NAD	7% Cellulose 93% Non-Fibrous
19-04-02060-008	B-3-37-3B	--	Black Tar; Homogeneous	NAD	7% Cellulose 93% Non-Fibrous
19-04-02060-009	B-3-37-3C	--	Black Tar; Homogeneous	NAD	7% Cellulose 93% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 200598
Project/Test Address: B-03-037; USH 53 SB Over USH 8; Town
of Stanley, WI

Report Number: 19-04-02060

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
----------------------	-------------------------	------------	-----------------------	----------	--------------------

QC Sample: 29-M22009-2

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Christian H. Schaible

Reviewed By Authorized Signatory:



Missy Kanode
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714 NVLAP #101882-0 VELAP 460172. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected



EHS
Laboratories™

Environmental Hazards Services, LLC

Asbestos Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT:

www.leadlab.com



19-04-02060

Due Date:

04/17/2019

(Wednesday)

AE

Company Name: GEI Consultants, Inc.

Account Number: 1901822

Address: 3159 Voyager Drive City/State/zip: Green Bay, WI 54311

Phone #: 920-241-2725 Email: k.sandmire@geiconsultants.com Fax: 920-415-8225

Project Name / Testing Address: B-03-037, USH 53 SB over USH 8 City/State (Required): Town of Stanley, WI

Collected by: Kyle C. Sandmire AII-217616 P.O. # 1901822

TURN AROUND TIMES: IF NO TAT IS SPECIFIED, SAMPLE(S) WILL BE PROCESSED AND CHARGED AS 3 - DAY TAT.

	1 Day	2 Day	3 Day	* Same Day - Must Call Ahead				* Weekend - Must Call Ahead			
No.	Client Sample ID	HA Area #	Collection	Date	Time	PLM	PLM Point Count 400	PLM Point Count 1000	PLM NY Protocol	TEM - Bulk	Comments
1	B-3-37-1A thru 1C			4/14/2019	7:30 AM/PM	X					Silver paint
2	B-3-37-2A thru 2C				7:30 AM/PM	X					Expansion crack
3	B-3-37-3A thru 3C				7:30 AM/PM	X					Black tar
4					AM / PM						
5					AM / PM						
6					AM / PM						
7					AM / PM						
8					AM / PM						
9					AM / PM						
10					AM / PM						
Released by: <u>Kyle C. Sandmire</u>			Signature: <u>[Signature]</u>			Date/Time: <u>4/9/2019 8:00</u>					
Received by: <u>[Signature]</u>			Signature: <u>[Signature]</u>			Date/Time: <u>4/11/19 2:38 PM</u>					

BRIDGE INSPECTION REPORT



STATE OF WISCONSIN
DEPARTMENT OF TRANSPORTATION

Inspection Report for B-03-037 (USH 8)

USH 53 SB over USH 8
May 16,2017



Type	Prior	Frequency (mos)	Performed
Routine	05-13-15	24	X
Damage	02-09-07	0	
Interim	02-19-07	0	
SIA Review	06-11-13	48	X

Latitude 45°23'44.61"N
Longitude 91°45'30.08"W

Owner STATE HIGHWAY DEPT
Maintainer STATE HIGHWAY DEPT

Time Log

Team members

Hours	Minutes	Wjk
0	50	

Name	Number	Signature	Date
Inspector Kovalleski, William J	8007	<i>William J Kovalleski</i> E-signed by Bill(dotwjk)	08-07-17

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 2

Identification & Location

Feature On: USH 53 SB	Section Town Range: S29 T34N R11W	Structure Number: B-03-037
Feature Under: USH 8	County: BARRON	
Location 8.2M S JCT STH 48 TO E	Municipality: STANLEY	Structure Name: USH 8

Geometry

measurements in feet, except where noted

Approach Roadway Width: 40	Bridge Roadway Width: 40.0	Total Length: 244.2
Approach Pavement Width: 44	Deck Width: 43.8	Deck Area (sq ft): 10695

Traffic

	Lanes	ADT	ADT year	Traffic Pattern
On	2	5400	2014	ONE WAY TRAFFIC
Under	4	7400	2014	TWO WAY TRAFFIC

Capacity

Load Rating

Inventory rating: HS21	Overburden depth (in): 2.0	Last rating date: 07-29-13	Controlling: INTERIOR DECK GIRDER Moment
Operating rating: HS35	Deck surface material: INTEGRAL CONCRETE	Re-rate for capacity (Y/N):	Control location: 1.0 SPAN 1, 118.5
Posting:	Re-rate notes:		

Hydraulic

Classification

Scour Critical Code(113): (N) NO WATERWAY	Q100 (ft3/sec): 0	
High water elevation (ft): 0.0	Velocity (ft/sec): 0.0	Sufficiency #: 99.0

Span(s)

Span #	Material	Configuration	Depth (in)	Length (ft)	Main
1	CONT STEEL	DECK GIRDER		118.5	
2	CONT STEEL	DECK GIRDER		121.5	Y

Expansion joint(s)

Temperature:

File:	New:
-------	------

Clearance

Item	File Measurement (ft)	File Date	New Measurement (ft)
Highway Min Vertical Under Cardinal	17.0		
Highway Min Vertical Under Non-Cardinal	17.58		
Horizontal Under Cardinal	97.5		
Horizontal Under Non-Cardinal	97.5		
Highway Min Vertical On Cardinal			
Horizontal On Cardinal			

Special Components

Component	Year	Work Performed	Note
DECK - IOWA MIX	1994	OVERLAY - CONCRETE	

Construction History

Year	Work Performed	FOS id
1998	PAINTING	1197-10-71
1994	OVERLAY - CONCRETE	1190-22-60
1972	NEW STRUCTURE	1197-06-72

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 3

Structure No.: **B-03-037**

Maintenance Items History

Item	Recommended by	Status	Status change	Year completed
Deck - Patching	Bjorklund, Allan M (8003)	COMPLETE	07/06/15	2015
Patch ends of deck along joints both ends. Est. 19 SF on north end, 25 SF on south. Use SET 45 or similar.				
Deck - Seal Surface Cracks	Harrington, Daniel J (8004)	COMPLETE	01/17/13	
epoxy deck cracks over pier 300 LF				
Deck - Patching	Harrington, Daniel J (8004)	COMPLETE	01/17/13	
repair spalls in backwall N abut approx 8 LF				
Deck - Patching	Harrington, Daniel J (8004)	COMPLETE	01/17/13	
repair backwall spalls 24 LF.				
Deck - Patching	Bjorklund, Allan M (8003)	COMPLETE	07/06/15	2015
Patch deck, est 20sf S abut, 24sf N abut. Polymer conc patch material.				

Maintenance Items

Item	Priority	Recommended by	Status	Status change
Expansion Joints - Repair	CRITICAL	Bjorklund, Allan M (8003)	IDENTIFIED	05/19/15
2LF of steel extrusion of the south joint is broken at centerline in outside lane.				
Substructure - Other Work	HIGH	Bjorklund, Allan M (8003)	IDENTIFIED	05/19/15
Seal concrete columns, 3 ea.				

Elements

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	12		Reinforced Concrete Deck	SF	10,696	10,292	402	2	0
			Delamination - Spall - Patched Area	SF		0	2	2	0
		1080	Repairs at SW and NW rust staining by joint. SE corner spalling w exposed rebar.						
			Cracking (RC)	SF		0	400	0	0
		1130	Few fine to hrline transverse cracks at even spacing near Pier w/ lt efflorescence. Span 2, Bay 3 (west) - 3ft wide span concrete deterioration staining with lt rust staining.						
		8000	Wearing Surface (Bare)	SF	10,696	6,260	4,392	44	0
X	107		Debonding/Spall/Patched Area/Pothole	SF		0	0	44	0
		3210	Spalling along both joints on paving blocks, 19SF along North joint, 25SF along South joint.						
			Crack (Wearing Surface)	SF		0	4,392	0	0
		3220	Fine map cracking, 18ftx244ft.						
			Steel Open Girder	LF	1,220	820	400	0	0
			Girders appear straight and plumb with no obvious indications of out-of-plane movement. NOTE: Traffic impact to west fascia girder over USH 8 rt lane. Will grind out damage, third girder also scraped on bottom flange. In span 1 girders 1,3,4 & 5 ground at hits, tested with Mag-particle and painted.						
	8516	1000	Corrosion	LF		0	400	0	0
			Rust mainly on bottom flanges and lower web over roadways.						
			Painted Steel	SF	17,000	4,250	10,200	1,700	850
			Painted overcoat 9/19/98. Rust showing bottom flange over roadway 8 and fascia bearings. Traffic impact to west fascia girder over USH 8 rt lane. Will grind out damage, third girder also scraped on bottom flange. In span 1 girders 1,3,4 & 5 ground at hits, tested with Mag-particle and painted. Webs peeling 2011.						
		3440	Effectiveness (Steel Protective Coatings)	SF		4,250	10,200	1,700	850
			Paint has failed in areas over the roadway. General dulling of surface with peeling of the topcoat on the exterior girders.						

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 4

Structure No.: **B-03-037**

X	205		Reinforced Concrete Column	EA	3	2	1	0	0
		1080	Delamination - Spall - Patched Area Col 5 btm west spall w exposed rebar (poor cover)	EA		0	1	0	0
X	215		Reinforced Concrete Abutment Staining at NW from joint.	LF	91	76	6	9	0
		1080	Delamination - Spall - Patched Area SOUTH: 1ft edge spall at G1 / CS3 edge spall west face w/ rust at joint.	LF		0	1	1	0
		1130	Cracking (RC) SOUTH: CS3 vertical cracks at G2, Bays 2 & 3, G4, and Bay 4 / 2 hrln horiz at G1 to edge. NORTH: CS3 vert cracks at Bays 1, 2, & 3 / hrline vert cracks at G 1 & 3, and Bay 4. some cracks extend up into backwall.	LF		0	5	8	0
X	234		Reinforced Concrete Cap East nose btm - honeycombing poor consolidation.	LF	42	42	0	0	0
X	300		Strip Seal Expansion Joint	LF	85	41	0	42	2
		2310	Leakage, Seal Adhesion, Damage, Cracking Steel extrusion broken on the south joint at centerline in outside lane for 2ft.	LF		0	0	0	2
		2360	Adjacent Deck or Header Damage Damage to concrete backwall along joints, 19lf on north, 25lf on south.	LF		0	0	42	0
X	311		Moveable Bearing At abutments - rockers	EA	10	6	4	0	0
		1000	Corrosion Lt edge rusting - fascia worse.	EA		0	4	0	0
X	313		Fixed Bearing At Pier	EA	5	3	2	0	0
		1000	Corrosion Lt edge rusting - fascia worse.	EA		0	2	0	0
X	331		Reinforced Concrete Bridge Rail	LF	488	486	0	2	0
		1080	Delamination - Spall - Patched Area Spall w/exposed rebar SE @ abut 2 lf.	LF		0	0	2	0
		1130	Cracking (RC)	LF		0	0	0	0
X	8400		Integral Wingwall	EA	4	1	3	0	0
		8902	Wall Movement SW tipped 1/4in.	EA		0	1	0	0
		8903	Wall Deterioration SE-delam top. SW - fine vert crack mid w/ spall top. NW - vry fine vert crack mid.	EA		0	2	0	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 5

Structure No.: **B-03-037**

Assessments

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	9001		Drainage - Approach C&G inlets at north end - slight settle.	EA	4	2	2	0	0
X	9030		Signs - Object Markers	EA	2	2	0	0	0
X	9043		Slope Protection- Crushed Aggregate with Bit. Rocks tightly adhered. Vegetation and loose/bleaching at edges.	EA	2	2	0	0	0
X	9167		Steel Diaphragm On abutments - vry lt freckle rust.	EA	8	8	0	0	0
X	9250		Cross Bracing or Struts Freckle rust spotty over driving lanes.	EA	36	20	16	0	0
X	9322		Approach Roadway - Concrete (non-structural)	EA	2	2	0	0	0

NBI Ratings

	File	New
Deck	5	5
Superstructure	7	7
Substructure	7	7
Culvert	N	N
Channel	N	N
Waterway	N	N

Structure Specific Notes

OLD: (01) Structure is in very good condition. Paint job in 1998 is weathering well. Joints are dirty but are not leaking. Approaches are good. Slope paving needs to be repaired and resprayed. deck is very **good**.

Inspection Specific Notes

Inspector Site-Specific Safety Considerations

Structure Inspection Procedures

Walk-thru

Special Requirements

Chk Hours Cost Comments

Routine
Document Comment/Description

North abutment



Routine

Document Comment/Description

South abutment



Routine
Document Comment/Description

SW abutment



STRUCTURE INVENTORY AND APPRAISAL FIELD REVIEW FORM

B-03-037
USH 53 SB over USH 8

LOCATION

(3) Municipality:
 (16) Latitude(° ' "):
 (17) Longitude(° ' "):

STANLEY
45°23'44.61"N
91°45'30.08"W

TRAFFIC SERVICE

(28A) Lanes On:
 (28B) Lanes Under:
 (102) Traffic Pattern On:
 (102) Traffic Pattern Under:
 (19) Detour Length(mi):

2
4
-NO TRAFFIC <input checked="" type="checkbox"/> ONE WAY TRAFFIC -TWO WAY TRAFFIC
-NO TRAFFIC -ONE WAY TRAFFIC <input checked="" type="checkbox"/> TWO WAY TRAFFIC
0

GEOMETRY

(49) Structure Length(ft):
 (50) Sidewalk Width(ft):
 (50) Curb Width(ft):
 (52) Culvert Barrel Length(ft):
 (34) Skew:
 (51) Bridge Roadway Width(ft):
 (52) Deck Width(ft):
 Right Wingwall Length(ft):
 Left Wingwall Length(ft):
 (32) Approach Roadway Width(ft):
 (47) Minimum Horizontal(ft):
 (55) Minimum Right Lateral(ft):
 (56) Minimum Left Lateral(ft):

244.2	
Left: 0.0	Right: 0.0
Angle(°): 11	Direction: -RIGHT FORWARD <input checked="" type="checkbox"/> LEFT FORWARD
Cardinal	Non-Cardinal
40.0	40.0
43.8	43.8
40	40
Cardinal Under Clearance	Non-Cardinal Under Clearance
97.5	97.5
33.0	33.0
40.5	40.5

RAILING APPRAISAL

(36A) Bridge Rail Adequacy:
 (36B) Transition Adequacy:
 (36C) Approach Guardrail Adequacy:
 (36D) Guardrail Termination Adequacy:
 Outer Rail:

-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
Left	Right	Type
		TYPE F (TWO SQUARE TUBES) - STEEL(8)
		TYPE F (3 SQUARE TUBES) - STEEL(65)
		TYPE F (4 SQUARE TUBES) - STEEL(72)
		TYPE M-STEEL 3 SQUARE TUBES(93)
X	X	SLOPED FACE PARAPET LF(91)
		SLOPED FACE PARAPET HF(92)
		VERTICAL FACE PARAPET TYPE A(74)
		TYPE W-THRIE BEAM(79)
		TYPE H ON VERTICAL PARAPET(80)
		TIMBER(38)
		OTHER(99) (Please specify)
	CONT GUARD RAIL	
	NO APP GRDRL	
	NO ATTACHMENT	
5	22 MM(7/8") BOLT (Please enter quantity)	
	25 MM(1") BOLT (Please enter quantity)	
	OTHER (Please specify)	
X	(01) ENERGY ABSORBING TERMINAL/EAT	
	(02) TURN DOWN	
	(99) OTHER (Please specify)	

ROADWAY ALIGNMENT APPRAISAL

(72) Approach Alignment Appraisal:

	3 Intolerable- Substantial speed reduction
	6 Fair- Minor speed reduction
X	8 Good- No speed reduction

BRIDGE DECK
REPAIR QUANTITIES

12/6/2018

Ken,

Here's a summary of our new direction for the Barron County project. Wing replacements are still in the project and Al Bjorklund wants the joints replaced on the overlays.

I've also included Al's estimated quantities for deck repairs. I would like to have another conference call with Al to discuss this change in scope, let me know if you agree and we'll try to set up a time.

I'm guessing we'll need to amend your design contract.

Let me know if you have questions.

Thanks,

Brendan

1196-04-77

USH 53 (Chippewa Co Line - CTH I NB)

RSRF20

- Change SFY from 2021 to 2023
- Add ADV SFY of 2021
- Change estimate from \$14.460 M to \$12.0 M to reflect BOS-recommended bridge scope changes (see below)
- Update bridge information in FIIPS to reflect BOS-recommended bridge scope changes

1196-04-77:

Current FIIPS Estimate w/o delivery: 14,460,000

New FIIPS Estimate w/o delivery including BOS changes: 12,000,000

Structure Work including: Conc overlays on B-3-14,20,24,30; Conc Overlays and Joints on B-3-26, 37; Re-decks on B-3-16,18 plus any other incidental structure work.

Here are Al's guesses on deck repair quantities, [Type 1\(SY\)](#)-[Type 2\(SY\)](#)-[Full Depth\(SY\)](#)

1) 1196-04-77 (USH 53, Chippewa County Line – USH 8 SB) 2021 RSRF20 \$14.460 M

- B-03-14 (03) CONC OVLY [70-35-2](#)
- B-03-16 (06) REPLACE DECK
- B-03-18 (06) REPLACE DECK
- B-03-20 (03) CONC OVLY [100-50-15](#)
- B-03-24 (03) CONC OVLY [30-15-5](#)
- B-03-26 (58) CONC OVLY/NEW JOINTS [20-10-1](#)
- B-03-30 (03) CONC OVLY [125-60-10](#)
- B-03-37 (58) CONC OVLY/NEW JOINTS [95-45-5](#)