

ATTACHMENT 1
INSPECTION REPORT



STATE OF WISCONSIN
DEPARTMENT OF TRANSPORTATION

Inspection Report for B-40-280

W GRANTOSA DR WB over STH 145-W FOND DU LAC AV
Jul 21,2018



B-40-280
W GRANTOSA DR WB over STH 145-W FOND DU LAC AV
North Elevation
7/21/2018

Type	Prior	Frequency (mos)	Performed
Routine	07-21-16	24	X
Deck Evaluation			X
SIA Review	07-21-16	48	

Start Coordinates		End Coordinates (optional)	
Latitude	43°06'45.22"N	Latitude	
Longitude	88°00'08.74"W	Longitude	
Owner	STATE HIGHWAY DEPT	Maintainer	STATE HIGHWAY DEPT

Time Log Team members

Hours	Minutes	
1	55	

Name	Number	Signature	Signature Date
Inspector	Zippel, William J	<i>William J Zippel</i>	10-02-18
		E-signed by William Zippel(wzippel)	

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 2

Identification & Location

Feature On: W GRANTOSA DR WB	Section Town Range: S34 T08N R21E	Structure Number: B-40-280
Feature Under: STH 145-W FOND DU LAC AV	County: MILWAUKEE	
Location 0.2M E JCT STH 181	Municipality: MILWAUKEE	Structure Name:

Geometry

measurements in feet, except where noted

Approach Roadway Width: 36	Bridge Roadway Width: 36.0	Total Length: 198.2
Approach Pavement Width: 36	Deck Width: 45.5	Deck Area (sq ft): 9018

Traffic

	Lanes	ADT	ADT year	Traffic Pattern
On	3	4000	2016	ONE WAY TRAFFIC
Under	8	27900	2015	TWO WAY TRAFFIC

Capacity

Load Rating

Inventory rating: HS14	Overburden depth (in): 2.0	Last rating date: 01-14-13	Controlling: INTERIOR DECK GIRDER Moment
Operating rating: HS24	Deck surface material: MICROSILICA MODIFIED CONC	Re-rate for capacity (Y/N):	Control location: 4.9 SPAN 2, 34.1
Posting:	Re-rate notes:		

Hydraulic

Classification

Scour Critical Code(113): (N) NO WATERWAY	Q100 (ft3/sec): 0	
High water elevation (ft): 0.0	Velocity (ft/sec): 0.0	Sufficiency #: 52.7

Span(s)

Span #	Material	Configuration	Depth (in)	Length (ft)	Main
1	CONT STEEL	DECK GIRDER		34.0	
2	CONT STEEL	DECK GIRDER		70.0	Y
3	CONT STEEL	DECK GIRDER		60.0	
4	CONT STEEL	DECK GIRDER		30.0	

Expansion joint(s)

Temperature:

Joint #	Location	Type	Last inspection date	File:	New:72
1	EAST ABUTMENT	SSA-400L	07-15-14	Last measure (in)	New measure (in)
2	WEST ABUTMENT	SSA-400L	07-15-14	0.1	0.1
				0.2	0.1

Clearance

Item	File Measurement (ft)	File Date	New Measurement (ft)
Highway Min Vertical Under Cardinal	14.76		
Highway Min Vertical Under Non-Cardinal	15.49		
Horizontal Under Cardinal	52.0		
Horizontal Under Non-Cardinal	61.3		
Highway Min Vertical On Cardinal			
Horizontal On Cardinal			

Special Components

Component	Year	Work Performed	Note
DECK - IOWA MIX	1992	OVERLAY - CONCRETE	MICRO-SILICA MODIFIED CONCRETE

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 3

Structure No.: **B-40-280**

Construction History

Year	Work Performed	FOS id
1993	ADD PED FENCING	1360-03-73
1992	OVERLAY - CONCRETE	1360-00-74
1965	NEW STRUCTURE	

Maintenance Items History

Item	Recommended by	Status	Status change	Year completed
Deck - Other Work	Tormey, Jeffrey T (9510)	REJECTED	02/24/17	
Monitor for concrete removal on underside of overhangs				
Misc - Other Work	Zalewski, Thomas A (9515)	REJECTED	10/01/18	
Repair sinkhole under bridge in STH 145 NB Lt. shoulder about 1' deep				
Deck - Repair Railing	Tormey, Jeffrey T (9510)	COMPLETE	10/01/18	2018
Repair Broken fence rail/post connection at NE Wingwall				

Maintenance Items

Item	Priority	Recommended by	Status	Status change
Misc - Remove/Monitor Loose Concrete	HIGH	Tormey, Jeffrey T (9510)	IDENTIFIED	02/24/17
Remove loose concrete at delams and monitor for concrete removal on underside of deck and overhangs.				
IMP-Structure Replacement	MEDIUM	Zalewski, Thomas A (9515)	IDENTIFIED	08/05/14
Recommend 2020				
Superstructure - Other Work	MEDIUM	Zalewski, Thomas A (9515)	IDENTIFIED	08/05/14
Replace sheared bolts at bearing hold down devices. Extend slot to accommodate movement.				
Substructure - Repair Abutment / Wings	MEDIUM	Zippel, William J (9605)	IDENTIFIED	10/01/18
Repair SW wing where joint has closed and bridge rail and tube rail are damaged.				
Misc - Repair / Replace Utilities or Signs	MEDIUM	Zippel, William J (9605)	IDENTIFIED	10/01/18
Replace obj marker sign at SE corner.				
Misc - Cut Brush	LOW	Tormey, Jeffrey T (9510)	IDENTIFIED	07/28/16
Remove tree from north edge of west slope paving.				
Approach - Patch Bituminous	LOW	Zippel, William J (9605)	IDENTIFIED	10/01/18
Repair open cracks and potholes forming at both approaches.				

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 4

Structure No.: **B-40-280**

Elements

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	12		Reinforced Concrete Deck-Black Steel Reinforcing Spans #'d West to East. Bays #'d from N to S.	SF	9,018	8,114	672	232	0
			Delamination - Spall - Patched Area	SF		0	300	232	0
		1080	Sp 1: Sound and unsound full depth deck repair - 25 SF CS2 and 25 SF CS3. Delams Bay 2 and S OH (4 SF CS3). Sp 2: Sound and unsound full depth deck repair - 100 SF CS2 and 100 SF CS3. Sp 3: Sound and unsound full depth deck repair - 75 SF CS2 and 75 SF CS3. 12 SF Delam over ramp. 8SF Spall over Pier, S OH. Sp 4: Sound full depth deck repair - 100 SF CS2. 4 SF Delam Bay 2. 4 SF Spall over Pier, S OH.						
			Cracking (RC)	SF		8,646	372	0	0
		1130	All spans: Transverse, Longit, and map cracking with eff & leaking Sp 1: 65 SF CS2 Narrow transv cracks and 20 SF Longit CS2 cracks in Bay 3. Sp 2: 44 SF CS2 Narrow transv cracks and 50 SF CS2 map cracking in Bay 3. Sp 3: 39 SF CS2 Narrow transv cracks, 50 SF Longit CS2 cracks in Bay 3, and 50 SF CS2 map cracking in Bay 4. Sp 4: 64 SF CS2 Narrow transv cracks.						
		8514	Concrete Overlay	SF	7,135	3,205	715	3,215	0
X	107		Debonding/Spall/Patched Area/Pothole	SF		0	0	2,500	0
		3210	May 2015 IR: "Numerous large delaminations throughout the deck." 30-35% Delam. Asphalt patch near Pier 1.						
			Crack (Wearing Surface)	SF		0	715	715	0
		3220	Narrow to medium longit and map cracking throughout deck. Some overlap with delams above. Approx 10% additional CS2 and 10% additional CS3.						
X	107		Steel Open Girder Spans #'d West to East. Girders #'d from N to S.	LF	1,167	0	1,107	60	0
			Corrosion	LF		0	1,107	60	0
		1000	Lt/med rust on Btm Flg; Lt freckled rust at underside btm flg; Lt to med freckled rust at webs, esp. at G1; Section loss initiated in some areas over roadway (spans 2 and 3) or near abutments, especially at edges of bottom flanges (Approx 60LF CS3).						
		8516	Painted Steel	SF	10,659	0	6,395	3,198	1,066
X	205		Effectiveness (Steel Protective Coatings)	SF		0	6,395	3,198	1,066
		3440	Peeling paint at btm flg edge, bubbling at underside of flanges and webs, freckled rust on webs. Approximate 60% CS2, 30% CS3, 10% CS4.						
X	205		Reinforced Concrete Column Piers #'d West to East. Columns #'d from N to S.	EA	9	3	0	6	0
			Delamination - Spall - Patched Area	EA		0	0	6	0
		1080	P1: Lge delam w/spall & exp rebar at Col 1, delam at base Col 2, delam near top Col 3: 3 @ CS3; P2: Unsound patch @ all 3 Cols, Spall with exp rebar col 3: 3 @ CS3; P3: OK						
X	205		Cracking (RC)	EA		0	0	0	0
		1130	Defects overlap spalls/delams. P1: Vertical narrow cracks in Col 1 P2: HL to Narrow map crks at patches P3: OK.						

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 5

Structure No.: **B-40-280**

X	215		Reinforced Concrete Abutment	LF	91	19	72	0	0
		1080	Delamination - Spall - Patched Area W Abut - 4 Sound conc patches in body - 8' CS2, Sound patches in bkwl - 20' CS2; E Abut - 3 Sound conc patches in body - 6' CS2, Sound patches in bkwl - 20' CS2	LF		0	54	0	0
		1130	Cracking (RC) W Abut - 4 Narrow vert crks in body - 4' CS2, 2 Narrow vert crks in bkwl - 2' CS2; E Abut - 6 Narrow vert crks in body - 6' CS2, 6 Narrow vert crks in bkwl - 6' CS2;	LF		0	18	0	0
X	234		Reinforced Concrete Cap Piers #d West to East.	LF	127	122	0	5	0
		1080	Delamination - Spall - Patched Area P1: Delam @ N end - 1' CS3; P2: Spall and failed patch @ N end - 1' CS3; P3: Spall @ E Face Between Col 1-2 - 1' CS3	LF		0	0	3	0
		1130	Cracking (RC) P2: HL crks at patch, Med diag. crk between Col 1-2 extends through cap to both faces - 2' CS3;	LF		0	0	2	0
X	300		Strip Seal Expansion Joint Both Jts nearly Closed, no measurement possible.	LF	72	0	0	72	0
		2310	Leakage, Seal Adhesion, Damage, Cracking W Abut - Cracks, abrasion, and small spalls at corners. Jt closed - 36' CS3; E Abut - Cracks, abrasion, and small spalls at corners. Jt closed - 36' CS3	LF		0	0	72	0
X	311		Moveable Bearing Located at both abutments and Piers 1 and 3	EA	24	0	11	13	0
		1000	Corrosion W. Abut: Lt/Mod rust - 4 @ CS2, 2 @ CS3 P1: Lt Rust - 6 @ CS2; P3: Lt rust - 6 @ CS2; E. Abut: Lt/Mod rust, 4 @ CS2, 2 @ CS3	EA		0	11	4	0
		1020	Connection E Abut: Girder 2 bearing has sheared bolt at hold down assembly: 1 @ CS3. Broken keeper at G6 (Qty overlaps corrosion).	EA		0	0	1	0
		2220	Alignment W Abut: Bearings G1, G5 and G6 are at limit of expansion. E Abut: Bearings G5 and G6 are at limit of expansion. Qty overlaps corrosion.	EA		0	0	8	0
		2240	Loss of Bearing Area W. Abut: G1 not in contact with bronze plate. Qty overlaps corrosion. E. Abut: G1 bearing is only about half in contact.	EA		0	0	0	0
X	313		Fixed Bearing Located at Pier 2	EA	6	0	6	0	0
		1000	Corrosion Lt to mod rust	EA		0	6	0	0
X	331		Reinforced Concrete Bridge Rail	LF	438	237	130	71	0
		1080	Delamination - Spall - Patched Area South: Shallow rebar w/rust stains - 100' CS2; Small spall at E end corner - 1' CS3; Delams at curb - 30' CS3; Spalls w/exposed rebar at curb - 40' CS3	LF		0	100	71	0
		1130	Cracking (RC) North: Nar vert crks at fence posts - 30' CS2; HL map crks; South: HL horiz and map crks, Horiz crks/spall w/exp rebar at SW Wingwall. Wide Horiz crack on back of rail where joint is tight. Quantity overlaps.	LF		408	30	0	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 6

Structure No.: **B-40-280**

X	8400		Integral Wingwall	EA	4	3	1	0	0
		8903	Wall Deterioration SW: HL map crkng - CS1; NW: HL map crkng - CS1; SE: Narrow map crkng - CS2; NE: OK .	EA		2	1	0	0

Assessments

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	9001		Drainage - Ends of Structure Curb and gutter at each corner; Inlet at NW	EA	4	4	0	0	0
X	9009		Sidewalk Transv and long HL crks throughout; Large spalls at curb, some have fallen into shoulder. Many delams and exist. patches at curb .	EA	1	0	0	1	0
X	9011		Utilities Street lighting on piers: Corroded surface mounted conduits, some broken lights	EA	1	0	0	1	0
X	9030		Signs - Object Markers Sign that had been at the SE corner has been sheared off with impact.	EA	1	0	0	0	1
X	9042		Slope Protection- Concrete E. Slope: Cracks w/minor settlement - CS2; W. Slope: Cracks w/settlement @ top, broken up around Cols @ toe, Tree growing along N edge of structure - CS2	EA	2	0	2	0	0
X	9167		Steel Diaphragm Lt/mod rust, heavier over Rdwy.	EA	60	0	60	0	0
X	9323		Approach Roadway - Asphalt E. Appr: Patched, Trans Crack w/settlement all lanes. Potholes forming at PB and longit joints - CS2; W. Appr: Cracks , slightly low at hdr, potholes forming at PB and around sewer MH - CS2	EA	2	0	2	0	0
X	9335		Decorative Rail Lt rust on anchor bolts. Scrapes/gouges from traffic impact at E end. At SW Corner, rail tubes are wearing into each other where exp jt has closed.	EA	1	0	1	0	0
X	9336		Luminaire Bases	EA	2	2	0	0	0
X	9337		Protective Screening Peeling paint on galvanized posts and rails, Bottom Rail broken at end post connection at WE wingwall.	EA	1	0	1	0	0

NBI Ratings

	File	New
Deck	4	4
Superstructure	5	5
Substructure	5	5
Culvert	N	N
Channel	N	N
Waterway	N	N

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 7

Structure No.: **B-40-280**

Structure Specific Notes

Inspection Specific Notes

Inspector Site-Specific Safety Considerations

Structure Inspection Procedures

Access from shoulder.

Special Requirements

Chk	Hours	Cost	Comments
-----	-------	------	----------

Routine

Document Comment/Description

Top of deck looking west.



Routine

Document Comment/Description

RC Deck - Sound and unsound full depth patches.

7/21/2018



Routine

Document Comment/Description

RC Deck - Spalls Span 3 at South overhang over pier.
Steel Open Gir - Top flange corrosion.

7/21/2018



Routine

Document Comment/Description

Conc OL - Asphalt patch near Pier 1 and cracking.



Routine

Document Comment/Description

Steel Open Gir - Corrosion with section loss initiated at Span 2 Girder 4.



Routine

Document Comment/Description

RC Col - P2: Unsound patch @ all 3 Cols. Photo shows Col 1 patch cracking and spall developing.



Routine
Document Comment/Description

RC Abut - W Abut - Typical sound patches and vertical cracks. Photo shows Bay 1.



Routine

Document Comment/Description

RC Cap - P2: Med diag. crk between Col 1-2 extends through cap to both faces - 2' CS3.



Routine

Document Comment/Description

RC Cap - Spall and failed patch at N End Pier 2.

7/21/2018



Routine

Document Comment/Description

W Abut - Cracks, abrasion, and small spalls at corners. Jt closed.



Routine**Document Comment/Description**

Moveable Bearings - West abut, G1. Corrosion on bearing and bronze plate is not in contact with girder sole plate.



Routine

Document Comment/Description

Moveable bearings - West Abut G2 broken bolt at hold down assembly.

7/21/2018



Routine**Document Comment/Description**

RC Bridge Rail - West end of South Rail, spalling in rail, cracking with rust stains, and spalls in curb section.



Routine

Document Comment/Description

RC Bridge Rail - West end of South Rail - Wide crack at joint where joint is tight.



Routine**Document Comment/Description**

Sidewalk - Transv and long HL crks throughout; Large spalls at curb, some have fallen into shoulder. Many delams and exist. patches at curb.



Routine

Document Comment/Description

Obj Marker sign: Sheared off with impact at SE corner.



Routine
Document Comment/Description

Dec rail: At SE Corner, rail tubes are wearing into each other where exp jt has closed.



Non-Image Documents

Type	Document	Document Comment/Description	Attached
Deck Evaluation	b40-280_18_Kd1.pdf	May 2015 Deck Eval	X

This page intentionally left blank

DECK INSPECTION SHEET

STRUCTURE NO.: B-40-280

FEATURE ON <u>W. Grantosa Dr. (WB)</u>	MAINTAINER <u>State</u>	COUNTY <u>Milwaukee</u>	ROADWAY WIDTH (FEET) <u>36.0</u>	TOTAL LENGTH (FEET) <u>198.2</u>
FEATURE UNDER <u>STH 145 - W. Fond du Lac Ave.</u>	LOCATION <u>0.2 ME Jct STH 181</u>	SKEW ANGLE <u>9 Left</u>	DECK AREA (sq.ft.) <u>7,018</u>	RDWY AREA (sq.ft.) <u>7,135</u>
STRUCTURE TYPE <u>Cont Steel Deck Girder</u>	SPANS <u>4</u>	LENGTHS <u>34.0, 70.0, 60.0, 30.0</u>	NO. OF LANES <u>3</u>	NO. OF SHOULDERS <u>0</u>

CONSTRUCTION HISTORY

YEAR

1965
1992

WORK PERFORMED

New Structure
Concrete Overlay

INFRARED SURVEY RESULTS (LEVEL 1)

ESTIMATED % TOTAL DISTRESS* 30-35%

If <2% _____

DATE OF SURVEY

5/1/15TOTAL ROADWAY
AREA
(sq. ft.)7,135AREA IN
SHADE/DEBRIS
(sq. ft.)NoneAREA INSPECTED
(sq. ft.)7,135

*ESTIMATED % TOTAL DISTRESS IS THE DEFECT AREAS ONLY AND IS NOT THE
ESTIMATED REHABILITATION AREA*

TYPE OF DEFECT	PERCENT OF AREA INSPECTED					
	0-5	5-10	10-15	15-20	20-25	25+
Delamination						<u>30-35%</u>
Debonding	<u>None</u>					
Concrete Patching	<u>None</u>					
Asphalt Patching	<u>None</u>					
Spalling	<u>None</u>					
PREVIOUS SURVEYS						
YEAR LEVEL (Total Defects)						
<u>2010 1</u>					<u>X</u>	
<u>2005 1</u>			<u>X</u>			
<u>2001 1</u>		<u>X</u>				

COMMENTS: - Numerous large delaminations throughout the deck.# PATCHES: 0# OF CORES: 0

RESULTS: _____

PROJECT ID.: 1000-70-15WORK ORDER: #2

ATTACHMENT 2
DEFICIENT AREAS





23-DEC-1997 10:03

ScreenScan


FORM E 811 02

BENCH MARK		
NO	STATION	DESCRIPTION
22	40.00	S W CORNER CONC PORCH # 7224 W VILLARD AVE.
23	40.00	(VILLARD)
		ELEV 121.53

COUNTY & HIGHWAY	ROUTE & CLASS	SECTION	STATE	FEDERAL	DIVISION	PROJECT	SHEET NO	TOTAL SHEETS
40.1	27.1	22.6				FOZT-1(22) 170	383	



W.B. LANE WEST GRANTOSA DRIVE GRADE LINE (B-40-280)



E.B. LANE WEST GRANTOSA DRIVE GRADE LINE (B-40-281)

FOND DU LAC AVE. GRADE LINE
8'-0" RT. & LT. OF C
GENERAL NOTES

DRAWINGS SHALL NOT BE SCALED.
ALL CONCRETE MASONRY SHALL BE GRADE A-A.
FC-1400 PSI.
HOT-POURED ELASTIC TYPE JOINT SEALER SHALL CONFORM TO ASTM DESIGNATION D1190.
BEVEL EXPOSED EDGES OF CONCRETE 1" UNLESS OTHERWISE SHOWN OR NOTED.
IMBED ALL BAR STEEL 2" UNLESS OTHERWISE SHOWN.
ALL FIELD CONNECTIONS SHALL BE 3/8" RIVETS OR HIGH STRENGTH BOLTS UNLESS OTHERWISE SHOWN.
THE SLOPE IN FRONT OF THE ABUTMENTS SHALL BE COVERED WITH "SLOPE PAVING" AS SHOWN IN "PLAN" ON THIS SHEET AND IN SECTION AA' ON SHEET 0414.
ALL SPACES EXCAVATED AND NOT OCCUPIED BY THE STRUCTURE SHALL BE BACKFILLED WITH GRANULAR BACKFILL TO THE ELEVATION AND SECTION EXISTING PRIOR TO EXCAVATION.

SUPERSTRUCTURE CONDITION NOT FULLY DOCUMENTED BECAUSE REDECKING IS ANTICIPATED, SEE PHOTOS IN -OTH.pdf

TOTAL ESTIMATED QUANTITIES

BID ITEMS	UNIT	SUPER	W ABUT	PIER 1	PIER 2	PIER 3	E ABUT	TOTAL
EXCAVATION FOR STRUCTURES	CY	145	60	45	45	40	40	500
GRANULAR BACKFILL	CY	40	45	45	40	40	40	210
CONCRETE MASONRY	CY	241.4	70.5	40.6	44.7	38.0	70.9	506.1
BAR STEEL REINFORCEMENT	LB	77,800	2,120	510	6,450	4,800	2,140	98,420
STRUCTURAL CARBON STEEL	LB	35,570	---	---	---	---	---	85,570
STRUCTURAL LOW ALLOY STEEL	LB	94,650	---	---	---	---	---	94,650
TUBULAR RAILING TYPE B	LF	428.9	---	---	---	---	---	428.9
SLOPE PAVING - CONCRETE	SF	248	---	---	---	---	232	480
LUBRICATED BRONZE PLATES	LB	276	---	---	---	---	---	276
BEARING PADS	SF	37	---	---	---	---	---	37
ELECTRICAL WORK (B-40-280)	LS	1	---	---	---	---	---	1
NOW BID ITEMS								
1/2" ZINC OR ALUMINUM PLATES	SF	45	---	---	---	---	---	45



LIST OF DRAWINGS

1 GENERAL PLAN	X27920
2 SUPERSTRUCTURE	X27921
3 SUPERSTRUCTURE	X27922
4 LONG SECTION & BEARINGS - STRINGER 1	X27923
5 LONG SECTION & BEARINGS - STRINGERS 2,3,4,5,6	X27924
6 EXPANSION JOINT	X27925
7 TUBULAR STEEL RAILING - TYPE "B"	X27926
8 TUBULAR ALUMINUM RAILING - TYPE "B"	X27927
9 LIGHTING DETAILS	X27928
10 WEST ABUTMENT	X27929
11 PIER 1	X27930
12 PIER 2	X27931
13 PIER 3	X27932
14 EAST ABUTMENT	X27933
15 SUBSURFACE EXPLORATION	X27934

PLAN
4 SPAN CONTINUOUS STEEL I BEAM SUPERSTRUCTURE WITH CONC. 3 COLUMN PIERS AND CONCRETE SILL ABUTMENTS.

REVISION	STATE HIGHWAY COMMISSION OF WISCONSIN
GENERAL PLAN	
NO. MILWAUKEE	CITY MILWAUKEE
SECTION 34	ROUTE 8 N
DESIGN SPEC. AASHO 61	LOADING H20-S16
DATE 11-5-63	DESIGN VGH
RECOMMENDED	11. B. Schult
APPROVED	E. L. Roetig
STRUCTURE B - 40-280	
SHEET 1 OF 15	

X27920



HEAVY RUST @ BRG & BOTTOM FLANGE, MISSING BOLTS @ HOLD DOWN.

HEAVY LAMINATE RUST @ BRG & BOTTOM FLANGE





LAMINATE RUST & PITTING @ INTERIOR GIRDERS

HEAVY RUST/SCORING LOSE @ FASCIA BRG & BOTTOM FLANGE

HEAVY BOTTOM FLANGE RUST, PITTING @ BRGS

BENT BRG SOLE PLATE


HEAVY RUST @ BRG, PITTING @ BOTTOM FLANGE



BEAM	A	B	C	D	E	F	G	H
1	1.4	1.6	1.7	1.6	1.4	1.2	0.9	0.7
2	1.4	1.6	1.7	1.6	1.4	1.2	0.9	0.7
3	1.4	1.6	1.7	1.6	1.4	1.2	0.9	0.7
4	1.4	1.6	1.7	1.6	1.4	1.2	0.9	0.7
5	1.4	1.6	1.7	1.6	1.4	1.2	0.9	0.7
6	1.4	1.6	1.7	1.6	1.4	1.2	0.9	0.7


STATE HIGHWAY COMMISSION OF WISCONSIN
SUPERSTRUCTURE
DESIGN BY: A S H O G I
DATE: 11-5-63
STRUCTURE: B-40-280
SHEET: 2 OF 15
N27921

NOTE HOLD DOWN DEVICES
SHALL BE USED AT
STRINGERS 2, 3, 4 & 5.



NOTE: HOLD DOWN DEVICES
SHALL BE USED ON
STR 2, 3, 4, 15 AT
BOTH ABUTS.

NOTE: STIFF RIBBONS SHALL
BE PLACED PARALLEL
TO E BRG




STRINGER
(SIDEWALK STR.)

BILL OF BARS


77.800⁷

DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT

DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT.							
FOUR	MARY	NO	SIZE	LENGTH	SPACING	LOCATION	
S1	776	6	21	3	6"	FLOOR - TOP	TRANS.
S2	36	6	18	0	SHOWN	"	LONG - SYM ABOUT 4 FEET
S3	312	6	35	9	6"	"	BOT - LONG
S4	210	5	35	9	1"	"	TOP - LONG
S5	362	6	19	0	6"	"	BOT - TRANS.
S6	362	6	24	0	6"	"	"
S7	195	5	7	0	1 - 0	SIDEWALK	TRANS.
S8	9	5	34	6	SHOWN	"	LONG - SPAN 1
S9	18	5	25	6	"	"	" 2
S10	18	5	30	6	"	"	" 3
S11	9	5	30	6	"	"	" 4
S12	195	5	6	0	1 - 0	"	TRANS
S13	5	6	34	6	SHOWN	CURB - LONG	SPAN 1
S14	10	6	26	6	"	"	2
S15	10	6	30	6	"	"	3
S16	5	6	30	6	"	"	4
S17	195	6	3	9	1 - 0	"	TRANS.
S18	195	6	2	6	1 - 0	"	"
S19	390	5	6	0	1 - 0	RAILING PARAPET - SOWK & CURB	
S20	10	4	7	3	SHOWN	DIAPHRAGM @ ABUT	
S21	50	5	2	6	1 - 0	"	"
S22	5	5	7	3	SHOWN	LIGHTING SUPPORTS	
S23	4	5	8	6	"	"	"
S24	4	5	13	6	SHOWN	FLOOR @ LIGHTING SUPPORTS	
S25	4	5	7	0	"	"	SOWK @ LIGHTING SUPPORTS
S26	4	5	7	9	"	"	"
S27	4	5	8	9	"	"	"
S28	4	5	9	6	"	"	"
S29	36	6	5	9	10	"	TOP & BOT - TRANS - @ LG SUP
S30	4	5	3	6	SHOWN	"	LONG - @ LG SUP
S31	4	5	6	3	"	"	"




SPLICE 1 & 2




SPLICE 3:4


SPLICE #3 SHOWN SPLICE #4
SIMILAR EXCEPT FOR NO SHIM R




SPLICE 5 & 6




SPLICE 7 & 8



DETAIL A




DETAIL B



DETAIL C

BILL OF BARS

POUR	MARK	NO	SIZE	LENGTH	SPACING	LOCATION
RAILING PARAPET	R1	8	5	20'-0"	SHOWN	RAILING PARAPET
	R2	8	5	14'-0"	"	"
	R3	4	5	20'-5"	"	"
	R4	4	5	23'-3"	"	"
	R5	4	5	24'-9"	"	"
	R6	4	5	20'-6"	"	"
	R7	4	5	21'-6"	"	"
	R8	4	5	16'-6"	"	"
	R9	8	5	17'-6"	"	"
	R10	8	5	12'-6"	"	"
	R11	4	5	24'-6"	"	"
	R12	4	5	23'-0"	"	"
	R13	4	5	21'-3"	"	"
	R14	4	5	24'-0"	"	"
	R15	4	5	22'-0"	"	"
	R16	4	15	12'-5"	"	"




POURING DIAGRAM

NOTE: TWO OR MORE POURS MAY BE COMBINED AND THE TRANSVERSE CONST JOINTS OMITTED IF THE POUR FOR AN ENTIRE SPAN OR THE PORTION OF A SPAN TO A CONST JOINT CAN BE COMPLETED WITHIN FOUR HOURS AFTER CONCRETE OVER THE ADJACENT PIER IS PLACED.

NOTE DIRECTION OF POUR MAY BE REVERSED IF PORTION OF POUR FROM THE PIER CAN BE COMPLETED IN A 4-HOUR PERIOD.



DETAIL D




DETAIL


REVISED 	STATE HIGHWAY COMMISSION OF WISCONSIN	
	SUPERSTRUCTURE	
	DESIGN SPEC A A 5 H O	W/LOADING H 20 S 16 (1) COMB'D SPEC 1963
	DATE 11-5-63 DESIGN V G H DRAWN J C K, CRD J M	
STRUCTURE B 40-280		SHEET 3 OF 15

X27922




PROJECT: FORT-1(22) 173 383




LONGITUDINAL SECTION
FOR LOCATION & DETAILS OF STRINGER.
SPlice SEE K27923
SECTION IS PARALLEL TO STRINGER.



BEARING TYPE 'A'
2 REQ'D.




BEARING TYPE 'B'
1 REQ'D.





BEARING NOTES

- ALL STRUCTURAL STEEL BEARING PLATES SHALL BE FLAT ROLLED STEEL PLATES WITH ALL SURFACES SMOOTH & FREE FROM WARP & ALL EDGES SMOOTH, STRAIGHT, & VERTICAL.
- ALL PLATE CUTS SHALL BE MACHINE FLAME CUTS OR MACHINE CUTS.
- PINTLES SHALL BE MACHINED TO A DRIVING FIT. CHAMFER TOP OF PINTLE 1/8\"/>
- LUBRICATE TOP SURFACES ONLY OF BRONZE PLATES.
- ANCHOR BOLTS TO BE 1/2\"/>
- ALL MATERIAL EXCLUDING ANCHOR BOLTS, NUTS, AND WASHERS SHALL BE MADE OF A242 STEEL WITH A CORROSIVE RESISTANCE OF 4 OR MORE TIMES THAT OF A36 STEEL.
- THE TOP 4\"/>
- ALL MATERIAL IN BEARINGS, EXCLUDING BRONZE PLATES AND BEARING PADS SHALL BE PAID FOR AT THE UNIT PRICE BID FOR STRUCTURAL LOW ALLOY STEEL.
- ALL SURFACES MARKED 'F' SHALL BE MACHINE FINISHED.



BEARING TYPE 'C'
2 REQ'D.




* BRG 'A' = 3\"/>


FATI HIGHWAY COMMISSION OF WISCONSIN			
LONG. SECTION & BEARINGS			
STRINGER 1			
DESIGNED BY	AASVD GL	DATE	11-5-63
CHECKED BY	VGH	DATE	11-5-63
STRUCTURE	B 40-280	SHEET	4 OF 15

K27923


SHEET	PROJECT	TOTAL
FO27-1(22) 175	383	




SECTION E1




SECTION E2




TYPICAL DIAPHRAGM DETAIL



SECTION THRU JOINT AT CURB



SECTION THRU JOINT AT SIDEWALK



PART PLAN

EAST ABUT SHOWN, WEST ABUT SIMILAR EXCEPT SDWK & CURB ARE REVERSED TO OPPOSITE SIDES.

LEGEND

- 1. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 2. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 3. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 4. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 5. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 6. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 7. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 8. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 9. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 10. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 11. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 12. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 13. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 14. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 15. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 16. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 17. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 18. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 19. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 20. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 21. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 22. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 23. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 24. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 25. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 26. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 27. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.
- 28. 1/2" S.T. C.W. 36" x 36" ROWY. WIDTH.


NOTES

- EXPANSION JOINT SHALL BE BUILT TO CONFORM TO ROWY.
- SUPERELEVATION AND GRADE.
- ONE FIELD SPICE SHALL BE PERMITTED.
- ALL ITEMS, MARKED ** SHALL BE MADE OF A242 STEEL.
- WITH A CORROSIVE RESISTANCE OF 4 OR MORE TIMES THAT OF A36 STEEL.
- ALL MATERIAL IN EXPANSION JOINT SHALL BE PAID FOR AS STRUCTURAL LOW ALLOY STEEL.
- AFTER CONCRETE HAS SET REMOVE BOLTS #17 AND FILL HOLES WITH HOT POURED ELASTIC TYPE JOINT SEALER.
- NO PAINT SHALL BE APPLIED TO EXPANSION JOINT EXCEPT AS NOTED.
- AFTER CONCRETE HAS SET THE JOINT OPENING SHALL BE THOROUGHLY CLEANED.
- APPLY 1/2" COAT OF BITUMASTIC TO METAL SURFACES FORMING THE JOINT AND FILL WITH HOT POURED ELASTIC TYPE JOINT SEALER.
- *** 1/2" HOLE IN BAR #3 & 4.


NOTE: CONC END DIAPHRAGM TO EXTEND BETWEEN WEBS OF FASCIA STRINGERS

REVISION	STATE HIGHWAY COMMISSION OF WISCONSIN
	EXPANSION JOINT
DESIGN SPEC A A S H O 501	LOADING H 20 S16
DATE 11-5-63	BY J C K
STRUCTURE B-40-280	SHEET 6 OF 15


X27925




PART ELEVATION




PART PLAN




SECTION A




END PLATE SHIM DETAILS




POST SHIM DETAILS




ANCHOR BOLT SETTING DETAILS




AT POSTS



SECTION THRU SIDEWALK




SECTION THRU CURB




POST DETAILS

NOTES

- 1 STEEL RAIL POSTS SHALL BE SET NORMAL TO GRADE.
- 2 RAILING SHALL BE FABRICATED IN LENGTHS AS SHOWN.
- 3 STEEL SHIMS SHALL BE USED UNDER POSTS AND UNDER END PLATES WHERE REQUIRED FOR ALIGNMENT.
- 4 WHEN PARAPETS AND CURBS ARE POURED CONTINUOUSLY FROM END TO END THEY SHALL BE SEPARATED AT THE DEFLECTION JOINTS BY A PIECE OF ZINC OR ALUMINUM PLATE CUT AS SHOWN IN SECTION A BY SHADDED AREA. IF INSTRUCTION JOINTS IN PARAPETS AND CURBS ARE USED AT THE DEFLECTION JOINTS ONE SIDE OF JOINT SHALL BE COATED WITH BITUMINOUS PAINT AND PLATE SEPARATORS MAY BE OMITTED.
- 5 THE FOLLOWING MATERIALS SHALL BE USED:
TOP RAILING SHALL BE 3 1/2" STANDARD PIPE ASTM DESIGNATION A53.
BOTTOM RAILING SHALL BE 3" STANDARD PIPE ASTM DESIGNATION A53.
POST SHALL BE FABRICATED FROM MATERIAL CONFORMING TO ASTM DESIGNATION A36.
ANCHOR BOLTS TO BE MADE FROM MATERIAL CONFORMING TO ASTM DESIGNATION A307.
SLEEVES SHALL BE 3" STANDARD PIPE ASTM DESIGNATION A53 FOR TOP RAIL AND 3 SEAMLESS STEEL TUBING (1/4" WALL THICKNESS) FOR BOTTOM RAIL.
6 CAULK EXPOSED OPENINGS BETWEEN SHIMS WITH LEAD WOOL.



SHOP RAIL SPLICE DETAIL




FIELD ERECTION JOINT DETAIL

IF USED THE LOCATION OF THE SHOP SPLICE SHALL BE SHOWN ON THE SHOP DRAWINGS.

REVISION	STATE HIGHWAY COMMISSION OF WISCONSIN
	TUBULAR STEEL RAILING
	TYPE "B"
DESIGN SPEC	AASHTO '67
LOADING	20 KIP
DATE	1963
DATE II-S-G-5	DESIGN 572
DRAWN	JCK
CHECK	24
STRUCTURE	B-40-280
SHEET	7 OF 15



X27926

REV	DESCRIPTION	DATE	BY	CHK
4	FO27-(22) 177 383			



DETAIL AT TOP OF CURB & PARAPET


* THE T HEIGHT OF CURB SHALL BE MAINTAINED AT ALL POINTS OF BEARING.



ALUMINUM POST CASTING


NOTES

1. ALUMINUM RAILING POSTS TO BE SET NORMAL TO GRADE.
2. THE HEX NUTS, WASHERS AND THE UPPER 3' OF 4" x 4" LONG ANCHOR BOLTS SHALL BE GALVANIZED OR CADMIUM PLATED. THE ANCHOR BOLT HOLES, BASE OF RAILING POSTS AND ANCHOR BOLTS, NUTS AND WASHERS SHALL BE COATED WITH AN ALUMINUM IMPREGNATED CAULKING COMPOUND. ANCHOR BOLTS, HEX NUTS AND WASHERS TO BE STRUCTURAL CARBON STEEL.
3. ALUMINUM TUBING SHALL BE FABRICATED IN 2 OR 3 PANEL LENGTHS.
4. ALUMINUM ALLOY SHIMS SHALL BE USED UNDER POSTS AND UNDER END PLATES WHERE REQUIRED FOR ALIGNMENT.
5. WHEN PARAPETS AND CURBS ARE CURED CONTINUOUSLY FROM END TO END THEY SHALL BE SEPARATED AT THE DEFLECTION JOINTS BY A PIECE OF 1/2" ZINC OR ALUMINUM PLATE CUT AS SHOWN IN SECTION "B" BY THE SHADED AREA. IF CONSTRUCTION JOINTS IN PARAPETS AND CURBS ARE USED AT THE DEFLECTION JOINTS ONE SIDE OF JOINT SHALL BE COATED WITH BITUMINOUS PAINT AND PLATE SEPARATORS MAY BE OMITTED.




PART PLAN


DOUBLE LINE ALUMINUM RAILING



END PLATE (ALUMINUM)




END PLATE SHIM DETAILS




POST SHIM DETAILS

SECTION THRU SIDEWALK



SECTION B


SECTION C



AT END PLATE

AT POSTS

ANCHOR BOLT SETTING DETAILS





SECTION THRU CURB


REVISED	STATE HIGHWAY COMMISSION OF WISCONSIN
	TUBULAR ALUMINUM RAILING TYPE B
	DESIGN SPEC A.A.S.H.O. 61 LOADINGS 20 SIL 1963
	DATE 11-5-63 DESIGN BY D. DRAWN BY N. CHK. M.
	B-40-280 SHEET 8 OF 15

X 27927


DIVISION	PROJECT	SHEET NO	TOTAL SHEETS
4	F027-1(22)	178	383



REINFORCEMENT
PLAN AT LIGHT STANDARD




TRANSFORMER BASE BOLT LOCATION




ANCHOR BOLT DETAIL

NOTE: ANCHOR ASSEMBLY TO BE INCLUDED IN BID
ITEM "STRUCTURAL CARBON STEEL."



PLAN AT LIGHT STANDARD




PLAN

ESTIMATED QUANTITIES FOR ELECTRICAL WORK

ITEM	UNIT	QUANTITY
2½" GALV STEEL CONDUIT	LF	202
2" GALV STEEL CONDUIT	LF	15
15" x 12" x 6" FLANGED JUNCTION BOX	EACH	2
EXPANSION FITTING (2½")	EACH	2
2½" GALV PIPE CAPS	EACH	2
2" GALV PIPE CAPS	EACH	2

ONLY MAJOR ITEMS ARE LISTED IN ESTIMATED QUANTITIES FOR ELECTRICAL WORK AND ARE GIVEN FOR THE CONTRACTORS CONVENIENCE THE CONTRACTOR SHALL VERIFY THEIR ACCURACY



DETAIL OF EXPANSION FITTING

NOTES

PAINT ALL EMBEDDED CONDUIT FOR 18" ON EACH SIDE OF THE DEFLECTION JOINT IN SIDEWALK WITH A HEAVY COAT OF BITUMINOUS PAINT.

REVISION 	STATE HIGHWAY COMMISSION OF WISCONSIN		
	LIGHTING DETAILS		
	DESIGN BY: AASHO '61	LOADING: H20 S16	CONSTR. DATE: 1969
	DATE: 11-6-63	DESIGN: VGH	DRAWN: JCK
STRUCTURE B-40-280		SHEET 9 OF 15	



X27928

BILL OF BARS 5,110 #


DIMENSIONS IN BENDING DETAILS ARE OUT TO CWT.

FOUR	MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET
FOOTINGS	B1	16	6	7-3	SHOWN	EXTERIOR FOOTINGS	
	B2	18	5	6-9	SHOWN	" "	
	B3	10	7	8-3	SHOWN	INTERIOR "	
	B4	10	7	8-0	SHOWN	" "	
	B5	16	7	3-6	SHOWN	FOOTING & COLUMNS "	B
	B6	3	4	9-6	SHOWN	" - HOOPS	C
	B6	46	4	9-6	SHOWN	COLUMN - HOOPS	C
	B7	6	7	24-6	SHOWN	COLUMN 1 VERT	B
	B8	6	7	19-0	SHOWN	" 1 "	B
COLUMNS & GIRDER	B9	12	7	18-0	SHOWN	" 2 "	
	B10	6	7	20-3	SHOWN	" 3 "	B
	B11	6	7	25-6	SHOWN	" 3 "	B
	B12	6	10	14-0	SHOWN	GIRDER TOP "	
	A13	6	10	10-0	SHOWN	" " "	
	B14	8	11	17-6	SHOWN	" BOTTOM	
	B15	20	4	11-9	SHOWN	" STIRRUPS	D
	B16	24	5	10-3	SHOWN	" "	D
	B17	4	11	20-0	SHOWN	" BOTTOM	
	B18	8	5	11-6	SHOWN	" TOP	
	B19	4	4	20-0	SHOWN	" SIDES	
	B20	4	4	6-3	SHOWN	" ENDS	A


** BUNDLE BARS.
 * SAME SPACING AS VERTICAL COLUMN BARS.




DETAIL A



DETAIL B




DETAIL C




SECTION THRU COLUMNS

CONCRETE MASONRY


FOOTINGS	13.8	C.Y.
COLUMNS	12.1	C.Y.
BIRDER	14.7	C.Y.
TOTAL	40.6	C.Y.




DETAIL D




SECTION A-A



SECTION B-B




SECTION C-C



EXTERIOR FOOTING

FOOTING PLAN



ELEVATION

NOTE: BAR STEEL REINF. IS
SYM ABOUT 6 OF COL "2"
EXCEPT AS SHOWN.

1-6" x 1-6" x 4" KEY
CONST. JOINT. —

8'x2' SPALL
NORTH FACE

DIVISION	PROJECT	SHEET NO.	TOTAL SHEETS
4	FO27-1(22) 181	383	


BILL OF BARS 6450 #

DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT

ITEM	MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET.
FOOTINGS	C1	26	5	7-6	SHOWN	EXTERIOR FOOTING	
	C2	28	6	9-6	SHOWN	"	
	C3	16	7	10-6	SHOWN	INTERIOR "	
	C4	13	6	8-0	SHOWN	"	
	C5	42	8	4-0	SHOWN	FOOTING & COLUMNS	B
	C6	3	4	9-6	1-0	" - HOOPS	C
COLUMNS & GIRDER	C6	43	4	9-6	SHOWN	COLUMN - HOOPS	C
	C7	6	8	23-6	SHOWN	COLUMN 1 VERT.	B
	C8	6	8	18-0	SHOWN	" 1 "	B
	C9	14	8	17-0	SHOWN	" 2 "	B
	C10	6	8	19-0	SHOWN	" 3 "	B
	C11	6	8	24-6	SHOWN	" 3 "	B
	C12	6	10	14-0	SHOWN	GIRDER TOP **	
	C13	6	10	10-0	SHOWN	"	
	C14	8	11	17-6	SHOWN	" BOTTOM	
	C15	20	4	11-9	SHOWN	" STIRRUPS	D
	C16	24	5	10-3	SHOWN	"	D
	C17	4	11	20-0	SHOWN	" BOTTOM	
	C18	8	5	11-6	SHOWN	" TOP	
	C19	4	4	20-0	SHOWN	" SIDES	
	C20	4	4	6-3	SHOWN	" ENDS	A
	C21	2	8	17-6	SHOWN	COLUMN 3 VERT.	
	C22	2	8	6-3	SHOWN	" 1 "	

** BUNDLE BARS
* SAME SPACING AS VERTICAL COLUMN BARS


6-8"	C7 C11
4-0"	C8 C10
9"	C5



DETAIL A

DETAIL B

DETAIL C







SECTION THRU COLUMNS


CONCRETE MASONRY

FOOTINGS	18.8 C.Y.
COLUMNS	11.3 C.Y.
GIRDER	14.6 C.Y.
TOTAL	44.7 C.Y.


DETAIL D




PLAN



SECTION A-A



SECTION B-B






SECTION C-C

STATE HIGHWAY COMMISSION OF WISCONSIN
PIER 2
DESIGN SPEC. A.S.H.D. 61
DATE 11-5-63
STRUCTURE B-40-280

23-DEC-1997 10:10






ScreenScan



BILL OF BARS 4,800 #

DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT

MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET
D1	16	5	6'-9	SHOWN	EXTERIOR FOOTINGS	
D2	16	5	6'-3	SHOWN	"	
D3	8	7	7'-9	SHOWN	INTERIOR	
D4	8	7	7'-6	SHOWN	"	
D5	36	7	3'-6	SHOWN	FOOTING & COLUMNS	B
D6	3	4	9'-6	SHOWN	" HOOPS	C
D6	4	4	9'-6	SHOWN	"	C
D7	6	7	23'-0	SHOWN	COLUMN 1 VERT	B
D8	6	7	17'-9	SHOWN	" 1 "	B
D9	12	7	16'-6	SHOWN	" 2 "	B
D10	6	7	18'-9	SHOWN	" 3 "	B
D11	6	7	24'-0	SHOWN	" 3 "	B
D12	6	10	14'-0	SHOWN	GIRDER TOP	
D13	6	10	10'-0	SHOWN	"	
D14	8	11	17'-6	SHOWN	" BOTTOM	
D15	20	4	11'-9	SHOWN	" STIRRUPS	D
D16	24	5	10'-3	SHOWN	"	D
D17	4	11	20'-0	SHOWN	" BOTTOM	
D18	8	5	11'-6	SHOWN	" TOP	
D19	4	4	20'-0	SHOWN	" SIDES	
D20	4	4	6'-3	SHOWN	" ENDS	A



CONCRETE MASONRY

FOOTINGS	12.2 C.Y.
COLUMNS	11.0 C.Y.
GIRDER	14.8 C.Y.
TOTAL	38.0 C.Y.

STATE HIGHWAY COMMISSION OF WISCONSIN

PIER 3

DESIGN SPEC. AASHO 61, LOADING H20 S16, 1963

DATE 11-5-63, DESIGN V.S.H., DRAWN C.H.P., CRD











STRUCTURE B-40-280, SHEET 13 OF 15

X 27932



BILL OF BARS 2140

DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT.

POUR MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET
E1	18	4	23-3	SHOWN	BODY - HORIZ.	
E2	46	4	4-8	1-0	" - VERT	A
E3	6	6	23-6	SHOWN	" - HORIZ.	
E4	23	4	13-3	2-0	" - VERT	B
E5	6	4	18-9	SHOWN	PARAPET - HORIZ.	
E6	35	5	4-9	1-0	" - VERT	C
E7	8	4	8-6	SHOWN	" - HORIZ. DO NOT LAP	
E8	23	5	8-3	1-8	" - VERT	C
E9	16	4	6-6	6	PARAPET & SDWK.	D
E10	10	4	4-9	SHOWN	BODY & WING	D
E11	3	4	16-0	1-6	WING 3	D
E12	6	4	8-3	1-8	" 3	
E13	8	4	8-9	1-8	" 3	
E14	6	4	1-0	1-8	" 4	D
E15	5	4	9-3	1-8	" 4	
E16	9	4	9-3	1-8	" 4	
E17	28	4	3-9	SHOWN	GRID	D
E18	20	4	4-0	SHOWN	"	
E19	8	5	9-3	SHOWN	RAILING PARAPET	
E20	20	5	6-0	1-0	"	C
E21	8	4	10-9	1-6	WING 3	
E22	8	4	12-3	1-6	" 4	
E23	3	4	11-0	1-6	" 3	D




PROJECT NO.	4
PROJECT	F027-1(22)
SHEET NO.	184
TOTAL SHEETS	383



SUBSURFACE EXPLORATION FOR FOUNDATION DESIGN

FOR THE DESIGN OF THE STRUCTURE FOUNDATION, TO OBTAIN RELATIVE DATA CONCERNING THE CHARACTER OF MATERIAL IN AND UPON WHICH THE FOUNDATION MIGHT BE BUILT, BORINGS AND/OR SOUNDINGS WERE MADE AT POINTS APPROXIMATELY AS INDICATED ON THIS DRAWING WITH THE LOG OF SUCH EXPLORATION DATA AS INTERPRETED FOR SUCH DESIGN PURPOSE AS SHOWN. THE EXPLORATIONS WERE MADE BY ORDINARY AND CONVENTIONAL METHODS AND ARE DEEMED ADEQUATE FOR SUCH PURPOSE. HOWEVER, SINCE IT IS A MATTER OF COMMON KNOWLEDGE THAT THE EXACT CHARACTER OF ANY MATERIAL AND ITS REACTION IS DIFFICULT TO DETERMINE FROM SUCH SUBSURFACE EXPLORATION AND THAT THE KIND AND CHARACTER OF MATERIAL AT THE SITE WHERE THE FOUNDATIONS ARE BUILT MAY VARY SUBSTANTIALLY FROM THAT INDICATED BY THE LOG THEY ARE MADE AVAILABLE TO THE BIDDERS SIMPLY FOR WHAT THEY ARE WORTH, WITHOUT ANY WARRANTY, EXPRESSED OR IMPLIED THAT THE MATERIAL TO BE ENCOUNTERED IN BUILDING THE FOUNDATION WILL CONFORM THEREWITH. IF THE LOG IS USED BY THE CONTRACTOR IN MAKING HIS BID, IT IS HEREBY EXPRESSLY STIPULATED THAT THE COMMISSION ACCEPTS NO RESPONSIBILITY FOR SAID USE.


UNLESS OTHERWISE SPECIFIED THE BLOWS PER FOOT AT THE LOCATIONS INDICATED ARE BASED ON DRIVING A 2" OD x 1.4" ID SPLIT SPOON SAMPLER WITH A 140 LB. HAMMER HAVING A FREE FALL OF 30 INCHES. THE BLOW COUNT IS TAKEN IN UNDISTURBED SOIL IMMEDIATELY BELOW A CASED OR OPEN HOLE ELIMINATING SIDE FRICTION ON THE DRIVE PIPE.




STATE HIGHWAY COMMISSION OF WISCONSIN			
SUBSURFACE EXPLORATION			
11-5-63 DB 184 1963 H2056			
STRUCTURE	B-40-280	SHEET	15 OF 15

X27934

LOOKING
EAST



LOOKING WEST



SLOPE PAVING

B-40-280

ATTACHMENT 3
ASBESTOS REPORT



708 Heartland Trail, Suite 3000
Madison, WI 53717

608.826.3600 PHONE
608.826.3941 FAX

www.TRCSolutions.com

Bridge Asbestos Inspection Report

WisDOT Project ID: 0656-50-30

Structure Number: B-40-0280

Structure Name: W. Grantosa Drive WB over STH 145/Fond du Lac Avenue

City/County: City of Milwaukee, Milwaukee County

Lat/Long Coordinates: 430645.22/ 880008.74

TRC Project Number: 283673.0000.0000

Date Inspected: July 20, 2017

Inspected By/License Number: Ross Hartwick, All-195369

Findings:

Files available online for this bridge were reviewed, including the "As-built" drawings. The inspection to identify and collect samples of potential asbestos-containing material (ACM) was completed following WisDOT standard sampling procedure for bridge inspections found in FDM 21-35-45.


The gasket located under the railing attachment plates on the concrete parapet tested positive for asbestos greater than 1% and is therefore regulated ACM. If the ACM will be disturbed during the planned bridge rehabilitation, the ACM must be removed prior to any work. Standard Special Provision (STSP) 203-005 should be incorporated into the specifications. If the ACM will not be disturbed during the planned bridge rehabilitation, STSP 107-120 should be included in the specifications.

Sample Number	Sample Description	Sample Location	Analytical Results and Method	Friable/ Non-friable or No ACM	Quantity of ACM Material
WB-1	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	0
WB-2	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	
WB-3	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	

Sample Number	Sample Description	Sample Location	Analytical Results and Method	Friable/ Non-friable or No ACM	Quantity of ACM Material
WB-4	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	0
WB-5	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	
WB-6	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	
WB-7	Gasket	Under railing attachment plate	PLM, 5%	Non-friable	7.5"x34"x2 + 7.5"x7.5"x28 = 14.5 sq ft
WB-8	Gasket	Under railing attachment plate	Not analyzed, positive stop	--	
WB-9	Gasket	Under railing attachment plate	Not analyzed, positive stop	--	
WB-10	Tar	Bearing support piers	PLM, non-detect	No ACM	0
WB-11	Tar	Bearing support piers	PLM, non-detect	No ACM	
WB-12	Tar	Bearing support piers	PLM, non-detect	No ACM	
WB-13	Silver paint	Girder	PLM, non-detect	No ACM	0
WB-14	Silver paint	Girder	PLM, non-detect	No ACM	
WB-15	Silver paint	Girder	PLM, non-detect	No ACM	
WB-16	Silver paint	Galvanized metal conduit	PLM, non-detect	No ACM	0
WB-17	Silver paint	Galvanized metal conduit	PLM, non-detect	No ACM	
WB-18	Silver paint	Galvanized metal conduit	PLM, non-detect	No ACM	

If you have any questions, please contact me, at (608) 826-3628.

TRC Environmental Corporation



Daniel Haak
Project Manager




Ross Hartwick
Asbestos Inspector

Attachments: Location Map, Photos, and Laboratory Report

Report Distribution:

Recipient	Electronic (PDF) Copy	Paper Copy
BTS-ESS sharlene.tebeest@dot.wi.gov	X (via email)	X
REC Andrew.malsom@dot.wi.gov	X (via email)	
Project Manager jason.zemke@dot.wi.gov	X (via email)	
Other		



B-40-0280

Bridge B-40-0280



Black paint on pedestrian fence and railing



Caulk in parapet expansion joint and sidewalk joint



Gasket under railing attachment plate on parapet



Tar on bridge bearing support piers



Silver paint on girder



Silver paint on galvanized metal conduit



BULK ASBESTOS ANALYSIS REPORT

CLIENT: Wisconsin Department of Transportation

Lab Log #: 0050965
Project #: 283673.0000.0000
Date Received: 07/21/2017
Date Analyzed: 07/21/2017

Site: Bridge Inspection, B-40-280

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials		Asbestos %	Asbestos Type
WB-01	Black (paint)	Yes	No	--	---		ND	None
WB-02	Black (paint)	Yes	No	--	---		ND	None
WB-03	Black (paint)	Yes	No	--	---		ND	None
WB-04	Grey (caulk)	Yes	No	--	---		ND	None
WB-05	Grey (caulk)	Yes	No	--	---		ND	None
WB-06	Grey (caulk)	Yes	No	--	---		ND	None
WB-07	Grey (gasket)	Yes	No	--	---		5%	Chrysotile
WB-08	--	--	--	--	--		NA/PS	--
WB-09	--	--	--	--	--		NA/PS	--
WB-10	Dark Grey (tar)	Yes	No	--	10%	synthetic fiber	ND	None
WB-11	Dark Grey (tar)	Yes	No	--	10%	synthetic fiber	ND	None
WB-12	Dark Grey (tar)	Yes	No	--	10%	synthetic fiber	ND	None
WB-13	Black/Silver (paint)	Yes	No	--	---		ND	None
WB-14	Black/Silver (paint)	Yes	No	--	---		ND	None
WB-15	Black/Silver (paint)	Yes	No	--	---		ND	None
WB-16	Black/Brown (paint)	Yes	No	--	---		ND	None
WB-17	Black/Brown (paint)	Yes	No	--	---		ND	None

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0
RI #AAL-007 TX #300354
CO# AL-15020

AIHA-LAP, LLC #100122 CT #PH-0426
VT #AL014538 LA#05011 VA #3333 000283
PHIL# 461 PA#68-03387

ME LA-0075, LB-0071
AZ #A20944

MA #AA000052
HI #L-09-004

NY #10980 WV#LT000411
NJ #CT004 CA #2907



POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
WB-18	Black/Brown (paint)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%

ND - asbestos was not detected

Trace - asbestos was observed at level of less than 1%

NA/PS - Not Analyzed / Positive Stop

SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by:

Kathleen Williamson, Laboratory Manager

Reviewed by:

Cathryn Lemire, Approved Signatory

Date Issued

07/23/2017

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0	AIHA-LAP, LLC #100122	CT #PH-0426	ME LA-0075, LB-0071	MA #AA000052	NY #10980	WV# LT000411
RI #AAL-007	TX #300354	VT #AL014538	LA#05011	VA #3333 000283	AZ #A20944	HI #L-09-004
CO# AL-15020	PHIL# 461	PA#68-03387			NJ #CT004	CA #2907

ATTACHMENT 3
ASBESTOS REPORT



708 Heartland Trail, Suite 3000
Madison, WI 53717

608.826.3600 PHONE
608.826.3941 FAX

www.TRCSolutions.com

Bridge Asbestos Inspection Report

WisDOT Project ID: 0656-50-30

Structure Number: B-40-0280

Structure Name: W. Grantosa Drive WB over STH 145/Fond du Lac Avenue

City/County: City of Milwaukee, Milwaukee County

Lat/Long Coordinates: 430645.22/ 880008.74

TRC Project Number: 283673.0000.0000

Date Inspected: July 20, 2017

Inspected By/License Number: Ross Hartwick, All-195369

Findings:

Files available online for this bridge were reviewed, including the "As-built" drawings. The inspection to identify and collect samples of potential asbestos-containing material (ACM) was completed following WisDOT standard sampling procedure for bridge inspections found in FDM 21-35-45.


The gasket located under the railing attachment plates on the concrete parapet tested positive for asbestos greater than 1% and is therefore regulated ACM. If the ACM will be disturbed during the planned bridge rehabilitation, the ACM must be removed prior to any work. Standard Special Provision (STSP) 203-005 should be incorporated into the specifications. If the ACM will not be disturbed during the planned bridge rehabilitation, STSP 107-120 should be included in the specifications.

Sample Number	Sample Description	Sample Location	Analytical Results and Method	Friable/ Non-friable or No ACM	Quantity of ACM Material
WB-1	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	0
WB-2	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	
WB-3	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	

Sample Number	Sample Description	Sample Location	Analytical Results and Method	Friable/ Non-friable or No ACM	Quantity of ACM Material
WB-4	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	0
WB-5	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	
WB-6	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	
WB-7	Gasket	Under railing attachment plate	PLM, 5%	Non-friable	7.5"x34"x2 + 7.5"x7.5"x28 = 14.5 sq ft
WB-8	Gasket	Under railing attachment plate	Not analyzed, positive stop	--	
WB-9	Gasket	Under railing attachment plate	Not analyzed, positive stop	--	
WB-10	Tar	Bearing support piers	PLM, non-detect	No ACM	0
WB-11	Tar	Bearing support piers	PLM, non-detect	No ACM	
WB-12	Tar	Bearing support piers	PLM, non-detect	No ACM	
WB-13	Silver paint	Girder	PLM, non-detect	No ACM	0
WB-14	Silver paint	Girder	PLM, non-detect	No ACM	
WB-15	Silver paint	Girder	PLM, non-detect	No ACM	
WB-16	Silver paint	Galvanized metal conduit	PLM, non-detect	No ACM	0
WB-17	Silver paint	Galvanized metal conduit	PLM, non-detect	No ACM	
WB-18	Silver paint	Galvanized metal conduit	PLM, non-detect	No ACM	

If you have any questions, please contact me, at (608) 826-3628.

TRC Environmental Corporation



Daniel Haak
Project Manager




Ross Hartwick
Asbestos Inspector

Attachments: Location Map, Photos, and Laboratory Report

Report Distribution:

Recipient	Electronic (PDF) Copy	Paper Copy
BTS-ESS sharlene.tebeest@dot.wi.gov	X (via email)	X
REC Andrew.malsom@dot.wi.gov	X (via email)	
Project Manager jason.zemke@dot.wi.gov	X (via email)	
Other		



Bridge B-40-0280



Black paint on pedestrian fence and railing



Caulk in parapet expansion joint and sidewalk joint



Gasket under railing attachment plate on parapet



Tar on bridge bearing support piers



Silver paint on girder



Silver paint on galvanized metal conduit



BULK ASBESTOS ANALYSIS REPORT

CLIENT: Wisconsin Department of Transportation

Lab Log #: 0050965
Project #: 283673.0000.0000
Date Received: 07/21/2017
Date Analyzed: 07/21/2017

Site: Bridge Inspection, B-40-280

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials		Asbestos %	Asbestos Type
WB-01	Black (paint)	Yes	No	--	---		ND	None
WB-02	Black (paint)	Yes	No	--	---		ND	None
WB-03	Black (paint)	Yes	No	--	---		ND	None
WB-04	Grey (caulk)	Yes	No	--	---		ND	None
WB-05	Grey (caulk)	Yes	No	--	---		ND	None
WB-06	Grey (caulk)	Yes	No	--	---		ND	None
WB-07	Grey (gasket)	Yes	No	--	---		5%	Chrysotile
WB-08	--	--	--	--	--		NA/PS	--
WB-09	--	--	--	--	--		NA/PS	--
WB-10	Dark Grey (tar)	Yes	No	--	10%	synthetic fiber	ND	None
WB-11	Dark Grey (tar)	Yes	No	--	10%	synthetic fiber	ND	None
WB-12	Dark Grey (tar)	Yes	No	--	10%	synthetic fiber	ND	None
WB-13	Black/Silver (paint)	Yes	No	--	---		ND	None
WB-14	Black/Silver (paint)	Yes	No	--	---		ND	None
WB-15	Black/Silver (paint)	Yes	No	--	---		ND	None
WB-16	Black/Brown (paint)	Yes	No	--	---		ND	None
WB-17	Black/Brown (paint)	Yes	No	--	---		ND	None

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0
RI #AAL-007 TX #300354
CO# AL-15020

AIHA-LAP,LLC #100122 CT #PH-0426
VT #AL014538 LA#05011 VA #3333 000283
PHIL# 461 PA#68-03387

ME LA-0075, LB-0071
AZ #A20944

MA #AA000052
HI #L-09-004

NY #10980 WV#LT000411
NJ #CT004 CA #2907



POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
WB-18	Black/Brown (paint)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%

ND - asbestos was not detected

Trace - asbestos was observed at level of less than 1%

NA/PS - Not Analyzed / Positive Stop

SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: <u>K. Williamson</u> Kathleen Williamson, Laboratory Manager	Reviewed by: <u>Cathryn Lemire</u> Cathryn Lemire, Approved Signatory	Date Issued 07/23/2017
---	---	----------------------------------

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0	AIHA-LAP, LLC #100122	CT #PH-0426	ME LA-0075, LB-0071	MA #AA000052	NY #10980	WV# LT000411
RI #AAL-007	TX #300354	VT #AL014538	LA#05011	VA #3333 000283	AZ #A20944	HI #L-09-004
CO# AL-15020	PHIL# 461	PA#68-03387			NJ #CT004	CA #2907

ATTACHMENT 4
STRUCTURE ALTERNATIVE
REPORT & ASSOCIATED E-MAILS



collaborāte / formulāte / innovāte

MEMORANDUM

TO: Roy Stollenwerk, P.E. & Christine Hanna, P.E.

FROM: GRAEF

DATE: October 26, 2018

SUBJECT: Bridge Alternative Life Cycle Cost Analysis
ID 1360-11-00
Grantosa Dr. over STH 145
Bridges B-40-280 and B-40-281
Milwaukee County

Construction is planned on two bridges over STH 145 as part of Project 1360-11-70. The project is scheduled for a PS&E date of May 1, 2020 and construction is currently scheduled for 2021.

The abutments on Bridges B-40-280 and B-40-281 are supported by spread footings. A site visit on March 23, 2018 indicated the east abutments of both bridges had slid towards STH 145, and possibly rotated. Although efforts to address the abutment movements were made in 1992 by way of lengthening the expansion slots of the hold-down bearings, at the time of GRAEF's inspection additional movements had taken place which had left the expansion bearings significantly out of alignment. As a result, alternatives to address the abutment movements were investigated.

Bridge improvement options include:

1. Conversion of the east and west abutments on both bridges to semi-expansion seats.
2. Replacement of the east and west abutments on both bridges
3. Complete bridge replacement using steel girders that match the existing substandard vertical clearance.
4. Complete bridge replacement using prestressed girders that raise the roadway profile to meet a minimum vertical clearance of 16'-4".

For each alternative, a construction and life cycle cost analysis has been prepared. A 75-year analysis period has been selected based on the anticipated design life of newly constructed bridges in Wisconsin, and an effective discount rate of 3.5% was assumed. Future major construction/rehabilitation activities were assumed at specified years beyond the initial construction. Recurring future maintenance items (such as bridge inspections) were not included as these were assumed to be the same for all alternatives. Construction unit costs used for the life cycle cost analysis are listed in Appendix A.

Conversion to Semi-Expansion Abutments

Semi-expansion abutments allow the girder ends to contract in cold temperatures, but provide restraint in hotter temperatures. Use of ½" thick elastomeric girder bearing pads placed on polyethylene sheets allow the girder ends to freely slide and result in a low maintenance bearing system. Conversion of the existing abutments to semi-expansion abutments will require temporary shoring of the existing bridge girders, existing abutment removal above the bearing seats, removal of the existing steel hold-down bearing devices, placing new elastomeric bearing pads under the girders, and casting a solid diaphragm to encase the ends of the bridge girders. Cleaning and flame metallizing the girder ends will help to protect the steel from future corrosion due to encasement in the concrete diaphragms

Use of semi-expansion bearings on steel girder bridges is limited to 150-ft which is less than the existing 194-ft bridge length. The Bureau of Structures Development Unit is willing to grant an exception to this provision given the shallow 30" girder depth.

Because the existing abutment bodies will be reused and the original bridge was designed for an H-20 load, the soil bearing pressure was checked for the additional dead load of the semi-expansion bearing's concrete end diaphragm and the HS-20 live loading used for load rating purposes. Preliminary results using service loads indicate that the maximum soil bearing press is approximately 2.9 ksf at the abutment toe under full dead plus live loads. This is less than the 5.0 ksf allowable soil bearing pressure indicated in the original abutment design calculations, and suggests abutment conversion is a feasible option.

A second feasibility check for this alternative was performed to address girder uplift. AASHTO Standard Specifications 3.17.1 was checked using results from an MDX line girder model. Preliminary calculations indicate that the end diaphragm will need to be extended 2.5-ft beyond the abutment front face to provide adequate dead load to resist uplift forces. See Figure 1.




Figure 1: Conversion to Semi-expansion Abutment

For this alternative, the life cycle cost estimate considered that the existing bridge will be approximately 55 years old when rehabilitated. Appendix B lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 55 years - new deck construction, abutment conversion to semi-expansion bearings, steel girder repainting, and flame metallizing the steel girder ends. Miscellaneous repairs were assumed to cost 15% of the major rehabilitation items. Construction costs also include associated roadway approach work and contingencies.

Year 20, bridge age 75 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 35, bridge age 90 years – demolition and construction of a new prestressed concrete girder bridge with structural approach slabs. The new bridge length is assumed to be 7% greater than the existing bridge to accommodate the new roadway profile. Construction costs also include roadway work to raise Grantosa Drive, acquire right-of-way, and associated contingencies.

Year 55, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 70, bridge age 35 years - new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 75, bridge age 40 years – no major construction activities are anticipated at this stage. As part of the life cycle cost analysis, a residual value of the bridge was estimated to represent the remaining service life beyond year 75. It was estimated based on an anticipated NBI condition rating of 6 for a 40-year old bridge, prorated against an NBI rating of 9 when new and 3 at the end of its service life. The residual value is calculated as:

$$\frac{(\text{cost for a new bridge}) \times (\text{NBI}_{40} - \text{NBI}_{\text{service life}})}{(\text{NBI}_{\text{new}} - \text{NBI}_{\text{service life}})}$$

Abutment Replacements

For this alternative, type A3 pile supported abutments were assumed. Type A3 pile supported abutments have a minimum of 2 rows of piles with the front row battered to help resist lateral forces (see Figure 2). Current practice in Wisconsin is to generally use pile supported abutments to control vertical settlement. Replacement of the existing abutments will require temporary shoring of the existing bridge girders, existing abutment removal, pile driving, concrete placement for the new abutments and wingwalls, and installation of new hold-down expansion bearings under the girders. Given the age of the bridge, it was assumed that construction of new structure approach slabs would not be cost effective even though new abutments could be designed to handle these loads.



For this alternative, the life cycle cost estimate considered that the existing bridge will be approximately 55 years old when rehabilitated. Appendix C lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 20, bridge age 75 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 35, bridge age 90 years – demolition and construction of a new prestressed concrete girder bridge with structural approach slabs. The new bridge length is assumed to be 7% greater than the existing bridge to accommodate the new roadway profile. Construction costs also include roadway work to raise Grantosa Drive, acquire right-of-way, and associated contingencies.

Year 55, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 70, bridge age 35 years - new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 75, bridge age 40 years – no major construction activities are anticipated at this stage. As part of the life cycle cost analysis, a residual value of the bridge was estimated to represent the remaining service life beyond year 75. It was estimated using the same method for the semi-expansion abutment conversion alternative.

Complete Replacement with a New Steel Girder Bridge

This alternative replaces the existing structures with steel girder bridges at the same roadway profile as the existing. The current substandard vertical clearance will remain. For life cycle cost analysis purposes, a steel girder replacement bridge with the same total length, width, and substructure locations as the existing was assumed. This approach was judged to be feasible because the existing abutments and piers are founded on shallow footings and there are no existing piles to cause interferences. Caution must be exercised concerning pile design and driving to avoid the existing 24" sanitary sewer at the west abutment of B-40-280 and the west pier of B-40-281. Structure approach slabs were assumed to be constructed as part of the bridge replacement given the projected ADT on Grantosa Drive.

For this alternative, the life cycle cost estimate considered that the existing bridge will have a life span of 75 years. Appendix D lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 0 years – demolition and construction of a new steel girder bridge with structural approach slabs. The new bridge deck area is assumed to match the existing bridge.

Year 20, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 35, bridge age 35 years – new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 55, bridge age 55 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 75, bridge age 75 years – demolition and construction of a new prestressed concrete girder bridge is assumed, but these costs are not included in the life cycle analysis because the new bridge's service life falls beyond the 75-year study period. In addition, it is assumed that the existing bridge has no remaining usable service life and therefore no residual value.

Complete Replacement with a New Prestressed Concrete Girder Bridge

This alternative replaces the existing structures with 36" deep prestressed concrete girder bridges. Since this alternative requires raising the profile of Grantosa Drive, it is assumed the roadway profile is raised to attain the 16'-4" minimum vertical clearance required for STH 145. For life cycle cost analysis purposes, length of a prestressed concrete girder replacement bridge was approximated to be about 7% greater than the existing assuming a 3:1 embankment extension at the top of the existing. The bridge widths were assumed to be unchanged from the existing, as were the pier locations. This approach was judged to be feasible because the existing abutments and piers are founded on shallow footings and there are no existing piles to cause interference. Caution must be exercised concerning pile design and driving to avoid the existing 24" sanitary sewer at the west abutment of B-40-280 and the west pier of B-40-281. Structure approach slabs were assumed to be constructed as part of the bridge replacement given the projected ADT on Grantosa Drive.

Associated roadway improvements include raising the profile of Grantosa Drive approximately 2'-5" to attain a minimum vertical clearance of 16'-4" to meet FDM 11-35 requirements for new bridges. The required rise in roadway profile considers a 36W" prestressed concrete girder shape which has the capacity to span up to 100-ft. It is assumed that right-of-way acquisition will be required for the raised profile on Grantosa Drive.

For this alternative, the life cycle cost estimate considered that the existing bridge will have a life span of 75 years. Appendix E lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 0 years – demolition and construction of a new prestressed concrete girder bridge with structural approach slabs. The new bridge length is

assumed to be 7% greater than the existing bridge to accommodate the new roadway profile. Construction costs also include roadway work to raise Grantosa Drive, acquire right-of-way, and associated contingencies.

Year 20, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 35, bridge age 35 years – new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 55, bridge age 55 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 75, bridge age 75 years – demolition and construction of a new prestressed concrete girder bridge is assumed, but these costs are not included in the life cycle analysis because the new bridge's service life falls beyond the 75-year study period. In addition, it is assumed that the existing bridge has no remaining usable service life and therefore no residual value.

Conclusions

Results of the life cycle cost analyses are summarized in Table 1 below.

Table 1: Life Cycle Costs of Design Alternatives

Description	Initial Cost at Year 0	Life Cycle Cost at Present Value	Life Cycle Cost as an Annuity
Alternative 1 – Redeck and conversion to a semi-expansion abutment	\$1,230,000 per bridge, \$2,460,000 total	\$2,320,000 per bridge, \$4,640,000 total	\$87,900/bridge/year, \$176,000 total/year
Alternative 2 – Redeck and abutment replacement	\$1,530,000 per bridge, \$3,060,000 total	\$2,630,000 per bridge, \$5,270,000 total	\$99,800/bridge/year, \$200,000 total/year
Alternative 3 – Replacement with steel girder bridge	\$1,950,000 per bridge, \$3,900,000 total	\$2,410,000 per bridge, \$4,820,000 total	\$91,100/bridge/year, \$182,000 total/year
Alternative 4 – Replacement with prestressed concrete girder bridge	\$3,090,000 per bridge, \$6,180,000 total	\$3,510,000 per bridge, \$7,020,000 total	\$133,000/bridge/year, \$266,000 total/year

Recommendations

Results of the life cycle cost analysis show that Alternative 1, redeck and conversion to a semi-expansion abutment, has not only the lowest life cycle cost, but also the lowest first cost as part of the current project. This is a result of maximizing the existing bridge's

service life and original public investment, and of minimizing the amount of rehabilitation work needed to address the abutment movements.

A technical concern is the continued use of abutments experiencing excessive movements and hold-down bearings exhibiting uplift damage. These concerns are addressed by conversion to a semi-expansion abutment. Semi-expansion abutments by nature will provide lateral bracing against forces that tend to cause abutment sliding and overturning. In addition, final design to provide adequate dead load of the end diaphragms will eliminate undesirable live load uplift forces. A technical advantage offered by Alternative 1 is that pile driving is not needed, thereby eliminating the risk of damaging the existing 24" sanitary sewer.

Given the economic and technical benefits, we recommend that Alternative 1 be selected as the preferred option.

KGW:kgw

X:\ML\2017\20170145\Project_Information\Reports\Bridge Alternative Study\1360-11-00_STH 145 - Bridge Alternative Study Memo.docx

cc: File

APPENDIX A

Construction Unit Costs

Rehab Unit Prices from WisDOT Year End Structure Cost Summary Spreadsheets and the WisDOT Bridge Manual

New Steel Bridge

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2016	\$147.09	\$168.37	Say \$175/SF
2015	\$201.30		
2014	\$182.81		
2013	\$142.28		
Sum =		\$673.48	

New PPC Bridge

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$123.10	\$116.55	Say \$125/SF
2016	\$117.76		
2015	\$132.82		
2014	\$108.15		
2013	\$100.92		
Sum =		\$582.75	

Concrete Overlay (use total system values)

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$14.51	\$18.86	Say \$20/SF
2016	\$23.89		
2015	\$18.19		
Sum =		\$56.59	

New Deck (use total system values)

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$85.13	\$78.83	Say \$80/SF
2016	\$78.37		
2015	\$73.00		
Sum =		\$236.50	

Painting (use total system values)

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$16.29	\$19.37	Say \$18/SF
2016	\$16.93		
2015	\$24.90		
Sum =		\$58.12	

APPENDIX B

Alternative 1 – Conversion to Semi-expansion Abutments

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/11/2018

OPTION: Alternate #1 - Convert (2) existing abutments to semi-expansion

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Salvage (Residual) Value
as a % of Replacement Cost: 50.0% (assumes NBI = 9 new, 3 at end of service life, and 6 at end of analysis period)

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	New deck on 55 year old bridge	9100	SF	\$80	\$728,000	\$728,000
0	Convert 2 abutments to semi-expansion	2	EACH	\$47,000	\$94,000	\$94,000
0	Steel girder repainting	10700	SF	\$18	\$192,600	\$192,600
0	Misc. repairs (15% of major rehab items)	1	LS	\$152,190	\$152,190	\$152,190
0	Roadway approach, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$66,000	\$66,000	\$66,000
0					\$0	\$0
	Subtotal - Initial Costs					\$1,232,790
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay on 75 year old bridge	9100	SF	\$20	\$182,000	\$91,467
20	Misc. repairs (20% of major rehab items)	1	LS	\$36,400	\$36,400	\$18,293
20					\$0	\$0
20					\$0	\$0
35	Demo existing 90 year old bridge	9100	SF	\$20	\$182,000	\$54,596
35	New PPC girder bridge	9750	SF	\$125	\$1,218,750	\$365,597
35	New structure approach slabs	1	LS	\$57,000	\$57,000	\$17,099
35	Raising Grantosa, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$1,400,000	\$1,400,000	\$419,968
35	ROW acquisition	1	LS	\$180,000	\$180,000	\$53,996
55	Concrete overlay on 20 year old bridge	9750	SF	\$20	\$195,000	\$29,398
55	Misc. repairs (10% of major rehab items)	1	LS	\$19,500	\$19,500	\$2,940
55					\$0	\$0
55					\$0	\$0
70	New deck on 35 year old bridge	9750	SF	\$80	\$780,000	\$70,189
70	Misc. repairs (15% of major rehab items)	1	LS	\$117,000	\$117,000	\$10,528
70					\$0	\$0
70					\$0	\$0
75	Salvage (Residual) value - 40 year old bridge	1	LS	(\$609,375)	-\$609,375	-\$46,170
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$2,320,690
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$87,883</i>

APPENDIX C

Alternative 2 – Abutment Replacement

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/11/2018

OPTION: [Alternate #2 - Replace \(2\) existing abutments](#)

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Salvage (Residual) Value
as a % of Replacement Cost: 50.0% (assumes NBI = 9 new, 3 at end of service life, and
6 at end of analysis period)

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	New deck on 55 year old bridge	9100	SF	\$80	\$728,000	\$728,000
0	Replace 2 abutment	2	EACH	\$176,000	\$352,000	\$352,000
0	Steel girder repainting	10700	SF	\$18	\$192,600	\$192,600
0	Misc. repairs (15% of major rehab items)	1	LS	\$190,890	\$190,890	\$190,890
0	Roadway approach, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$66,000	\$66,000	\$66,000
0					\$0	\$0
	Subtotal - Initial Costs					\$1,529,490
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay on 75 year old bridge	9100	SF	\$20	\$182,000	\$91,467
20	Misc. repairs (20% of major rehab items)	1	LS	\$36,400	\$36,400	\$18,293
20					\$0	\$0
20					\$0	\$0
35	Demo existing 90 year old bridge	9100	SF	\$20	\$182,000	\$54,596
35	New PPC girder bridge	9750	SF	\$125	\$1,218,750	\$365,597
35	New structure approach slab	2	EACH	\$57,000	\$114,000	\$34,197
35	Raising Grantosa, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$1,400,000	\$1,400,000	\$419,968
35	ROW acquisition	1	LS	\$180,000	\$180,000	\$53,996
55	Concrete overlay on 20 year old bridge	9750	SF	\$20	\$195,000	\$29,398
55	Misc. repairs (10% of major rehab items)	1	LS	\$19,500	\$19,500	\$2,940
55					\$0	\$0
55					\$0	\$0
70	New deck on 35 year old bridge	9750	SF	\$80	\$780,000	\$70,189
70	Misc. repairs (15% of major rehab items)	1	LS	\$117,000	\$117,000	\$10,528
70					\$0	\$0
70					\$0	\$0
75	Salvage (Residual) value - 40 year old bridge	1	LS	(\$609,375)	-\$609,375	-\$46,170
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$2,634,489
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$99,766</i>

APPENDIX D

Alternative 3 – Steel Girder Bridge Replacement

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/25/2018

OPTION: [Alternate #3 - New steel girder bridge \(200' x 45.5'\)](#)

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	Demo existing bridge	9100	SF	\$20	\$182,000	\$182,000
0	New steel girder bridge	9100	SF	\$175	\$1,592,500	\$1,592,500
0	New structure approach slabs	2	EACH	\$57,000	\$114,000	\$114,000
0	Roadway approach, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$66,000	\$66,000	\$66,000
0					\$0	\$0
	Subtotal - Initial Costs					\$1,954,500
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay	9100	SF	\$20	\$182,000	\$91,467
20	Misc. repairs (10% of major rehab items)	1	LS	\$18,200	\$18,200	\$9,147
20					\$0	\$0
20					\$0	\$0
35	New deck	9100	SF	\$80	\$728,000	\$218,383
35	Steel girder repainting	10700	SF	\$18	\$192,600	\$57,776
35	Misc. repairs (15% of major rehab items)	1	LS	\$138,090	\$138,090	\$41,424
35					\$0	\$0
35					\$0	\$0
55	Concrete overlay	9100	SF	\$20	\$182,000	\$27,438
55	Misc. repairs (20% of major rehab items)	1	LS	\$36,400	\$36,400	\$5,488
55					\$0	\$0
55					\$0	\$0
75					\$0	\$0
75					\$0	\$0
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$2,405,622
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$91,099</i>

APPENDIX E

Alternative 4 – Prestressed Concrete Girder Bridge Replacement

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/25/2018

OPTION: [Alternate #4 - New PPC girder bridge \(214' x 45.5'\)](#)

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	Demo existing bridge	9100	SF	\$20	\$182,000	\$182,000
0	New PPC girder bridge	9750	SF	\$125	\$1,218,750	\$1,218,750
0	New structure approach slabs	2	EACH	\$57,000	\$114,000	\$114,000
0	Raising Grantosa, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$1,400,000	\$1,400,000	\$1,400,000
0	ROW acquisition	1	LS	\$180,000	\$180,000	\$180,000
	Subtotal - Initial Costs					\$3,094,750
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay	9750	SF	\$20	\$195,000	\$98,000
20	Misc. repairs (10% of major rehab items)	1	LS	\$19,500	\$19,500	\$9,800
20					\$0	\$0
20					\$0	\$0
35	New deck	9750	SF	\$80	\$780,000	\$233,982
35	Misc. repairs (15% of major rehab items)	1	LS	\$117,000	\$117,000	\$35,097
35					\$0	\$0
35					\$0	\$0
55	Concrete overlay	9750	SF	\$20	\$195,000	\$29,398
55	Misc. repairs (20% of major rehab items)	1	LS	\$39,000	\$39,000	\$5,880
55					\$0	\$0
55					\$0	\$0
75					\$0	\$0
75						\$0
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$3,506,907
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$132,804</i>

From: [Landini, Anthony P - DOT](#)
To: [Stollenwerk, Roy T - DOT](#)
Cc: [DOT 13601100 STH 145-Grantosa-Leon](#); [Wood, Kevin](#); [Schowalter, Steven](#); [Hanna, Christine - DOT](#); [Ksontini, Najoua - DOT](#); [Pettit, Mary Beth](#)
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281
Date: Tuesday, October 30, 2018 10:25:50 AM
Attachments: [image001.png](#)
[image002.png](#)
[image003.png](#)

Roy

The memorandum has been revised as per discussions with Consultant.

Tony

From: Pettit, Mary Beth [mailto:marybeth.pettit@graef-usa.com]
Sent: Friday, October 26, 2018 2:05 PM
To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>; Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>
Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Schowalter, Steve <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>; Ksontini, Najoua - DOT <najoua.ksontini@dot.wi.gov>
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281

All,

Kevin and Tony have corresponded this week and the memorandum has been finalized and attached for your records.

Thank you to everyone for your help! We will incorporate the recommendation of the deck replacement with the conversion to semi-expansion abutments.

Thank you,
Mary Beth

From: Stollenwerk, Roy T - DOT [mailto:Roy.Stollenwerk@dot.wi.gov]
Sent: Tuesday, October 23, 2018 3:22 PM
To: Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>
Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Pettit, Mary Beth <marybeth.pettit@graef-usa.com>; Schowalter, Steven <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>; Ksontini, Najoua - DOT <najoua.ksontini@dot.wi.gov>
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281

Tony,

Thanks for your review and concurrence.

Kevin and Mary Beth – Please respond to Tony’s comment regarding the LCC analysis for Alternatives 3 & 4 and resubmit is necessary. Thanks.

Roy Stollenwerk

30% Design Project Manager
Wisconsin Department of Transportation
PH: (262) 548-6474

From: Landini, Anthony P - DOT
Sent: Tuesday, October 23, 2018 12:43 PM
To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>
Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Pettit, Mary Beth <marybeth.pettit@graef-usa.com>; Schowalter, Steve <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>; Ksontini, Najoua - DOT <najoua.ksontini@dot.wi.gov>
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281

Roy

BOS concurs with recommended Alternative 1 – Re-deck and conversion to a semi-expansion abutments.

This is a nice report, but I believe there is a problem with the LCC analysis for Alternatives 3 & 4 that does not affect the recommendation. By adding the cost of a new bridge at year 75, which is the analysis period, the remaining service life of that new structure should be subtracted. If the Consultant agrees, I suggest the report be updated and resubmitted so we have the proper documentation.

Tony

From: Stollenwerk, Roy T - DOT
Sent: Tuesday, October 16, 2018 3:21 PM
To: Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>
Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Pettit, Mary Beth <marybeth.pettit@graef-usa.com>; Schowalter, Steve <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>

Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Tony,

GRAEF has submitted the attached Bridge Alternative Life Cycle Cost Analysis for the Grantosa Drive bridges of STH 145, Bridges B-40-280 and B-40-281. Their conclusion is that Alternative 1 – Redeck and conversion to a semi-expansion abutment has the lowest first cost and lowest life cycle cost. Please review the analysis and comment on their recommendation of Alternative 1 as the preferred option.

Thanks, and let us know if you have any questions.

Roy Stollenwerk

30% Design Project Manager

Wisconsin Department of Transportation

PH: (262) 548-6474

From: Landini, Anthony P - DOT

Sent: Thursday, September 06, 2018 3:25 PM

To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>

Cc: Bonk, Aaron M - DOT <Aaron.Bonk@dot.wi.gov>; Shadewald, Laura - DOT <Laura.Shadewald@dot.wi.gov>

Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Roy

The scope for ii should be to convert both abutments to semi-expansion.

Aaron and Laura have been more involved in man hour estimates so one of them may be willing to provide comments on that portion.

Tony

From: Stollenwerk, Roy T - DOT

Sent: Thursday, September 06, 2018 1:55 PM

To: Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>

Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>

Subject: FW: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Tony,

GRAEF has submitted the attached draft amendment for the alternative analysis for the Grantosa Drive abutments that are tipping. We would like to get the amendment going as soon as possible so

that we can keep the project design on schedule. Could you please review the scope of work to make sure it includes the information that BOS is looking for. Your opinion on the cost of the amendment would also be appreciated.

Thanks for your help.

Roy Stollenwerk

30% Design Project Manager
Wisconsin Department of Transportation
PH: (262) 548-6474

From: Pettit, Mary Beth [<mailto:marybeth.pettit@graef-usa.com>]
Sent: Friday, August 31, 2018 2:59 PM
To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>
Cc: Schowalter, Steve <steven.schowalter@graef-usa.com>; Wood, Kevin <kevin.wood@graef-usa.com>
Subject: [WARNING: ATTACHMENT(S) MAY CONTAIN MALWARE]I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Roy,

Per our discussion earlier this week, please find attached a draft of the amendment for the study and memo preparation for the alternatives at Grantosa. Most importantly, we need to be sure the scope the way it is written on page 2 covers what you believe should be in the report. We can discuss next steps with this amendment once you have had a chance to review.

We are planning to complete this work in approximately 3 weeks.

Please feel free to call with questions\concerns.

Thank you!

Mary Beth Pettit, P.E.

Principal



One Honey Creek Corporate Center
125 South 84th Street, Suite 401
Milwaukee, WI 53214-1407

414 / 259 1500 office
414 / 266 9175 direct
414 / 467 8912 mobile
414 / 259 0037 fax

marybeth.pettit@graef-usa.com

www.graef-usa.com



GRAEF is the trade name of Graef-USA Inc.

This email and any attachments may contain confidential information to be used only by the intended recipient(s). If you are not the intended recipient of this email, you are expected to disregard the content, delete the email message, and notify the original sender.



Please consider the environment before printing this page.