

ATTACHMENT 1
INSPECTION REPORT



STATE OF WISCONSIN
DEPARTMENT OF TRANSPORTATION

Inspection Report for B-40-281

W GRANTOSA DR EB over STH 145-W FOND DU LAC AV
Jul 21, 2018



B-40-281
W GRANTOSA DR EB over STH 145-W
FOND DU LAC AV
South Elevation
7/21/2018

Type	Prior	Frequency (mos)	Performed
Routine	07-21-16	24	X
Deck Evaluation			X
SIA Review	07-21-16	48	

Start Coordinates
Latitude

Longitude

Owner

End Coordinates (optional)

Latitude

Longitude

Maintainer

Time Log

Team members

Hours	Minutes	
1	40	

Name	Number	Signature	Signature Date
Inspector		<i>William J Zippel</i>	
Zippel, William J	9605	E-signed by William Zippel(wzippel)	10-02-18

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 2

Identification & Location

Feature On: W GRANTOSA DR EB	Section Town Range: S34 T08N R21E	Structure Number: B-40-281
Feature Under: STH 145-W FOND DU LAC AV	County: MILWAUKEE	
Location 0.2M E JCT STH 181	Municipality: MILWAUKEE	Structure Name:

Geometry

measurements in feet, except where noted

Approach Roadway Width: 36	Bridge Roadway Width: 36.0	Total Length: 198.2
Approach Pavement Width: 36	Deck Width: 45.5	Deck Area (sq ft): 9018

Traffic

	Lanes	ADT	ADT year	Traffic Pattern
On	3	4000	2016	ONE WAY TRAFFIC
Under	8	27900	2015	TWO WAY TRAFFIC

Capacity

Load Rating

Inventory rating: HS14	Overburden depth (in): 2.0	Last rating date: 01-14-13	Controlling: INTERIOR DECK GIRDER Moment
Operating rating: HS24	Deck surface material: MICROSILICA MODIFIED CONC	Re-rate for capacity (Y/N):	Control location: 4.9 SPAN 2, 34.1
Posting:	Re-rate notes:		

Hydraulic

Classification

Scour Critical Code(113): (N) NO WATERWAY	Q100 (ft3/sec): 0	
High water elevation (ft): 0.0	Velocity (ft/sec): 0.0	Sufficiency #: 52.7

Span(s)

Span #	Material	Configuration	Depth (in)	Length (ft)	Main
1	CONT STEEL	DECK GIRDER		34.0	
2	CONT STEEL	DECK GIRDER		70.0	Y
3	CONT STEEL	DECK GIRDER		60.0	
4	CONT STEEL	DECK GIRDER		30.0	

Expansion joint(s)

Temperature:

Joint #	Location	Type	Last inspection date	File:	New:72
1	EAST ABUTMENT	SSA-400L	07-15-14	Last measure (in)	New measure (in)
2	WEST ABUTMENT	SSA-400L	07-15-14	0.9	0.6
				1.0	0.6

Clearance

Item	File Measurement (ft)	File Date	New Measurement (ft)
Highway Min Vertical Under Cardinal	14.96		
Highway Min Vertical Under Non-Cardinal	15.22		
Horizontal Under Cardinal	52.0		
Horizontal Under Non-Cardinal	61.3		
Highway Min Vertical On Cardinal			
Horizontal On Cardinal			

Special Components

Component	Year	Work Performed	Note
DECK - IOWA MIX	1992	OVERLAY - CONCRETE	MICRO-SILICA MODIFIED CONCRETE OVERLAY

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 3

Structure No.: **B-40-281**

Construction History

Year	Work Performed	FOS id
0	NOT BUILT	0077-02-23
1993	ADD PED FENCING	1360-03-73
1992	OVERLAY - CONCRETE	1360-00-74
1965	NEW STRUCTURE	

Maintenance Items

Item	Priority	Recommended by	Status	Status change
IMP-Structure Replacement	MEDIUM	Sadowski, Jason (9593)	IDENTIFIED	07/21/14
Recommend 2020.				
IMP-Deck Replacement	MEDIUM	Tormey, Jeffrey T (9510)	IDENTIFIED	07/28/16
Schedule Deck Replacement				
Bearings - Reposition	MEDIUM	Zippel, William J (9605)	IDENTIFIED	10/01/18
Reposition east abutment expansion bearings.				
Deck - Repair Sidewalk	MEDIUM	Zippel, William J (9605)	IDENTIFIED	10/01/18
Repair sidewalk on bridge and on approaches.				
Bearings - Reposition	LOW	Tormey, Jeffrey T (9510)	IDENTIFIED	07/28/16
Modify Expansion Bearing hold downs to allow additional expansion				

Elements

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	12		Reinforced Concrete Deck	SF	9,018	8,528	446	44	0
			Spans #'d West to East. Bays #'d from N to S.						
		1080	Delamination - Spall - Patched Area Sp 1: 1 Sound full depth patch - 16 sf @ CS2, area of Delam in Bay 3 - 10sf @ CS3; Sp 2: Wet area in bay 3 E of P1 - CS1; Sp 3: Deck replaced in Bay 5 due to girder replacement - CS1; Sp 4: Area of delam - 30sf @ CS3, and spalled area about 4 SF in Bay 4.	SF		0	16	44	0
		1130	Cracking (RC) Scattered transverse cracks with efflorescence throughout deck. Sp 1: 60 SF CS2; Sp 2: 30 SF CS2; Sp 3: 30 SF CS2 and areas of narrow map cracking w/Lt Eff 100 sf CS2; Sp 4: 60 SF CS2 and areas of narrow map cracking w/Lt Eff 150 sf CS2;	SF		0	430	0	0
		8514	Concrete Overlay	SF	7,135	3,167	739	3,229	0
		8911	Abrasion, Wear, or Rutting (Wear. Surf.) Span 1 - Plow abrasion at west joint, south half of roadway (24SF CS2).	SF		0	24	0	0
		3210	Debonding/Spall/Patched Area/Pothole May 2015 IR: "Numerous large delaminations throughout the deck." 30-35% Delam. Two 2 ft spalls at West Abut (Lane 1 and Lane 2). 10SF Delam with concrete close to popping out Span 3.	SF		0	0	2,514	0
		3220	Crack (Wearing Surface) Narrow to medium longit and map cracking throughout deck. Some overlap with delams above. Approx 10% additional CS2 and 10% additional CS3.	SF		0	715	715	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 4

Structure No.: **B-40-281**

X	107		Steel Open Girder	LF	1,170	35	1,075	60	0
			Spans #d West to East. Girders #d from N to S. 35 ft section of G6 (South) Span 3 replaced in 2001						
		1000	Corrosion Lt to med edge rust at both flanges; Lt to med freckled rust at underside btm flg and at webs; Rust heavier over Rdwys with approx 60LF CS3 corrosion. New Girder Section paint is Scraped over Center Lane	LF		0	1,075	60	0
		8516	Painted Steel	SF	10,659	0	6,395	3,198	1,066
X	205		Reinforced Concrete Column	EA	9	5	1	3	0
			Piers #d West to East. Columns #d from N to S.						
		1080	Delamination - Spall - Patched Area P1: Lg Delam Col 2 - 1 @ CS3; P2: Lg Delam Col 1, Failed patch w/spall Col 2, Sound patch at Col 3, - 1@CS2 and 2 @ CS3; P3: OK	EA		0	1	3	0
		1130	Cracking (RC) P1: OK P2: HL map crks at delams and patches (Overlaps delam/spalls). P3: OK	EA		0	0	0	0
X	215		Reinforced Concrete Abutment	LF	91	27	63	1	0
		1080	Delamination - Spall - Patched Area W. Abut: 3 sound conc patches in body - 6' @ CS2, sound patches in bkwl 20' @ CS2, water in Bay 5 and behind G1 from leaking expansion joint; E. Abut: 4 sound conc patches in body - 4' @ CS2, 20 sound patches in bkwl - 20' @ CS2; Small spall at north end - 1 LF CS3.	LF		0	50	1	0
		1130	Cracking (RC) W. Abut: 3 Narrow vert crks in body - 3' @ CS2, 2 narrow vert crks in bkwl - 2' @ CS2; E. Abut: 4 Narrow vert & horiz crks in body - 4' @ CS2, 4 narrow vert crks in bkwl - 4' @ CS2;	LF		0	13	0	0
X	234		Reinforced Concrete Cap	LF	131	131	0	0	0
			Piers #d West to East.						
X	300		Strip Seal Expansion Joint	LF	72	0	71	1	0
			Measurements: West Abut: 3/4" @ 80 Degrees East Abut: 3/4" @ 80 Degrees						
X	300	2310	Leakage, Seal Adhesion, Damage, Cracking West Abut: Spall at CL. 1 LF CS3.	LF		0	0	1	0
		2350	Debris Impaction W. Abut: Filled w/debris - 36' CS2; E. Abut: Filled w/debris - 36' CS2	LF		0	71	0	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 5

Structure No.: **B-40-281**

X	311		Moveable Bearing	EA	24	0	15	9	0
			Located at both Abutments and Piers 1 and 3. Hold down assemblies at Girders 2-5 at both abutments.						
		1000	Corrosion	EA		0	15	3	0
			W. Abut: Hvy Rust @ G1, Mod Rust on G2-6 masonry plates - 5 @ CS2, 1 @ CS3. P1: Mod Rust - 6 @ CS2; P3: Lt Rust - 6 @ CS2; E. Abut: Mod/Hvy Rust - 4 @ CS2, 2 @ CS3;						
		1020	Connection	EA		0	0	0	0
			East Abut: Broken keeper G1. Pier 3: Broken keeper G6. West Abut: Broken keeper G1. Quantities overlap corrosion.						
		2220	Alignment	EA		0	0	6	0
			E. Abut: Brgs at or past expansion limits.						
		2240	Loss of Bearing Area	EA		0	0	0	0
			E Abut: Hold down pins bearing at the back of slot. Bronze Plate loss of bearing 1/2" to 3/4".						
X	313		Fixed Bearing	EA	6	0	6	0	0
			Located at Pier 2						
		1000	Corrosion	EA		0	6	0	0
			Lt Rust - 6 @ CS2						
X	331		Reinforced Concrete Bridge Rail	LF	219	4	175	40	0
		1080	Delamination - Spall - Patched Area	LF		0	150	40	0
			N. Rail: Rust stains at shallow rebars - 50' @ CS2; delams at curb face - 50' @ CS2, Spalls w/exp rebar at curb face - 30' @ CS3 S. Rail: Rust stains, shallow delams at Front face - 50' CS2						
		1130	Cracking (RC)	LF		194	25	0	0
			N. rail: HL map and horiz. crks; S. rail: HL map and horiz. crks. Narrow vert. cracks at posts - 25' CS2						
X	8400		Integral Wingwall	EA	4	3	1	0	0
		8903	Wall Deterioration	EA		3	1	0	0
			SW: HL map crk - CS1 NW: HL map crk - CS1 SE: HL map crk - CS1 SE: Narrow map crk - CS2						

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 6

Structure No.: **B-40-281**

Assessments

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	9001		Drainage - Ends of Structure All corners - Slopes - CS1	EA	4	4	0	0	0
X	9009		Sidewalk HL longit & trans crks, exist. patches, delams along curb face.	EA	1	0	1	0	0
X	9011		Utilities 6-4" dia Transite WE ducts in Bay 1, disconnected at both abuts, damaged just west of P2 - 1 @ CS3; 4" dia gas Line in Bay 4 - 1 @ CS1; 4- 3" dia Steel Police & Traffic Control Ducts in Bay 2, moderate rust in spans 2 & 3 - 1 @ CS2 Hangers in bay 2 corroded over rdwy, monitor. Street lighting: Corroded conduits and some broken light shrouds.	EA	4	1	1	2	0
X	9030		Signs - Object Markers @ NW corner at west end of north bridge rail, and NE corner on light pole in median	EA	2	2	0	0	0
X	9035		Signs - Other N-Hwy 145, Grantosa/Villard at SW corner.	EA	2	2	0	0	0
X	9042		Slope Protection- Concrete W. Abut: Cracks, SW corner heaved by dead tree - CS2; E. Abut: Cracks SE side settled - CS2; Lt vegetation at both	EA	2	0	2	0	0
X	9167		Steel Diaphragm Lt/Mod Rust, heavier over rdwy	EA	60	0	60	0	0
X	9323		Approach Roadway - Asphalt E. Appr: Distress @ Hdr Ln 1 & 3, slightly low, Lg spl in Ln 3 - 1 @ CS3; W. Appr: Open transverse and longitudinal cracks. Spalls at PB and shoulder, sidewalk is cracked. 1 @ CS3	EA	2	0	0	2	0
X	9335		Decorative Rail Lt rust on anchor bolts	EA	1	0	1	0	0
X	9336		Luminaire Bases	EA	2	2	0	0	0
X	9337		Protective Screening Peeling paint on galvanized posts and rails	EA	1	0	1	0	0

NBI Ratings

	File	New
Deck	4	4
Superstructure	6	5
Substructure	6	6
Culvert	N	N
Channel	N	N
Waterway	N	N

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 7

Structure No.: **B-40-281**

Structure Specific Notes

Deck replaced in 35-Ft section over S. beam in E. span.

Inspection Specific Notes

Inspector Site-Specific Safety Considerations

Structure Inspection Procedures

Access from shoulders.

Special Requirements

Chk	Hours	Cost	Comments
-----	-------	------	----------

Routine
Document Comment/Description
Top of deck looking West



Routine
Document Comment/Description

RC Deck - Typ transv crack with efflorescence. Photo shows Span 2 Bay 5.



7/21/2018

Routine
Document Comment/Description

RC Deck - Large area of delam with spalling. Span 4, Bay 4.



Routine

Document Comment/Description

Conc OL - Two 2 ft spalls at West Abut (Lane 1 and Lane 2).



Routine

Document Comment/Description

Conc OL - 10SF Delam with concrete close to popping out Span 3.



Routine**Document Comment/Description**

Steel Open Girder - Rust heavier over Rdwys with approx 60LF CS3 corrosion. Photo shows Span 2, girder 2.



Routine
Document Comment/Description

RC Col - Large delam Col 2, Pier 1.



Routine

Document Comment/Description

RC Abut - E. Abut: Small spall at north end - 1 LF CS3.



Routine

Document Comment/Description

Strip Seal Exp Jt - West Abut: Spall at CL.



Routine**Document Comment/Description**

Moveable bearing: E Abut, G1. Corrosion, broken inside keeper, and loss of bearing 3/4" above bronze plate.

7/21/2018



Routine**Document Comment/Description**

RC Bridge Rail - N. Rail: Rust stains at shallow rebars, delams at curb face, Spalls w/exp rebar at curb face. Photo near middle of bridge.



Routine

Document Comment/Description

Asphalt Appr: Cracks and potholes forming at west appr.



Non-Image Documents

Type	Document	Document Comment/Description	Attached
Deck Evaluation	b40-281_18_Kd1.pdf	May 2015 Deck Eval.	X

DECK INSPECTION SHEET

STRUCTURE NO.: B-40-281

FEATURE ON <u>W. Grantosa Dr. (EB)</u>	MAINTAINER <u>State</u>	COUNTY <u>Milwaukee</u>	ROADWAY WIDTH (FEET) <u>36.0</u>	TOTAL LENGTH (FEET) <u>198.2</u>
FEATURE UNDER <u>STH 145 - W. Ford du Lac Ave. 0.2 ME Jct STH 181</u>	LOCATION <u>0.2 ME Jct STH 181</u>	SKEW ANGLE <u>9 Left</u>	DECK AREA (sq.ft.) <u>9,018</u>	RDWY AREA (sq.ft.) <u>7,135</u>
STRUCTURE TYPE <u>Cont Steel Deck Girder</u>	SPANS <u>4</u>	LENGTHS <u>34.0, 70.0, 60.0, 30.0</u>	NO. OF LANES <u>3</u>	NO. OF SHOULDERS <u>0</u>

CONSTRUCTION HISTORY	YEAR <u>1965</u> <u>1992</u>	WORK PERFORMED <u>New Structure</u> <u>Concrete Overlay</u>
----------------------	------------------------------------	---

INFRARED SURVEY RESULTS (LEVEL 1)

ESTIMATED % TOTAL DISTRESS* 30-35%

If <2%

DATE OF SURVEY	TOTAL ROADWAY AREA (sq. ft.)	AREA IN SHADE/DEBRIS (sq. ft.)	AREA INSPECTED (sq. ft.)
<u>5/1/15</u>	<u>7,135</u>	<u>None</u>	<u>7,135</u>

ESTIMATED % TOTAL DISTRESS IS THE DEFECT AREAS ONLY AND IS NOT THE ESTIMATED REHABILITATION AREA

TYPE OF DEFECT	PERCENT OF AREA INSPECTED					
	0-5	5-10	10-15	15-20	20-25	25+
Delamination						<u>30-35%</u>
Debonding	<u>None</u>					
Concrete Patching *	<u>None</u>					
Asphalt Patching	<u>None</u>					
Spalling	<u>None</u>					
PREVIOUS SURVEYS						
YEAR LEVEL (Total Defects)						
<u>2010 1</u>					<u>X</u>	
<u>2005 1</u>			<u>X</u>			
<u>2001 1</u>		<u>X</u>				

COMMENTS: * Concrete patch (~120 ft.²) on east side of deck to traffic impact (2001). Not included in defect quantities.
- Numerous large delaminations throughout the deck.

PATCHES: 0 (see above)# OF CORES: 0


RESULTS:

PROJECT ID.: 1000-70-15WORK ORDER: #2

ATTACHMENT 2
DEFICIENT AREAS

BENCH MARK			
NO	STATION	DESCRIPTION	ELEV
22	22+40.00 (VILLARD)	S.W. CORNER CONC PORCH # 7224 W VILLARD AVE.	121.53

COUNTY & HIGHWAY	ROUTE & SECTION	CLASS & AGREEMENT	SHEET NO	TOTAL SHEETS
40.1	27.1	22.6	F027-1(22)	185 383



W.B. LANE WEST GRANTOSA DRIVE GRADE LINE (B-40 280)

E.B. LANE WEST GRANTOSA DRIVE GRADE LINE (B-40 281)

FOND DU LAC AVE. GRADE LINE (B-0 RT & LT OF Q)

GENERAL NOTES

DRAWINGS SHALL NOT BE SCALED.
ALL CONCRETE MASONRY SHALL BE GRADE A-A.
F_c 11,400 P.S.I.
NOT PAURED ELASTIC JOINT SEALER SHALL CONFORM TO ASTM DESIGNATION, D1190.
BEVEL EXPOSED EDGES OF CONCRETE 1" UNLESS OTHERWISE SHOWN OR NOTED
IMBED ALL BAR STEEL 2" UNLESS OTHERWISE SHOWN.
ALL FIELD CONNECTIONS SHALL BE 3/4" RIVETS OR HIGH STRENGTH BOLTS UNLESS OTHERWISE SHOWN.
THE SLOPE IN FRONT OF THE ABUTMENTS SHALL BE COVERED WITH "SLOPE PAVING AS SHOWN IN 'PLAN' ON THIS SHEET AND IN SECTION A-A" ON SHEET 19-13.
ALL SPACES EXCAVATED AND NOT OCCUPIED BY THE STRUCTURE SHALL BE BACKFILLED WITH GRANULAR BACKFILL TO THE ELEVATION AND SECTION EXISTING PRIOR TO EXCAVATION.

SUPERSTRUCTURE CONDITION NOT FULLY DOCUMENTED BECAUSE REDECKING IS ANTICIPATED, SEE PHOTOS IN -OTH.pdf

TOTAL ESTIMATED QUANTITIES

BID ITEMS	UNIT	SUPER	WAR	PIER 1	PIER 2	PIER 3	E ABUT	TOTAL
EXCAVATION FOR STRUCTURES	CY	195	75	70	60	140	190	
GRANULAR BACKFILL	CY	40	50	50	45	40	225	
CONCRETE MASONRY	CY	241.4	71.0	46.1	44.6	98.2	69.5	510.8
BAR STEEL REINFORCEMENT	LB	77,800	2,230	5,920	6,380	4,800	2,220	99,350
STRUCTURAL CARBON STEEL	LB	83,660						83,660
STRUCTURAL LOW ALLOY STEEL	LB	94,650						94,650
TUBULAR RAILING - TYPE B	LF	428.9						428.9
SLOPE PAVING - CONCRETE	SF	260					240	500
LUBRICATED BRONZE PLATES	LB	276						276
BEARING PADS	SF	37						37
ELECTRICAL WORK (B-40-281)	LS	1						1
NON B.D. ITEMS								
ZINC OR ALUMINUM PLATES	SF	45						45

LIST OF DRAWINGS

1	GENERAL PLAN	X27878
2	SUPERSTRUCTURE	X27879
3	SUPERSTRUCTURE	X27880
4	LONG SECTION & BEARINGS	X27881
5	LONG SECTION & BEARINGS	X27882
6	EXPANSION JOINT	X27883
7	TUBULAR STEEL RAILING - TYPE B	X27884
8	TUBULAR ALUMINUM RAILING - TYPE B	X27885
9	WEST ABUTMENT	X27886
10	PIER 1	X27887
11	PIER 2	X27888
12	PIER 3	X27889
13	EAST ABUTMENT	X27890
14	UTILITIES & LIGHTING DETAILS	X27891
FOR SUBSURFACE EXPLORATION SEE B-40-280		

STATE HIGHWAY COMMISSION OF WISCONSIN

GENERAL PLAN

CITY OF MILWAUKEE

SECTION 34

DESIGN SPEC AASHO G1

DATE 10-24-63


RECOMMENDED 1. B. Schultz

APPROVED E. L. Potvin


STRUCTURE B-40-281

SHEET 1 OF 14

X27878



X 27879




DETAIL E








K27880

F027-1(22) 188 383



LONGITUDINAL SECTION

FOR LOCATION & DETAILS OF STRINGER
SPICE SEE X21880
SECTION IS PARALLEL TO STRINGER.






BEARING TYPE 'A'
2 REQ'D.

BEARING TYPE 'B'
1 REQ'D.

BEARING NOTES

- ALL STRUCTURAL STEEL BEARING PLATES SHALL BE FLAT ROLLED STEEL PLATES WITH ALL SURFACES SMOOTH & FREE FROM WARP & ALL EDGES SMOOTH, STRAIGHT, & VERTICAL.
- ALL PLATE CUTS SHALL BE MACHINE FLAME CUTS OR MACHINE CUTS.
- PINTLES SHALL BE MACHINED TO A DRIVING FIT. CHAMFERED TOP OF PINTLE 1/8".
- LUBRICATE TOP SURFACES ONLY OF BRONZE PLATES.
- ANCHOR BOLTS TO BE 1/2" x 1/4" x 9" LONG WITH * PROJECTION ABOVE TOP OF CONCRETE. PROVIDE ONE 1/4" STANDARD DRAUGHT WASHER & ONE HEX NUT PER BOLT. THREAD BACK 3".
- ALL MATERIAL EXCLUDING ANCHOR BOLTS, NUTS, AND WASHERS SHALL BE MADE OF A242 STEEL WITH A CORROSION RESISTANCE OF 4 OR MORE TIMES THAT OF A36 STEEL.
- THE TOP 4 1/2" OF ANCHOR BOLTS, WASHERS & NUTS SHALL BE GALVANIZED.
- ALL MATERIAL IN BEARINGS, EXCLUDING BRONZE PLATES AND BEARING PADS SHALL BE PAID FOR AT THE UNIT PRICE BID FOR STRUCTURAL LOW ALLOY STEEL.
- ALL SURFACES MARKED F SHALL BE MACHINE FINISHED.

* BRG. A - 2
BRG. B - 4
BRG. C - 4




BEARING TYPE 'C'
2 REQ'D.

STATE HIGHWAY COMMISSION OF WISCONSIN			
LONG. SECTION & BEARINGS			
STRINGER 6			
DATE	DESIGNED BY	CHECKED BY	APPROVED BY
10/24/63	AASHO	VGW	10/25/63
STRUCTURE B 40 281		SHEET 4 OF 14	


X27881

PROJECT: F027-1(22) 189 383




LONGITUDINAL SECTION
GENERAL NOTES


ALL STRUCTURAL STEEL BEARING PLATES SHALL BE FLAT ROLLED STEEL PLATES WITH ALL SURFACES SMOOTH & FREE FROM LARP & ALL EDGES SMOOTH, STRAIGHT & VERT. CAL.
ALL PLATE CUTS SHALL BE MACHINE OR MACHINE PLATE CUTS.
ALL SURFACES MARKED "X" SHALL BE MACHINE FINISHED. F.A.S.A. 250.
ANCHOR BOLTS SHALL BE T-READED 3" PROVIDE ONE STD WROUGHT STEEL WASHER & ONE HEX. NUT PER FLT.
LUBRICATE TOP SURFACE OF BRONZE PLATE ONLY.
MACHINE FINISH BOTTOM OF FLANGE PLATES A.S.A. 125 IN DIRECTION OF MOVEMENT (EXPANSION BRG ONLY).
ALL MATERIAL EXCEPT ANCHOR BOLTS, NUTS, AND WASHERS SHALL BE MADE OF A242 STEEL WITH A CORROSIVE RESISTANCE OF 4 OR MORE TIMES THAT OF A242 STEEL.
THE TOP 1/4" OF ANCHOR BOLTS, WASHERS & NUTS SHALL BE GALVANIZED.
ALL MATERIAL IN BEARINGS EXCLUDING BRONZE PLATES AND BEARING PADS SHALL BE PAID FOR AT THE UNIT PRICE BID FOR STRUCTURAL LOW ALLOY STEEL.




PRE-SET ANCHOR BOLT PLAN
(AT HOLD DOWN DEVICE ONLY)



ANCHOR BOLT DETAIL
(AT HOLD DOWN DEVICE ONLY)




ABUT'S



BEARING "A"
(10 REQ'D, 2 TO HOLD DOWN)


BEARING "B"
(5 REQ'D)

3" HIGH TENSILE STRENGTH BOLTS SHALL BE PLACED BEFORE SLAB IS POURED AFTER MAKING CERTAIN THAT ALL PARTS ARE PROPERLY SEATED




ELEVATION

SECTION A1




STRINGER DETAIL



PIN DETAIL

HOLD DOWN DEVICE DETAILS


(AT ABUT'S ONLY)
STRINGERS 2,3,4,15



TYPICAL PINTLE DETAIL - ALL BRG'S


STATE HIGHWAY DEPARTMENT OF TRANSPORTATION			
LONG SECTION & BEARINGS			
STRINGERS 1 THRU 5			
DESIGNED BY	DATE	CHECKED BY	DATE
10/24/63	10/24/63	J.C.M.	1963
PROJECT NO.	B-40-281	SHEET	5 OF 14

X27882




- LEGEND**
- #1. ST. G. W. 39.5" RDWY. WIDTH.
 - #2. 4" x 4" RDWY. WIDTH.
 - #3. BAR 2" x 1/2" RDWY. WIDTH. WELD TO #2 WITH 2 LINES OF 1/2" FILLET WELD. 2" G.
 - #4. BAR 2 1/2" x 1/2" RDWY. WIDTH. WELD TO #2 WITH 2 LINES OF 1/2" FILLET WELD. 2" G.
 - #5. FABRICATED FROM 1/2" WELDED PL. WELD TO STEM & FLG. OF ST #1 WITH 1/2" FILLET WELD NEAR SIDE & FAR SIDE AND TO R 15 & R 25.
 - #6. 3/8" MIN. LAMINATED SHIM (SLOTTED)
 - #7. DRILL HOLES IN STRINGER FLANGE IN FIELD FOR 4 1/2" ERECTION BOLTS
 - #8. 1/2" BOLT WITH SQ NUT @ 2'-0" CTRS TACK WELD NUT TO #2 GREASE FOR EASY REMOVAL. 1 1/2" x 1 1/2" SLOTTED HOLE IN ST #1. LONG DIMENSION OF SLOTTED HOLE TO BE PARALLEL TO RDWY
 - #9. APPLY 1/2" COAT OF BITUMASTIC TO THIS SURFACE. AFTER CONCRETE HAS SET FILL WITH HOT POURED ELASTIC TYPE JOINT SEALER.
 - #10. 1/2" VENT HOLES @ 2'-0" CTRS ON L 2 & ST #1
 - #11. 1/2" BENT BAR @ 0'-9" ALTERNATE CTRS. BETWEEN STRINGERS. WELD TO ST #1 (1/2" LG)
 - #12. 1/2" BENT BAR @ 1'-0" CTRS WELD TO #2 (2' LG)
 - #13. L 3" x 2 1/2" x 1/2" APPROX 3'-0" CTRS. WELD TO #2.
 - #14. 1/2" BOLT @ 0'-9" LG. 1 NUT TACK WELD NUT TO #13.
 - #15. 1/2" PL CUT TO SDWK LIMITS AS SHOWN. SHOP WELD TO ST #1 & #6.
 - #16. 1/2" PL CUT TO SDWK LIMITS AS SHOWN. FIELD WELD TO PL #15.
 - #17. SAME AS BOLT #8 EXCEPT FOR LENGTH.
 - #18. 1/2" PLATE - BEND DOWN FACE OF CURB & SDWK LIMITS AS SHOWN. FIELD WELD TO ST #1.
 - #19. 1/2" PLATE - BEND DOWN FACE OF CURB & SDWK LIMITS AS SHOWN.
 - #20. R 2 1/2" x 1/2" BEND DOWN FACE OF CURB & SDWK LIMITS AS SHOWN. WELD TO R #15. FIELD WELD TO BAR #4.
 - #21. 1/2" BENT ANCHOR BAR. WELD TO R 15 & 25, 10 & 14, 16 & 24. (1/2" LG)
 - #22. L 3" x 2 1/2" x 1/2" WELD TO R #19. 1/2" PL WELDS ALL AROUND.
 - #23. 1/2" BOLT & NUT. TACK WELD NUT TO #22 (1/2" LG)
 - #24. R 6" x 1/2" - WELD TO R #19 CUT TO CURB & SDWK LIMITS AS SHOWN.
 - #25. 1/2" PLATE - CUT TO CONFORM TO SHAPE OF CURB. FIELD WELD TO PL #28.
 - #26. BAR 2 1/2" x 1/2" WELD TO R 15 & 19.
 - #27. BLOCK & BOLT FOR SHIPMENT WITH PIPE SLEEVE.
 - #28. 1/2" BOLT PROVIDE 2" HOLES @ 3'-0" CTRS IN ST #1 & #2 FOR 1/2" BOLT AND SUPPORT #5.

- NOTES**
- EXPANSION JOINT SHALL BE BUILT TO CONFORM TO RDWY. SUPERELEVATION AND GRADE.
 - ONE FIELD SPICE SHALL BE PERMITTED
 - ALL ITEMS MARKED #1 SHALL BE MADE OF A242 STEEL WITH A CORROSION RESISTANCE OF 4 OR MORE TIMES THAT OF A36 STEEL.
 - ALL MATERIAL IN EXPANSION JOINT SHALL BE PAID FOR AS STRUCTURAL LOW ALLOY STEEL.
 - AFTER CONCRETE HAS SET REMOVE BOLTS #8 & #17 AND FILL HOLES WITH HOT POURED ELASTIC TYPE JOINT SEALER.
 - NO PAINT SHALL BE APPLIED TO EXPANSION JOINT EXCEPT AS NOTED.
 - AFTER CONCRETE HAS SET THE JOINT OPENING SHALL BE THOROUGHLY CLEANED.
 - APPLY 1/2" COAT OF BITUMASTIC TO METAL SURFACES FORMING THE JOINT AND FILL WITH HOT POURED ELASTIC TYPE JOINT SEALER
 - #10 1/2" HOLE IN BAR #3 & #2.




NOTE: CONC END DIAPHRAGM TO EXTEND BETWEEN WEBS OF FASCIA STRINGERS


REVISION	STATE HIGHWAY COMMISSION OF WISCONSIN
	EXPANSION JOINT
DESIGN SPEC. A A B H O '01	LOADING H 20 S16
DATE 02-26-03	DESIGN J C K
STRUCTURE B-40-281	SHEET 6 OF 14
	X27993




PART ELEVATION




PART PLAN




END PLATE




SECTION A




SECTION B




END PLATE SHIM DETAILS




POST SHIM DETAILS




ANCHOR BOLT SETTING DETAILS




AT POSTS



SECTION THRU SIDEWALK




SECTION THRU CURB



SHOP RAIL SPLICE DETAIL

FIELD ERECTION JOINT DETAIL



POST DETAILS

NOTES


1. STEEL RAIL POSTS SHALL BE SET NORMAL TO GRADE.
2. RAILING SHALL BE FABRICATED IN LENGTHS AS SHOWN.
3. STEEL SHIMS SHALL BE USED UNDER POSTS AND UNDER END PLATES WHERE REQUIRED FOR ALIGNMENT.
4. WHEN PARAPETS AND CURBS ARE POURED CONTINUOUSLY FROM END TO END THEY SHALL BE SEPARATED AT THE DEFLECTION JOINTS BY A PIECE OF 1/2" ZINC OR ALUMINUM PLATE CUT AS SHOWN IN SECTION A BY SHADED AREA. IF CONSTRUCTION JOINTS IN PARAPETS AND CURBS ARE USED AT THE DEFLECTION JOINTS ONE SIDE OF JOINT SHALL BE COATED WITH BITUMINOUS PAINT AND PLATE SEPARATORS MAY BE OMITTED.
5. THE FOLLOWING MATERIALS SHALL BE USED:
TOP RAILING SHALL BE 3/4" STANDARD PIPE ASTM DESIGNATION A53.
BOTTOM RAILING SHALL BE 3" STANDARD PIPE ASTM DESIGNATION A53.
POST SHALL BE FABRICATED FROM MATERIAL CONFORMING TO ASTM DESIGNATION A36.
ANCHOR BOLTS TO BE MADE FROM MATERIAL CONFORMING TO ASTM DESIGNATION A307.
SLEEVES SHALL BE 3" STANDARD PIPE ASTM DESIGNATION A53 FOR TOP RAIL AND 3 SEAMLESS STEEL TUBING (1/2" WALL THICKNESS) FOR BOTTOM RAIL.
6. CAULK EXPOSED OPENINGS BETWEEN SHIMS WITH LEAD WOOL.

DESIGN	STATE HIGHWAY COMMISSION OF WISCONSIN
TYPE	TUBULAR STEEL RAILING
TYPE	TYPE "B"
DESIGN SPEC	AASHTO '61
LOADING	HS 20 S16
DATE	10/24/63
DESIGN	SPD
DRAWN	JCK
CAD	1/2
STRUCTURE	B-40-281
SHEET	7 OF 14


X27884

IF USED THE LOCATION OF THE SHOP SPLICE SHALL BE SHOWN ON THE SHOP DRAWINGS.


*** D-TY NUMBER	PERCENT	CHRG ED	TOTAL CHRG'G
4	F027-1(22)	192	383




PART ELEVATION




PART PLAN




END PLATE
(ALUMINUM)




END PLATE SHIM DETAILS




POST SHIM DETAILS




**DETAIL AT TOP OF
CURB & PARAPET**



SECTION THRU SIDEWALK



SECTION B




SECTION A


ALUMINUM POST CASTING

NOTES

- 1 ALUMINUM RAILING POSTS TO BE SET NORMAL TO GRADE.
- 2 THE HEX NUTS, WASHERS AND THE UPPER 3" OF 4" x 3 1/2" LONG ANCHOR BOLTS SHALL BE GALVANIZED OR CADMIUM PLATED. THE ANCHOR BOLT HOLES, BASE OF RAILING POSTS AND ANCHOR BOLTS, NUTS AND WASHERS SHALL BE COATED WITH AN ALUMINUM IMPREGNATED CAULKING COMPOUND.
- 3 ALUMINUM TUBING SHALL BE FABRICATED IN 2 OR 3 PANEL LENGTHS.
- 4 ALUMINUM ALLOY SHIMS SHALL BE USED UNDER POSTS AND UNDER END PLATES WHERE REQUIRED FOR ALIGNMENT.
- 5 WHEN PARAPETS AND CURBS ARE POURED CONTINUOUSLY FROM END TO END THEY SHALL BE SEPARATED AT THE DEFLECTION JOINTS BY A PIECE OF 1/2" ZINC OR ALUMINUM PLATE CUT AS SHOWN IN SECTION "B" BY THE SHADED AREA. IF CONSTRUCTION JOINTS IN PARAPETS AND CURBS ARE USED AT THE DEFLECTION JOINTS ONE SIDE OF JOINT SHALL BE COATED WITH BITUMINOUS PAINT AND PLATE SEPARATORS MAY BE OMITTED.



SECTION THRU CURB



AT END PLATE

AT POSTS

ANCHOR BOLT SETTING DETAILS

REVISED	STATE HIGHWAY COMMISSION OF WISCONSIN			
	TUBULAR ALUMINUM RAILING TYPE B			
	DESIGN SPEC A A 5HD 61	LOADING H 20 S16	SHEET 106	
	DATE 10/24/63	DESIGN STD	DRAWN J. A. CEB	CHK JAC
	B-40-281			SHEET 8 OF 14

X 27885





23-DEC-1997 10:15

ScreenScan

BILL OF BARS 2230


DIMENSIONS IN BRACING DETAILS ARE OUT TO OUT


POUR MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET
A1	18	4	23-3	SHOWN	BODY - HORIZ	
A2	46	4	4-6	1-C	" - VERT	A
A3	6	8	23-6	SHOWN	" - HORIZ	
A4	23	4	13-3	2-0	" - VERT	B
A5	6	4	12-9	SHOWN	PARAPET - HORIZ	
A6	35	5	4-9	1-0	" - VERT	C
A7	8	4	8-6	SHOWN	" - HORIZ DO NOT LAP	
A8	23	5	8-3	1-8	" - VERT	C
A9	16	4	6-6	8	PARAPET & SDWK	D
A10	10	4	4-9	SHOWN	BODY & WING	D
A11	3	4	16-0	1-6	WING 1	D
A12	6	4	8-3	1-8	" 1	
A13	8	4	8-9	1-6	" 1	
A14	6	4	11-0	1-6	" 2	D
A15	5	4	9-3	1-6	" 2	
A16	9	4	9-3	1-8	" 2	D
A17	28	4	3-9	SHOWN	GRID	
A18	20	4	4-0	SHOWN	"	
A19	8	5	9-3	SHOWN	RAILING PARAPET	
A20	20	5	6-0	1-0	"	C
A21	8	4	10-9	1-8	WING 1	
A22	8	4	11-0	1-6	" 2	
A23	3	4	11-0	1-6	" 1	D
A24	16	4	3-3	4	PARAPET - VERT B.F. & R.F.	
A25	8	4	5-0	4	" - HORIZ	
A26	8	4	6-0	4	"	



REVISED	STATE HIGHWAY COMMISSION OF WISCONSIN
WEST ABUTMENT	
DESIGN BY: AASHO 61' H20-5161' 1963	
REVISED: 10-24-63 - VGH - CHP	
STRUCTURE B 40-281	SHEET 9 OF 14

X27886





X27587

FOOT-1(22) 195 383

BILL OF BARS


6,380 #

DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT


FOOTING	NO	SIZE	LENGTH	SPACING	LOCATION	DE
C1	28	6	9-6	SHOWN	FOOTINGS - EXT.	
C2	26	5	7-6	"	"	
C3	16	7	10-6	"	" - INT.	
C4	13	6	8-0	"	"	
C5	42	8	4-0	"	" - DOWELS	D
C6	3	4	9-6	"	" - HOOPS	A
C6	43	4	9-6	SHOWN	COLUMN - HOOPS	A
C7	14	8	16-9	"	COLUMN 2	
C8	2	8	17-3	"	" 1	
C9	2	8	16-6	"	" 3	
C10	6	8	24-3	"	" 1	D
C11	6	8	23-6	"	" 3	D
C12	6	8	19-0	"	" 1	D
C13	6	8	18-3	"	" 3	D
C14	6	10	14-0	"	CAP **	
C15	6	10	10-0	"	" **	
C16	4	4	20-0	"	"	
C17	8	5	11-6	"	"	
C18	4	11	20-0	"	"	
C19	8	11	17-6	"	"	
C20	4	4	6-3	"	" - BANDS	B
C21	20	4	11-9	"	" - STIRRUPS	C
C22	24	5	10-3	"	" - STIRRUPS	C

* SAME SPACING AS VERTICAL COLUMN BARS


** BUNDLED BARS



SECTION C1




SECTION C2




SECTION C3




DETAIL A



DETAIL B




DETAIL C




DETAIL D




BUNDLE DETAIL




ELEVATION




PLAN




FOOTING PLAN



SECTION C4



SECTION C5



SECTION C6

CONCRETE MASONRY

FOOTINGS 18.8 CY
COLUMNS 11.3 CY
CAP 14.5 C.Y.
TOTAL 44.6 C.Y.

REVISED	STATE HIGHWAY COMMISSION OF WISCONSIN
PIER 2	
DESIGN SPEC. AASHTO 61	LOADING H20-516
DATE 10-24-63	DRAWN H.F.H.
STRUCTURE B-40-281	SHEET 11 OF 14


X 27888

BILL OF BARS 4800**


DIMENSIONS IN BENDING DETAILS ARE OUT TO OUT

FOOT MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET
FOOTINGS	D1	16	5	6-3	FOOTINGS - EXT.	
	D2	16	5	6-9	" - "	
	D3	8	7	7-6	" - INT.	
	D4	8	7	7-9	" - "	
	D5	36	7	3-6	" - DOWELS *	D
	D6	3	4	9-6	" - HOOPS	A
CAP & COLUMNS	D6	41	4	9-6	SHOWN COLUMN - HOOPS	A
	D7	12	7	16-6	" - 2	
	D8	6	7	23-9	" - 1	D
	D9	6	7	18-9	" - 1	D
	D10	6	7	23-0	" - 3	D
	D11	6	7	17-9	" - 3	D
	D12	6	10	14-0	" - CAP **	
	D13	6	10	10-0	" - "	
	D14	4	4	20-0	" - "	
	D15	8	5	11-6	" - "	
	D16	4	11	20-0	" - "	
	D17	8	11	17-6	" - "	
	D18	4	4	6-3	" - BANDS	B
	D19	20	4	11-9	" - STIRRUPS	C
	D20	24	5	10-3	" - STIRRUPS	C


* SAME SPACING AS VERTICAL COLUMN BARS
** BUNDLED BARS



SECTION D1




SECTION D2




SECTION D3




DETAIL A




DETAIL B




DETAIL C




DETAIL D




BUNDLE DETAIL





ELEVATION




PLAN




FOOTING PLAN



SECTION D4



SECTION D5



SECTION D6

CONCRETE MASONRY

FOOTINGS	12.1 C.Y.
COLUMNS	10.9 C.Y.
CAP	15.2 C.Y.
TOTAL	38.2 C.Y.

STATE HIGHWAY COMMISSION OF WISCONSIN

PROJECT	PIER 3
DESIGN SPEC	A A S. 4.0.
DATE	10-26-63
DESIGN	V G H
CHECK	H F H
DATE	10-26-63
STRUCTURE	B-40-281
SHEET	12 OF 14

X 27889

23-DEC-1997 10:17


SCREENSCAN

BILL OF BARS

2220

DIMENSIONS IN BRIDGING DETAILS ARE OUT TO OUT.



POUR MARK	NO	SIZE	LENGTH	SPACING	LOCATION	DET
E1	18	4	23-3	SHOWN	BODY - HORIZ	
E2	46	4	4-6	1-0	- VERT	A
E3	6	6	23-6	SHOWN	" - HORIZ	B
E4	23	4	13-3	2-C	- VERT	
E5	6	4	18-9	SHOWN	PARAPET - HORIZ	C
E6	35	5	4-9	1-0	- VERT	
E7	8	4	8-6	SHOWN	" - HORIZ DO NOT LAP	C
E8	23	5	8-3	1-6	- VERT	
E9	8	4	10-9	8	PARAPET & SDWK	D
E10	10	4	4-9	SHOWN	BODY & WING	
E11	3	4	16-3	1-6	WING 4 & PARAPET	D
E12	7	4	8-3	1-6	"	
E13	7	4	8-9	1-6	"	
E14	6	4	11-0	1-6	WING 3	D
E15	5	4	9-3	1-6	"	
E16	9	4	9-3	1-6	"	
E17	28	4	3-9	SHOWN	GRID	D
E18	16	4	4-0	SHOWN	"	
E19	6	5	9-3	SHOWN	RAILING PARAPET	C
E20	20	5	6-0	1-0	"	
E21	8	4	11-6	1-6	WING 3	
E22	8	4	12-9	1-6	WING 4	D
E23	3	4	11-0	1-6	WING 4	
E24	16	4	3-3	4	PARAPET - VERT. B.F. & R.F.	
E25	8	4	5-0	4	" - HORIZ	
E26	8	4	6-0	4	"	



2'x1' SPALL

0.5'x3.5' DELAM

2'x1' DELAM



DETAIL A

DETAIL B

DETAIL C

DETAIL D

SECTION B-B

SECTION C-C

SECTION A-A

ELEVATION WING 3 TYP

ELEVATION WING 4

REVISION	STATE HIGHWAY COMMISSION OF WISCONSIN
EAST ABUTMENT	
AASHTO 61 H20-S16 1963	
10-24-63 VGH C.K.P.	
STRUCTURE B 40 281	SHEET 13 14

X 27890

ATTACHMENT 3
ASBESTOS REPORT



708 Heartland Trail, Suite 3000
Madison, WI 53717

608.826.3600 PHONE
608.826.3941 FAX

www.TRCSolutions.com

Bridge Asbestos Inspection Report

WisDOT Project ID: 0656-50-30

Structure Number: B-40-0281

Structure Name: W. Grantosa Drive EB over STH 145/Fond du Lac Avenue

City/County: City of Milwaukee, Milwaukee County

Lat/Long Coordinates: 430643.17/ 880010.15

TRC Project Number: 283767.0000.0000

Date Inspected: July 20, 2017

Inspected By/License Number: Ross Hartwick, All-195369

Findings:

Files available online for this bridge were reviewed, including the "As-built" drawings. The inspection to identify and collect samples of potential asbestos-containing material (ACM) was completed following WisDOT standard sampling procedure for bridge inspections found in FDM 21-35-45.

The gasket located under the railing attachment plates on the concrete parapet and the transite pipes under the bridge tested positive for asbestos greater than 1% and is therefore regulated ACM. If the ACM will be disturbed during the planned bridge rehabilitation, the ACM must be removed prior to any work. Standard Special Provision (STSP) 203-005 should be incorporated into the specifications. If the ACM will not be disturbed during the planned bridge rehabilitation, STSP 107-120 should be included in the specifications.


Sample Number	Sample Description	Sample Location	Analytical Results and Method	Friable/ Non-friable or No ACM	Quantity of ACM Material
EB-1	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	0
EB-2	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	
EB-3	Black paint	Pedestrian fence, railing	PLM, non-detect	No ACM	

Sample Number	Sample Description	Sample Location	Analytical Results and Method	Friable/ Non-friable or No ACM	Quantity of ACM Material
EB-4	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	0
EB-5	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	
EB-6	Caulk	Parapet expansion joint, sidewalk joint	PLM, non-detect	No ACM	
EB-7	Gasket	Under railing attachment plate	PLM, 3%	Non-friable	7.5"x34"x2 + 7.5"x7.5"x28 = 14.5 sq ft
EB-8	Gasket	Under railing attachment plate	Not analyzed, positive stop	--	
EB-9	Gasket	Under railing attachment plate	Not analyzed, positive stop	--	
EB-10	Tar	Bearing support pier	PLM, non-detect	No ACM	0
EB-11	Tar	Bearing support pier	PLM, non-detect	No ACM	
EB-12	Tar	Bearing support pier	PLM, non-detect	No ACM	
EB-13	Silver paint	Girder	PLM, non-detect	No ACM	0
EB-14	Silver paint	Girder	PLM, non-detect	No ACM	
EB-15	Silver paint	Girder	PLM, non-detect	No ACM	
EB-16	Transite	Piping	PLM, 20%	Friable	6 pipes x 4" diameter x 198' long = 1,248 sq ft
EB-17	Transite	Piping	Not analyzed, positive stop	--	
EB-18	Transite	Piping	Not analyzed, positive stop	--	
EB-19	Pipe wrap	Utility Piping	PLM, non-detect	No ACM	0
EB-20	Pipe wrap	Utility Piping	PLM, non-detect	No ACM	
EB-21	Pipe wrap	Utility Piping	PLM, non-detect	No ACM	
EB-22	Paint	Galvanized metal conduit	PLM, non-detect	No ACM	0
EB-23	Paint	Galvanized metal conduit	PLM, non-detect	No ACM	
EB-24	Paint	Galvanized metal conduit	PLM, non-detect	No ACM	



If you have any questions, please contact me, at (608) 826-3628.

TRC Environmental Corporation



Daniel Haak
Project Manager




Ross Hartwick
Asbestos Inspector

Attachments: Location Map, Photos, and Laboratory Report

Report Distribution:

Recipient	Electronic (PDF) Copy	Paper Copy
BTS-ESS sharlene.tebeest@dot.wi.gov	X (via email)	X
REC Andrew.malsom@dot.wi.gov	X (via email)	
Project Manager jason.zemke@dot.wi.gov	X (via email)	
Other		



Bridge B-40-0281



Black paint on pedestrian fence and railing



Caulk in parapet expansion joint and sidewalk joint



Gasket under railing attachment plate



Tar on bearing support piers



Silver paint on girder



Transite piping



Transite piping



Pipe wrap on utility piping



Paint on galvanized metal conduit



BULK ASBESTOS ANALYSIS REPORT

CLIENT: Wisconsin Department of Transportation

Lab Log #: 0050964
Project #: 283673.0000.0000
Date Received: 07/21/2017
Date Analyzed: 07/21/2017

Site: Bridge Inspection, B-40-281

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
EB-01	Black (paint)	Yes	No	--	---	ND	None
EB-02	Black (paint)	Yes	No	--	---	ND	None
EB-03	Black (paint)	Yes	No	--	---	ND	None
EB-04	Grey (caulk)	Yes	No	--	---	ND	None
EB-05	Grey (caulk)	Yes	No	--	---	ND	None
EB-06	Grey (caulk)	Yes	No	--	---	ND	None
EB-07	Grey (gasket)	Yes	No	--	---	3%	Chrysotile
EB-08	--	--	--	--	--	NA/PS	--
EB-09	--	--	--	--	--	NA/PS	--
EB-10	Dark Grey (tar)	Yes	No	--	5% cellulose	ND	None
EB-11	Dark Grey (tar)	Yes	No	--	5% cellulose	ND	None
EB-12	Dark Grey (tar)	Yes	No	--	5% cellulose	ND	None
EB-13	Grey (paint)	Yes	No	--	---	ND	None
EB-14	Grey (paint)	Yes	No	--	---	ND	None
EB-15	Grey (paint)	Yes	No	--	---	ND	None
EB-16	Grey (utility conduit)	Yes	No	--	---	20%	Chrysotile
EB-17	--	--	--	--	--	NA/PS	--

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0
RI #AAL-007 TX #300354
CO# AL-15020

AIHA-LAP,LLC #100122 CT #PH-0426
VT #AL014538 LA#05011 VA #3333 000283
PHIL# 461 PA#68-03387

ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV# LT000411
AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907



POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
EB-18	--	--	--	--	--	NA/PS	--
EB-19	Black (pipe wrap)	Yes	No	--	---	ND	None
EB-20	Black (pipe wrap)	Yes	No	--	---	ND	None
EB-21	Black (pipe wrap)	Yes	No	--	---	ND	None
EB-22	Black (paint)	Yes	No	--	---	ND	None
EB-23	Black (paint)	Yes	No	--	---	ND	None
EB-24	Black (paint)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%

ND - asbestos was not detected

Trace - asbestos was observed at level of less than 1%

NA/PS - Not Analyzed / Positive Stop

SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by:

K. Williamson

Kathleen Williamson, Laboratory Manager

Reviewed by:

Cathryn Lemire

Cathryn Lemire, Approved Signatory

Date Issued

07/23/2017

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0
RI #AAL-007 TX #300354
CO #AL-15020

AIHA-LAP, LLC #100122 CT #PH-0426
VT #AL014538 LA#05011 VA #3333 000283
PHIL# 461 PA#68-03387

ME LA-0075, LB-0071 MA #AA000052
AZ #A20944 HI #L-09-004

NY #10980 WV# LT000411
NJ #CT004 CA #2907

ATTACHMENT 4
STRUCTURE ALTERNATIVE
REPORT & ASSOCIATED E-MAILS



collaborāte / formulāte / innovāte

MEMORANDUM

TO: Roy Stollenwerk, P.E. & Christine Hanna, P.E.

FROM: GRAEF

DATE: October 26, 2018

SUBJECT: Bridge Alternative Life Cycle Cost Analysis
ID 1360-11-00
Grantosa Dr. over STH 145
Bridges B-40-280 and B-40-281
Milwaukee County

Construction is planned on two bridges over STH 145 as part of Project 1360-11-70. The project is scheduled for a PS&E date of May 1, 2020 and construction is currently scheduled for 2021.

The abutments on Bridges B-40-280 and B-40-281 are supported by spread footings. A site visit on March 23, 2018 indicated the east abutments of both bridges had slid towards STH 145, and possibly rotated. Although efforts to address the abutment movements were made in 1992 by way of lengthening the expansion slots of the hold-down bearings, at the time of GRAEF's inspection additional movements had taken place which had left the expansion bearings significantly out of alignment. As a result, alternatives to address the abutment movements were investigated.

Bridge improvement options include:

1. Conversion of the east and west abutments on both bridges to semi-expansion seats.
2. Replacement of the east and west abutments on both bridges
3. Complete bridge replacement using steel girders that match the existing substandard vertical clearance.
4. Complete bridge replacement using prestressed girders that raise the roadway profile to meet a minimum vertical clearance of 16'-4".

For each alternative, a construction and life cycle cost analysis has been prepared. A 75-year analysis period has been selected based on the anticipated design life of newly constructed bridges in Wisconsin, and an effective discount rate of 3.5% was assumed. Future major construction/rehabilitation activities were assumed at specified years beyond the initial construction. Recurring future maintenance items (such as bridge inspections) were not included as these were assumed to be the same for all alternatives. Construction unit costs used for the life cycle cost analysis are listed in Appendix A.

Conversion to Semi-Expansion Abutments

Semi-expansion abutments allow the girder ends to contract in cold temperatures, but provide restraint in hotter temperatures. Use of ½" thick elastomeric girder bearing pads placed on polyethylene sheets allow the girder ends to freely slide and result in a low maintenance bearing system. Conversion of the existing abutments to semi-expansion abutments will require temporary shoring of the existing bridge girders, existing abutment removal above the bearing seats, removal of the existing steel hold-down bearing devices, placing new elastomeric bearing pads under the girders, and casting a solid diaphragm to encase the ends of the bridge girders. Cleaning and flame metallizing the girder ends will help to protect the steel from future corrosion due to encasement in the concrete diaphragms

Use of semi-expansion bearings on steel girder bridges is limited to 150-ft which is less than the existing 194-ft bridge length. The Bureau of Structures Development Unit is willing to grant an exception to this provision given the shallow 30" girder depth.

Because the existing abutment bodies will be reused and the original bridge was designed for an H-20 load, the soil bearing pressure was checked for the additional dead load of the semi-expansion bearing's concrete end diaphragm and the HS-20 live loading used for load rating purposes. Preliminary results using service loads indicate that the maximum soil bearing press is approximately 2.9 ksf at the abutment toe under full dead plus live loads. This is less than the 5.0 ksf allowable soil bearing pressure indicated in the original abutment design calculations, and suggests abutment conversion is a feasible option.

A second feasibility check for this alternative was performed to address girder uplift. AASHTO Standard Specifications 3.17.1 was checked using results from an MDX line girder model. Preliminary calculations indicate that the end diaphragm will need to be extended 2.5-ft beyond the abutment front face to provide adequate dead load to resist uplift forces. See Figure 1.




Figure 1: Conversion to Semi-expansion Abutment

For this alternative, the life cycle cost estimate considered that the existing bridge will be approximately 55 years old when rehabilitated. Appendix B lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 55 years - new deck construction, abutment conversion to semi-expansion bearings, steel girder repainting, and flame metallizing the steel girder ends. Miscellaneous repairs were assumed to cost 15% of the major rehabilitation items. Construction costs also include associated roadway approach work and contingencies.

Year 20, bridge age 75 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 35, bridge age 90 years – demolition and construction of a new prestressed concrete girder bridge with structural approach slabs. The new bridge length is assumed to be 7% greater than the existing bridge to accommodate the new roadway profile. Construction costs also include roadway work to raise Grantosa Drive, acquire right-of-way, and associated contingencies.

Year 55, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 70, bridge age 35 years - new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 75, bridge age 40 years – no major construction activities are anticipated at this stage. As part of the life cycle cost analysis, a residual value of the bridge was estimated to represent the remaining service life beyond year 75. It was estimated based on an anticipated NBI condition rating of 6 for a 40-year old bridge, prorated against an NBI rating of 9 when new and 3 at the end of its service life. The residual value is calculated as:

$$\frac{(\text{cost for a new bridge}) \times (\text{NBI}_{40} - \text{NBI}_{\text{service life}})}{(\text{NBI}_{\text{new}} - \text{NBI}_{\text{service life}})}$$

Abutment Replacements

For this alternative, type A3 pile supported abutments were assumed. Type A3 pile supported abutments have a minimum of 2 rows of piles with the front row battered to help resist lateral forces (see Figure 2). Current practice in Wisconsin is to generally use pile supported abutments to control vertical settlement. Replacement of the existing abutments will require temporary shoring of the existing bridge girders, existing abutment removal, pile driving, concrete placement for the new abutments and wingwalls, and installation of new hold-down expansion bearings under the girders. Given the age of the bridge, it was assumed that construction of new structure approach slabs would not be cost effective even though new abutments could be designed to handle these loads.




Figure 2: Standard A3 Abutment

Caution will be required while driving piles at the west abutment for bridge B-40-280 due to an existing 24" sanitary sewer passing underneath. This active sewer is located approximately 22-ft below the existing roadway and crosses the centerline of bearing at about a 30-degree angle.

For this alternative, the life cycle cost estimate considered that the existing bridge will be approximately 55 years old when rehabilitated. Appendix C lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 55 years - new deck construction, drive piles, replace the abutments, steel girder repainting, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items. Construction costs also include associated roadway approach work and contingencies.

Year 20, bridge age 75 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 35, bridge age 90 years – demolition and construction of a new prestressed concrete girder bridge with structural approach slabs. The new bridge length is assumed to be 7% greater than the existing bridge to accommodate the new roadway profile. Construction costs also include roadway work to raise Grantosa Drive, acquire right-of-way, and associated contingencies.

Year 55, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 70, bridge age 35 years - new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 75, bridge age 40 years – no major construction activities are anticipated at this stage. As part of the life cycle cost analysis, a residual value of the bridge was estimated to represent the remaining service life beyond year 75. It was estimated using the same method for the semi-expansion abutment conversion alternative.

Complete Replacement with a New Steel Girder Bridge

This alternative replaces the existing structures with steel girder bridges at the same roadway profile as the existing. The current substandard vertical clearance will remain. For life cycle cost analysis purposes, a steel girder replacement bridge with the same total length, width, and substructure locations as the existing was assumed. This approach was judged to be feasible because the existing abutments and piers are founded on shallow footings and there are no existing piles to cause interferences. Caution must be exercised concerning pile design and driving to avoid the existing 24" sanitary sewer at the west abutment of B-40-280 and the west pier of B-40-281. Structure approach slabs were assumed to be constructed as part of the bridge replacement given the projected ADT on Grantosa Drive.

For this alternative, the life cycle cost estimate considered that the existing bridge will have a life span of 75 years. Appendix D lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 0 years – demolition and construction of a new steel girder bridge with structural approach slabs. The new bridge deck area is assumed to match the existing bridge.

Year 20, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 35, bridge age 35 years – new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 55, bridge age 55 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 75, bridge age 75 years – demolition and construction of a new prestressed concrete girder bridge is assumed, but these costs are not included in the life cycle analysis because the new bridge's service life falls beyond the 75-year study period. In addition, it is assumed that the existing bridge has no remaining usable service life and therefore no residual value.

Complete Replacement with a New Prestressed Concrete Girder Bridge

This alternative replaces the existing structures with 36" deep prestressed concrete girder bridges. Since this alternative requires raising the profile of Grantosa Drive, it is assumed the roadway profile is raised to attain the 16'-4" minimum vertical clearance required for STH 145. For life cycle cost analysis purposes, length of a prestressed concrete girder replacement bridge was approximated to be about 7% greater than the existing assuming a 3:1 embankment extension at the top of the existing. The bridge widths were assumed to be unchanged from the existing, as were the pier locations. This approach was judged to be feasible because the existing abutments and piers are founded on shallow footings and there are no existing piles to cause interference. Caution must be exercised concerning pile design and driving to avoid the existing 24" sanitary sewer at the west abutment of B-40-280 and the west pier of B-40-281. Structure approach slabs were assumed to be constructed as part of the bridge replacement given the projected ADT on Grantosa Drive.

Associated roadway improvements include raising the profile of Grantosa Drive approximately 2'-5" to attain a minimum vertical clearance of 16'-4" to meet FDM 11-35 requirements for new bridges. The required rise in roadway profile considers a 36W" prestressed concrete girder shape which has the capacity to span up to 100-ft. It is assumed that right-of-way acquisition will be required for the raised profile on Grantosa Drive.

For this alternative, the life cycle cost estimate considered that the existing bridge will have a life span of 75 years. Appendix E lists the analysis details. Assumptions for major bridge construction activities for the 75-year analysis period include the following:

Year 0, bridge age 0 years – demolition and construction of a new prestressed concrete girder bridge with structural approach slabs. The new bridge length is

assumed to be 7% greater than the existing bridge to accommodate the new roadway profile. Construction costs also include roadway work to raise Grantosa Drive, acquire right-of-way, and associated contingencies.

Year 20, bridge age 20 years – concrete overlay, and miscellaneous repairs assumed to cost 10% of the major rehabilitation items.

Year 35, bridge age 35 years – new deck construction, and miscellaneous repairs assumed to cost 15% of the major rehabilitation items.

Year 55, bridge age 55 years – concrete overlay, and miscellaneous repairs assumed to cost 20% of the major rehabilitation items.

Year 75, bridge age 75 years – demolition and construction of a new prestressed concrete girder bridge is assumed, but these costs are not included in the life cycle analysis because the new bridge's service life falls beyond the 75-year study period. In addition, it is assumed that the existing bridge has no remaining usable service life and therefore no residual value.

Conclusions

Results of the life cycle cost analyses are summarized in Table 1 below.

Table 1: Life Cycle Costs of Design Alternatives

Description	Initial Cost at Year 0	Life Cycle Cost at Present Value	Life Cycle Cost as an Annuity
Alternative 1 – Redeck and conversion to a semi-expansion abutment	\$1,230,000 per bridge, <i>\$2,460,000 total</i>	\$2,320,000 per bridge, <i>\$4,640,000 total</i>	\$87,900/bridge/year, <i>\$176,000 total/year</i>
Alternative 2 – Redeck and abutment replacement	\$1,530,000 per bridge, <i>\$3,060,000 total</i>	\$2,630,000 per bridge, <i>\$5,270,000 total</i>	\$99,800/bridge/year, <i>\$200,000 total/year</i>
Alternative 3 – Replacement with steel girder bridge	\$1,950,000 per bridge, <i>\$3,900,000 total</i>	\$2,410,000 per bridge, <i>\$4,820,000 total</i>	\$91,100/bridge/year, <i>\$182,000 total/year</i>
Alternative 4 – Replacement with prestressed concrete girder bridge	\$3,090,000 per bridge, <i>\$6,180,000 total</i>	\$3,510,000 per bridge, <i>\$7,020,000 total</i>	\$133,000/bridge/year, <i>\$266,000 total/year</i>

Recommendations

Results of the life cycle cost analysis show that Alternative 1, redeck and conversion to a semi-expansion abutment, has not only the lowest life cycle cost, but also the lowest first cost as part of the current project. This is a result of maximizing the existing bridge's

service life and original public investment, and of minimizing the amount of rehabilitation work needed to address the abutment movements.

A technical concern is the continued use of abutments experiencing excessive movements and hold-down bearings exhibiting uplift damage. These concerns are addressed by conversion to a semi-expansion abutment. Semi-expansion abutments by nature will provide lateral bracing against forces that tend to cause abutment sliding and overturning. In addition, final design to provide adequate dead load of the end diaphragms will eliminate undesirable live load uplift forces. A technical advantage offered by Alternative 1 is that pile driving is not needed, thereby eliminating the risk of damaging the existing 24" sanitary sewer.

Given the economic and technical benefits, we recommend that Alternative 1 be selected as the preferred option.

KGW:kgw

X:\ML\2017\20170145\Project_Information\Reports\Bridge Alternative Study\1360-11-00_STH 145 - Bridge Alternative Study Memo.docx

cc: File

APPENDIX A

Construction Unit Costs

Rehab Unit Prices from WisDOT Year End Structure Cost Summary Spreadsheets and the WisDOT Bridge Manual

New Steel Bridge

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2016	\$147.09	\$168.37	Say \$175/SF
2015	\$201.30		
2014	\$182.81		
2013	\$142.28		
Sum =	\$673.48		

New PPC Bridge

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$123.10	\$116.55	Say \$125/SF
2016	\$117.76		
2015	\$132.82		
2014	\$108.15		
2013	\$100.92		
Sum =	\$582.75		

Concrete Overlay (use total system values)

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$14.51	\$18.86	Say \$20/SF
2016	\$23.89		
2015	\$18.19		
Sum =	\$56.59		

New Deck (use total system values)

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$85.13	\$78.83	Say \$80/SF
2016	\$78.37		
2015	\$73.00		
Sum =	\$236.50		

Painting (use total system values)

Year	Unit Cost \$/SF	Ave. Unit Cost \$/SF	
2017	\$16.29	\$19.37	Say \$18/SF
2016	\$16.93		
2015	\$24.90		
Sum =	\$58.12		

APPENDIX B

Alternative 1 – Conversion to Semi-expansion Abutments

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/11/2018

OPTION: Alternate #1 - Convert (2) existing abutments to semi-expansion

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Salvage (Residual) Value
as a % of Replacement Cost: 50.0% (assumes NBI = 9 new, 3 at end of service life, and 6 at end of analysis period)

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	New deck on 55 year old bridge	9100	SF	\$80	\$728,000	\$728,000
0	Convert 2 abutments to semi-expansion	2	EACH	\$47,000	\$94,000	\$94,000
0	Steel girder repainting	10700	SF	\$18	\$192,600	\$192,600
0	Misc. repairs (15% of major rehab items)	1	LS	\$152,190	\$152,190	\$152,190
0	Roadway approach, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$66,000	\$66,000	\$66,000
0					\$0	\$0
	Subtotal - Initial Costs					\$1,232,790
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay on 75 year old bridge	9100	SF	\$20	\$182,000	\$91,467
20	Misc. repairs (20% of major rehab items)	1	LS	\$36,400	\$36,400	\$18,293
20					\$0	\$0
20					\$0	\$0
35	Demo existing 90 year old bridge	9100	SF	\$20	\$182,000	\$54,596
35	New PPC girder bridge	9750	SF	\$125	\$1,218,750	\$365,597
35	New structure approach slabs	1	LS	\$57,000	\$57,000	\$17,099
35	Raising Grantosa, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$1,400,000	\$1,400,000	\$419,968
35	ROW acquisition	1	LS	\$180,000	\$180,000	\$53,996
55	Concrete overlay on 20 year old bridge	9750	SF	\$20	\$195,000	\$29,398
55	Misc. repairs (10% of major rehab items)	1	LS	\$19,500	\$19,500	\$2,940
55					\$0	\$0
55					\$0	\$0
70	New deck on 35 year old bridge	9750	SF	\$80	\$780,000	\$70,189
70	Misc. repairs (15% of major rehab items)	1	LS	\$117,000	\$117,000	\$10,528
70					\$0	\$0
70					\$0	\$0
75	Salvage (Residual) value - 40 year old bridge	1	LS	(\$609,375)	-\$609,375	-\$46,170
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$2,320,690
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$87,883</i>

APPENDIX C

Alternative 2 – Abutment Replacement

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/11/2018

OPTION: [Alternate #2 - Replace \(2\) existing abutments](#)

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Salvage (Residual) Value
as a % of Replacement Cost: 50.0% (assumes NBI = 9 new, 3 at end of service life, and
6 at end of analysis period)

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	New deck on 55 year old bridge	9100	SF	\$80	\$728,000	\$728,000
0	Replace 2 abutment	2	EACH	\$176,000	\$352,000	\$352,000
0	Steel girder repainting	10700	SF	\$18	\$192,600	\$192,600
0	Misc. repairs (15% of major rehab items)	1	LS	\$190,890	\$190,890	\$190,890
0	Roadway approach, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$66,000	\$66,000	\$66,000
0					\$0	\$0
	Subtotal - Initial Costs					\$1,529,490
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay on 75 year old bridge	9100	SF	\$20	\$182,000	\$91,467
20	Misc. repairs (20% of major rehab items)	1	LS	\$36,400	\$36,400	\$18,293
20					\$0	\$0
20					\$0	\$0
35	Demo existing 90 year old bridge	9100	SF	\$20	\$182,000	\$54,596
35	New PPC girder bridge	9750	SF	\$125	\$1,218,750	\$365,597
35	New structure approach slab	2	EACH	\$57,000	\$114,000	\$34,197
35	Raising Grantosa, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$1,400,000	\$1,400,000	\$419,968
35	ROW acquisition	1	LS	\$180,000	\$180,000	\$53,996
55	Concrete overlay on 20 year old bridge	9750	SF	\$20	\$195,000	\$29,398
55	Misc. repairs (10% of major rehab items)	1	LS	\$19,500	\$19,500	\$2,940
55					\$0	\$0
55					\$0	\$0
70	New deck on 35 year old bridge	9750	SF	\$80	\$780,000	\$70,189
70	Misc. repairs (15% of major rehab items)	1	LS	\$117,000	\$117,000	\$10,528
70					\$0	\$0
70					\$0	\$0
75	Salvage (Residual) value - 40 year old bridge	1	LS	(\$609,375)	-\$609,375	-\$46,170
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$2,634,489
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$99,766</i>

APPENDIX D

Alternative 3 – Steel Girder Bridge Replacement

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/25/2018

OPTION: [Alternate #3 - New steel girder bridge \(200' x 45.5'\)](#)

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	Demo existing bridge	9100	SF	\$20	\$182,000	\$182,000
0	New steel girder bridge	9100	SF	\$175	\$1,592,500	\$1,592,500
0	New structure approach slabs	2	EACH	\$57,000	\$114,000	\$114,000
0	Roadway approach, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$66,000	\$66,000	\$66,000
0					\$0	\$0
	Subtotal - Initial Costs					\$1,954,500
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay	9100	SF	\$20	\$182,000	\$91,467
20	Misc. repairs (10% of major rehab items)	1	LS	\$18,200	\$18,200	\$9,147
20					\$0	\$0
20					\$0	\$0
35	New deck	9100	SF	\$80	\$728,000	\$218,383
35	Steel girder repainting	10700	SF	\$18	\$192,600	\$57,776
35	Misc. repairs (15% of major rehab items)	1	LS	\$138,090	\$138,090	\$41,424
35					\$0	\$0
35					\$0	\$0
55	Concrete overlay	9100	SF	\$20	\$182,000	\$27,438
55	Misc. repairs (20% of major rehab items)	1	LS	\$36,400	\$36,400	\$5,488
55					\$0	\$0
55					\$0	\$0
75					\$0	\$0
75					\$0	\$0
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$2,405,622
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$91,099</i>

APPENDIX E

Alternative 4 – Prestressed Concrete Girder Bridge Replacement

LIFE CYCLE COST ANALYSIS WORK SHEET

Project Name: Grantosa Ave. Bridge Alternative Analysis B-40-280/281

Project Number: 2017-0145.00

Date: 10/25/2018

OPTION: [Alternate #4 - New PPC girder bridge \(214' x 45.5'\)](#)

Discount Rate (effective): 3.5% (accounts for relative financial risk of investment)

Life Cycle: 75 years

Year	Description	Quantity	Unit	Unit Price	Extension (use present values)	Present Value
	INITIAL COSTS					
0	Demo existing bridge	9100	SF	\$20	\$182,000	\$182,000
0	New PPC girder bridge	9750	SF	\$125	\$1,218,750	\$1,218,750
0	New structure approach slabs	2	EACH	\$57,000	\$114,000	\$114,000
0	Raising Grantosa, mobilization, earthwork contingencies, etc. PER BRIDGE	1	LS	\$1,400,000	\$1,400,000	\$1,400,000
0	ROW acquisition	1	LS	\$180,000	\$180,000	\$180,000
	Subtotal - Initial Costs					\$3,094,750
	FUTURE ITEMS (ONE TIME COSTS)					
20	Concrete overlay	9750	SF	\$20	\$195,000	\$98,000
20	Misc. repairs (10% of major rehab items)	1	LS	\$19,500	\$19,500	\$9,800
20					\$0	\$0
20					\$0	\$0
35	New deck	9750	SF	\$80	\$780,000	\$233,982
35	Misc. repairs (15% of major rehab items)	1	LS	\$117,000	\$117,000	\$35,097
35					\$0	\$0
35					\$0	\$0
55	Concrete overlay	9750	SF	\$20	\$195,000	\$29,398
55	Misc. repairs (20% of major rehab items)	1	LS	\$39,000	\$39,000	\$5,880
55					\$0	\$0
55					\$0	\$0
75					\$0	\$0
75						\$0
	Future Items (annual costs)					
	None anticipated			\$0	\$0	\$0
	Total Life Cycle Costs					\$3,506,907
	<i>Annuity Cost/Year</i>	<i>n =</i>	<i>75</i>	<i>years</i>		<i>\$132,804</i>

From: [Landini, Anthony P - DOT](#)
To: [Stollenwerk, Roy T - DOT](#)
Cc: [DOT 13601100 STH 145-Grantosa-Leon](#); [Wood, Kevin](#); [Schowalter, Steven](#); [Hanna, Christine - DOT](#); [Ksontini, Najoua - DOT](#); [Pettit, Mary Beth](#)
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281
Date: Tuesday, October 30, 2018 10:25:50 AM
Attachments: [image001.png](#)
[image002.png](#)
[image003.png](#)

Roy

The memorandum has been revised as per discussions with Consultant.

Tony

From: Pettit, Mary Beth [mailto:marybeth.pettit@graef-usa.com]
Sent: Friday, October 26, 2018 2:05 PM
To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>; Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>
Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Schowalter, Steve <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>; Ksontini, Najoua - DOT <najoua.ksontini@dot.wi.gov>
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281

All,

Kevin and Tony have corresponded this week and the memorandum has been finalized and attached for your records.

Thank you to everyone for your help! We will incorporate the recommendation of the deck replacement with the conversion to semi-expansion abutments.

Thank you,
Mary Beth

From: Stollenwerk, Roy T - DOT [mailto:Roy.Stollenwerk@dot.wi.gov]
Sent: Tuesday, October 23, 2018 3:22 PM
To: Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>
Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Pettit, Mary Beth <marybeth.pettit@graef-usa.com>; Schowalter, Steven <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>; Ksontini, Najoua - DOT <najoua.ksontini@dot.wi.gov>
Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281

Tony,

Thanks for your review and concurrence.

Kevin and Mary Beth – Please respond to Tony’s comment regarding the LCC analysis for Alternatives 3 & 4 and resubmit is necessary. Thanks.

Roy Stollenwerk

30% Design Project Manager

Wisconsin Department of Transportation

PH: (262) 548-6474

From: Landini, Anthony P - DOT

Sent: Tuesday, October 23, 2018 12:43 PM

To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>

Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Pettit, Mary Beth <marybeth.pettit@graef-usa.com>; Schowalter, Steve <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>; Ksontini, Najoua - DOT <najoua.ksontini@dot.wi.gov>

Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa B-40-280/281

Roy

BOS concurs with recommended Alternative 1 – Re-deck and conversion to a semi-expansion abutments.

This is a nice report, but I believe there is a problem with the LCC analysis for Alternatives 3 & 4 that does not affect the recommendation. By adding the cost of a new bridge at year 75, which is the analysis period, the remaining service life of that new structure should be subtracted. If the Consultant agrees, I suggest the report be updated and resubmitted so we have the proper documentation.

Tony

From: Stollenwerk, Roy T - DOT

Sent: Tuesday, October 16, 2018 3:21 PM

To: Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>

Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>; Wood, Kevin <kevin.wood@graef-usa.com>; Pettit, Mary Beth <marybeth.pettit@graef-usa.com>; Schowalter, Steve <steven.schowalter@graef-usa.com>; Hanna, Christine - DOT <Christine.Hanna@dot.wi.gov>

Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Tony,

GRAEF has submitted the attached Bridge Alternative Life Cycle Cost Analysis for the Grantosa Drive bridges of STH 145, Bridges B-40-280 and B-40-281. Their conclusion is that Alternative 1 – Redeck and conversion to a semi-expansion abutment has the lowest first cost and lowest life cycle cost. Please review the analysis and comment on their recommendation of Alternative 1 as the preferred option.

Thanks, and let us know if you have any questions.

Roy Stollenwerk

30% Design Project Manager

Wisconsin Department of Transportation

PH: (262) 548-6474

From: Landini, Anthony P - DOT

Sent: Thursday, September 06, 2018 3:25 PM

To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>

Cc: Bonk, Aaron M - DOT <Aaron.Bonk@dot.wi.gov>; Shadewald, Laura - DOT <Laura.Shadewald@dot.wi.gov>

Subject: RE: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Roy

The scope for ii should be to convert both abutments to semi-expansion.

Aaron and Laura have been more involved in man hour estimates so one of them may be willing to provide comments on that portion.

Tony

From: Stollenwerk, Roy T - DOT

Sent: Thursday, September 06, 2018 1:55 PM

To: Landini, Anthony P - DOT <Anthony.Landini@dot.wi.gov>

Cc: DOT 13601100 STH 145-Grantosa-Leon <DOT13601100STH145-Grantosa-Leon@dot.wi.gov>

Subject: FW: I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Tony,

GRAEF has submitted the attached draft amendment for the alternative analysis for the Grantosa Drive abutments that are tipping. We would like to get the amendment going as soon as possible so

that we can keep the project design on schedule. Could you please review the scope of work to make sure it includes the information that BOS is looking for. Your opinion on the cost of the amendment would also be appreciated.

Thanks for your help.

Roy Stollenwerk

30% Design Project Manager
Wisconsin Department of Transportation
PH: (262) 548-6474

From: Pettit, Mary Beth [<mailto:marybeth.pettit@graef-usa.com>]
Sent: Friday, August 31, 2018 2:59 PM
To: Stollenwerk, Roy T - DOT <Roy.Stollenwerk@dot.wi.gov>
Cc: Schowalter, Steve <steven.schowalter@graef-usa.com>; Wood, Kevin <kevin.wood@graef-usa.com>
Subject: [WARNING: ATTACHMENT(S) MAY CONTAIN MALWARE]I.D. 1360-11-00 | STH 145 | Amendment for Alternatives Analysis at Grantosa

Roy,

Per our discussion earlier this week, please find attached a draft of the amendment for the study and memo preparation for the alternatives at Grantosa. Most importantly, we need to be sure the scope the way it is written on page 2 covers what you believe should be in the report. We can discuss next steps with this amendment once you have had a chance to review.

We are planning to complete this work in approximately 3 weeks.

Please feel free to call with questions\concerns.

Thank you!

Mary Beth Pettit, P.E.

Principal



One Honey Creek Corporate Center
125 South 84th Street, Suite 401
Milwaukee, WI 53214-1407

414 / 259 1500 office
414 / 266 9175 direct
414 / 467 8912 mobile
414 / 259 0037 fax

marybeth.pettit@graef-usa.com

www.graef-usa.com



GRAEF is the trade name of Graef-USA Inc.

This email and any attachments may contain confidential information to be used only by the intended recipient(s). If you are not the intended recipient of this email, you are expected to disregard the content, delete the email message, and notify the original sender.



Please consider the environment before printing this page.