Julie's comments in blue ...

Lance,

See my comments below in blue.

Julie Brooks, PE

1090-05-02/72 Rehab items (Consultant – Black) and (DOT-your comments-Red)- While reviewing the inspection reports for the subject bridges, in addition to polymer overlay, we notice that there are some maintenance recommendations that needs to be taken care off for 124^{Th} street bridge. These are :

- Remove loose concrete from bottom flanges of prestressed concrete girders. Fill existing cracks & spalled areas (some areas have exposed rebar and/or strands). Loose concrete around spalls should be removed and spalls patched using Concrete Surface Repair item. Don't include shallow spalls in webs since the patching material would probably just fall off. Cracks in the girders should be filled using the Epoxy Crack Injection item. (This crack filling would only be used on the girders not abutments or other reinforced concrete elements such as parapets.)
- 2. Repair failed patch at the pier (column 3) This would be done under the Concrete Surface Repair item.
- 3. Place AC curb at SW wing tip Could be done with milling and overlaying the approaches.
- 4. Repair approaches from settlement and drainage issues Since the approaches are settling, they should be milled and overlaid.
- 5. Seal approaches at paving blocks Could be included with milling and overlaying approach.
- 6. Patch and seal abutment cracks. Water seeping through north abutment between girders 1 & 2 at the diaphragm If the joint between the approach and the deck is properly sealed, water most likely would stop seeping through below. We usually don't bother with Epoxy Crack Filling of cracks in the abutments.
- 7. Patch and seal pier cap spalls and cracks Concrete Surface Repair item should be used for patching spalls and delams. Cracks typically aren't addressed in pier caps unless extremely wide.
- 8. Seal vertical cracks on concrete parapet at both inside and outside faces This is not needed, only use Concrete Surface Repair item for patching spalls and delams.
- 9. Patch spalled areas at wingwalls Use Concrete Surface Repair item for patching the spall.
- 10. Slope paving pulling away from abutments by 2-3". Top panels at SW corner of slope paving appear to be settling. Fix cracking at slope paving. Cracked panels could be replaced. The separation at the top could be filled with an epoxy filler.

We are wondering if Maintenance like to take care of these items as well. Yes We also, noticed a sudden drop in Inventory and Operating ratings from to 2014 inspection report (INV R=HS 24, OP R=HS 48) to 2016 inspection report (INV R= HS 19, OP R= HS 32). We looked at the DOT HSI system and we could not find any supporting calculations / documents or a reason(s) of why this drop. Will you please obtain any documentation from BOS that has these information. This information would be available from the BOS rating unit (Josh Dietsche's unit).

We find no other items in 116th St. Bridge that require immediate attention other than scoped. The approach sidewalks could be adjusted/replaced. They are settled at all 4 corners and this is a high pedestrian traffic area because of a school nearby. This work would be shown in roadway plans – not the structure plans.

From: Brooks, Julie - DOT
Sent: Friday, March 22, 2019 10:00 AM
To: Parve, Lance - DOT <Lance.Parve@dot.wi.gov>
Subject: RE: For your Review and Comments from Consultant - 1090-05-02/72 and 1090-35-00/70 I43 Rock Freeway Bridges: Rehab Items - feel free to further comment

Lance,

See my comments below in blue.

Julie Brooks, PE

From: Parve, Lance - DOT
Sent: Wednesday, March 13, 2019 4:26 PM
To: Brooks, Julie - DOT <<u>julie.brooks@dot.wi.gov</u>>
Subject: For your Review and Comments from Consultant - 1090-05-02/72 and 1090-35-00/70 I-43
Rock Freeway Bridges: Rehab Items - feel free to further comment

1090-05-02/72 Rehab items (Consultant – Black) and (DOT-your comments-Red)- While reviewing the inspection reports for the subject bridges, in addition to polymer overlay, we notice that there are some maintenance recommendations that needs to be taken care off for 124^{Th} street bridge. These are :

 Remove loose concrete from bottom flanges of prestressed concrete girders. Fill existing cracks & spalled areas (some areas have exposed rebar and/or strands). Loose concrete around spalls should be removed and spalls patched using Concrete Surface Repair item. Don't include shallow spalls in webs since the patching material would probably just fall off. Cracks in the girders should be filled using the Epoxy Crack Injection item. (This crack filling would only be used on the girders – not abutments or other reinforced concrete elements such as parapets.)

- 2. Repair failed patch at the pier (column 3) This would be done under the Concrete Surface Repair item.
- 3. Place AC curb at SW wing tip Could be done with milling and overlaying the approaches.
- 4. Repair approaches from settlement and drainage issues Since the approaches are settling, they should be milled and overlaid.
- 5. Seal approaches at paving blocks Could be included with milling and overlaying approach.
- 6. Patch and seal abutment cracks. Water seeping through north abutment between girders 1 & 2 at the diaphragm If the joint between the approach and the deck is properly sealed, water most likely would stop seeping through below. We usually don't bother with Epoxy Crack Filling of cracks in the abutments.
- 7. Patch and seal pier cap spalls and cracks Concrete Surface Repair item should be used for patching spalls and delams. Cracks typically aren't addressed in pier caps unless extremely wide.
- 8. Seal vertical cracks on concrete parapet at both inside and outside faces This is not needed, only use Concrete Surface Repair item for patching spalls and delams.
- 9. Patch spalled areas at wingwalls Use Concrete Surface Repair item for patching the spall.
- 10. Slope paving pulling away from abutments by 2-3". Top panels at SW corner of slope paving appear to be settling. Fix cracking at slope paving. Cracked panels could be replaced. The separation at the top could be filled with an epoxy filler.

We are wondering if Maintenance like to take care of these items as well. Yes We also, noticed a sudden drop in Inventory and Operating ratings from to 2014 inspection report (INV R=HS 24, OP R=HS 48) to 2016 inspection report (INV R= HS 19, OP R= HS 32). We looked at the DOT HSI system and we could not find any supporting calculations / documents or a reason(s) of why this drop. Will you please obtain any documentation from BOS that has these information. This information would be available from the BOS rating unit (Josh Dietsche's unit).

We find no other items in 116th St. Bridge that require immediate attention other than scoped. The approach sidewalks could be adjusted/replaced. They are settled at all 4 corners and this is a high pedestrian traffic area because of a school nearby. This work would be shown in roadway plans – not the structure plans.

<< File: B-40-0376_qty - Prelim.pdf >> << File: B-40-0377_qty - Prelim.pdf >>

1090-35-00/70 Rehab items (attached spreadsheet)

<< File: 10903570- IH43-RehabItems.xlsx >>

(Still Awaiting Info on 4 HNTB Bridges – B-40-111, B-40-112, B-40-296, and B-40-297)

Realize that B-40-293, B-40-294, B-40-295, B-40-296, and B-40-297 are past effective TPO 10=yr

dates for rehab

even though BOS is forwarding TPOs for these bridges. All these bridges were built in 2007 and 2008. They are past the 10-year limit for placing TPO's. I highly recommend removing them from the project. If they stay in the project, maybe the treatment could change to a methacrylate sealer instead to seal any cracks. This would be better than a TPO which has a higher probability of failing.



708 Heartland Trail, Suite 3000 Madison, WI 53717

608.826.3600 PHONE 608.826.3941 FAX

www.TRCsolutions.com

Bridge Asbestos Inspection Report

WisDOT Project ID: 1090-05-02 Structure Number: B-40-0377 Structure Name: 116th Street over IH 43 City/County: City of Greenfield, Milwaukee County Lat/Long Coordinates: 425726.4/ 880328.09 TRC Project Number: 258938.0000.0000 Date Inspected: June 21, 2016 Inspected By/License Number: John Roelke, All-119523

Findings:

The inspection to identify and collect samples of potential asbestos-containing material (ACM) was completed following WisDOT standard sampling procedure for bridge inspections found in FDM 21-35-45.

None of the materials that were identified as potentially ACM and sampled tested positive for asbestos. The overlay on the bridge can proceed as planned. Standard Special Provision (STSP) 107-125 should be included in the specifications.

Sample	Sample	Sample	Sample Analytical Results and		Quantity of ACM
Number	Description	Location	Method	No ACM	Material
1	Caulk	Abutment joint	PLM, non-detect	No ACM	0
2	Caulk	Abutment joint	PLM, non-detect	No ACM	
3	Caulk	Abutment joint	PLM, non-detect	No ACM	
4	Caulk	Parapet joint	PLM, non-detect	No ACM	0
5	Caulk	Parapet joint	PLM, non-detect	No ACM	
6	Caulk	Parapet joint	PLM, non-detect	No ACM	
7	Black paint	Pedestrian fence	PLM, non-detect	No ACM	0
8	Black paint	Pedestrian fence	PLM, non-detect	No ACM	
9	Black paint	Pedestrian fence	PLM, non-detect	No ACM	

Sample	Sample	Sample			Quantity of ACM
Number	Description	Location	Method	No ACM	Material
10	Caulk	Around pedestrian fence attachment plate	PLM, non-detect	No ACM	0
11	Caulk	Around pedestrian fence attachment plate	PLM, non-detect	No ACM	
12	Caulk	Around pedestrian fence attachment plate	PLM, non-detect	No ACM	
13	Caulk	Around bolts in fence attachment plate	PLM, non-detect	No ACM	0
14	Caulk	Around bolts in fence attachment plate	PLM, non-detect	No ACM	
15	Caulk	Around bolts in fence attachment plate	PLM, non-detect	No ACM	
16	Paint	Girder	PLM, non-detect	No ACM	0
17	Paint	Girder	PLM, non-detect	No ACM	
18	Paint	Girder	PLM, non-detect	No ACM	

If you have any questions, please contact me, at (608) 826-3628.

TRC Environmental Corporation

DanulHunk

Daniel Haak Project Manager


John Rollke W

John Roelke Asbestos Inspector

Attachments: Location Map, Photos, and Laboratory Report

Report Distribution:		
Recipient	Electronic (PDF) Copy	Paper Copy
BTS-ESS sharlene.tebeest@dot.wi.gov	X (via email)	Х
REC andrew.malsom@dot.wi.gov	X (via email)	
Project Manager <u>ashley.kiepczynski@dot.wi.gov</u>	X (via email)	
Other steven.ring@dot.wi.gov	X (via email)	

ID 1090-05-02/72 IH 43 Bridge Rehab



REGIONS

MILWAUKEE 40-SE

<u>B-40-0377</u>











Caulk in abutment joint



Caulk in parapet joint





Caulk around pedestrian fence attachment plate and around bolts in plate (did not observe any gaskets under plate)



Paint on girder



Black paint on pedestrian fence



Industrial Hygiene Laboratory 21 Griffin Road North Windsor, CT 06095 (860) 298-6308



BULK ASBESTOS ANALYSIS REPORT

Wisconsin Department of Transportation CLIENT:

Lab Log #:	0048472
Project #:	258938.0000.0000
Date Received:	06/28/2016
Date Analyzed:	06/29/2016

Site: DOT Bridge Inspection, B-40-377

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi- Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
B-40-377 (1)	Grey	Yes	No			ND	None
B-40-377 (2)	Grey	Yes	No			ND	None
B-40-377 (3)	Grey	Yes	No			ND	None
B-40-377 (4)	Grey	Yes	No			ND	None
B-40-377 (5)	Grey	Yes	No			ND	None
B-40-377 (6)	Grey	Yes	No			ND	None
B-40-377 (7)	Black	Yes	No			ND	None
B-40-377 (8)	Black	Yes	No			ND	None
B-40-377 (9)	Black	Yes	No			ND	None
B-40-377 (10)	Grey	Yes	No			ND	None
B-40-377 (11)	Grey	Yes	No			ND	None
B-40-377 (12)	Grey	Yes	No			ND	None
B-40-377 (13)	Grey	Yes	No			ND	None
B-40-377 (14)	Grey	Yes	No			ND	None
B-40-377 (15)	Grey	Yes	No			ND	None
B-40-377 (16)	Grey	Yes	No			ND	None
B-40-377 (17)	Grey	Yes	No			ND	None

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0 **RI #AAL-007** TX #300354 CO# AL-15020

AIHA-LAP,LLC #100122 CT #PH-0426 VT #AL014538 LA#05011 VA #3333 000283 PA#68-03387 PHIL# 461

ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV# LT000411 AZ #A20944

HI #L-09-004

NJ #CT004 CA #2907

Industrial Hygiene Laboratory 21 Griffin Road North Windsor, CT 06095 (860) 298-6308



Results you can rely on

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi- Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
B-40-377 (18)	Grey	Yes	No			ND	None

Reporting limit- asbestos present at 1%

ND - asbestos was not detected

Trace - asbestos was observed at level of less than 1%

NA/PS - Not Analyzed / Positive Stop

SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2016. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2016. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: <u>Kathleen Williamson, Laboratory Manager</u> Reviewed by: <u>Margaret Planagan</u> Margaret Flanagan, Approved Signatory

PHIL# 461

Date Issued 06/29/2016

NVLAP Lab Code 101424-0 TX #300354 RI#AAL-007 CO# AL-15020

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

AIHA-LAP,LLC #100122 CT #PH-0426 VT #AL014538 LA#05011 VA #3333 000283 PA#68-03387

AZ #A20944

ME LA-0075, LB-0071 MA #AA000052 HI #L-09-004

NY #10980 WV# LT000411 NJ #CT004 CA #2907



STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION

Inspection Report for B-40-377

S 116TH ST over IH 43 Apr 17,2018



Туре	Prior	Frequency (mos)	Performed
Routine	09-27-16	24	Х
Damage	08-10-05		
Interim	09-18-07	0	
SIA Review	09-27-16	48	
Vertical Clearance Measured	09-27-16	0	

Longitude

Start Coordinates Latitude 42°57'26.40"N End Coordinates (optional)

Longitude 88°03'28.09"W Owner STATE HIGHWAY DEPT

Maintainer STATE HIGHWAY DEPT

	Time Log		Team membe	ers		
	Hours 1	Minutes 30				
	Name		Number	Signature		Date
Inspector	Reay, Scott		2023	Scott Reay E-signed by Scott Reay(swreay)		06-21-18

page 2

Identification & Location Feature On: S 116TH ST Section Town Range: Structure Number: S30 T06N R21E **B-40-377** Feature Under: County: IH 43 MILWAUKEE Location Municipality Structure Name: 1.3M N JCT STH 24 GREENFIELD Traffic Geometry measurements in feet, except where noted Lanes ADT ADT year Traffic Pattern Approach Roadway Width: Bridge Roadway Width: Total Length: 36 On 2 1800 TWO WAY TRAFFIC 36.0 165.0 2011 Approach Pavement Width: 36 Deck Width: Deck Area (sq ft): Under 59400 50.0 8250 4 2015 TWO WAY TRAFFIC Capacity Load Rating Inventory rating: Overburden depth (in): Last rating date: Controlling 08-21-13 INTERIOR DECK GIRDER Moment HS24 0.0 Operating rating: Deck surface material: Re-rate for capacity (Y/N): Control location: HS40 CONCRETE 4.0 SPAN 1, 33.2 Posting: Re-rate notes: Classification **Hydraulic** Scour Critical Code(113): Q100 (ft3/sec): (N) NO WATERWÁY 0 High water elevation (ft): Velocity (ft/sec): Sufficiency #: 0.0 0.0 98.9 Span(s) Configuration DECK GIRDER Length (ft) 82.5 Span # Material Depth (in) Main CONT STEEL 36 1 Y CONT STEEL DECK GIRDER 36 82.5 2 Expansion joint(s) Temperature: File: New: Clearance File Measurement (ft) File Date New Measurement (ft) Item 27-Sep-2016 Highway Min Vertical Under Cardinal 16.03 Highway Min Vertical Under Non-Cardinal 16.12 27-Sep-2016 Horizontal Under Cardinal 54.7 Horizontal Under Non-Cardinal 54.5 Highway Min Vertical On Cardinal Horizontal On Cardinal **Special Components** Work Performed Component Year Note DECK - IOWA MIX 1992 **OVERLAY - CONCRETE Construction History** Work Performed FOS id Year 2010 NEW SUPERSTRUCTURE 1090-18-70 2005 **REPAIR/REPLACE WINGS** 2070-05-70 0077-02-34 2002 REPAIR SUPERSTRUCTURE 2000 REPAIR SUPERSTRUCTURE 0077-02-17 OVERLAY - CONCRETE 1090-04-73 1992

ADD PED FENCING

NEW STRUCTURE

1090-02-70

page 3

Maintenance Items History

Structure No.: B-40-377

Item	Recommended by	Status	Status change	Year completed
Approach - Mud Jacking	Maxwell, Steve (2022)	REJECTED	05/02/18	
Sidewalk approaches should be restored to flush	to prevent trips, slips and falls esp	ecially close to b	usy school zone.	Mudjack or
wedging could be likely alternatives for repair.				

Maintenance Items

Item	Priority	Recommended by	Status	Status change
Approach - Mud Jacking	MEDIUM	Reay, Scott (2023)	IDENTIFIED	05/02/18
Repair settled sidewalk approaches - near school	, high pedestrian	n traffic.		

Elements

ICII	nents						Quantity in Co	ndition State	
Chk	Element	Defect	Description	UOM	Total	1	2	3	4
			Reinforced Concrete Deck-Coated Reinforcing	SF	8,275	7,541	734	0	0
X	12								
_			Cracking (RC)	SF		532	734	0	0
		1130	Diagonal, HL to narrow cracks w/effl. at all 4 corne HI map crk s1 g2-3	ers, tran	is hl-narro	w crack w	ith efflores	cence sp	an 1
			Wearing Surface (Bare)	SF	5,940	5,420	520	0	0
	8000								
			Crack (Wearing Surface)	SF		0	520	0	0
		3220	hl-narrow transverse and longitudinal cracks, m	ore at e	ends and r	near center	r pier.		
			Steel Open Girder	LF	994	794	200	0	0
K	107		Spans 1 and 2 numbered from south to north. Gir	ders 1 t	hrough 6 n	umbered fr	om west to	east.	
-			Corrosion	LF		0	200	0	0
		1000	Spot rust areas on bottom flanges and at shippin	g/conta	inment at	tachment	ooints		•
			Painted Steel	SF	9,877	9,577	200	0	100
	8516								
			Effectiveness (Steel Protective Coatings)	SF		9,567	200	0	100
		3440	Some areas of rust on bottom flanges and at s	hipping	/containm	ent attach	ment poin	ts.	
_			Reinforced Concrete Column	EA	3	2	0	1	0
X	205								•
_			Delamination - Spall - Patched Area	EA		2	0	1	0
		1080	Small delamination w/exp rebar - W. Column near	Btm	•		- I		
			Reinforced Concrete Abutment	LF	97	75	22	0	0
X	215		Abutment ends were lengthened with 2010 supe	rstruct	ure constru	uction.	- I		•
_			Cracking (RC)	LF		0	22	0	0
		1130	HL-nrw vertical cracks w/ efflorescence.						
			Reinforced Concrete Cap	LF	42	30	6	6	0
Х	234								
			Delamination - Spall - Patched Area	LF		30	6	6	0
		1080	Top corners of cap spalled due to reconstruction	remova	ls.				

page 4

page	e 4							Structure No.:	B-40-377
			Reinforced Concrete Bridge Rail	LF	491	413	78	0	0
X	331		Scattered pop outs, especially at reveal edges	•					
			Cracking (RC)	LF		413	78	0	0
		1130	HL - narrow vertical cracks w/effl.						
			Integral Wingwall	EA	4	1	3	0	0
X	8400								
			Wall Movement	EA		0	3	0	0
		8902	SW tipped 1", caulk broken. NW tipped 1/2", ca movement, caulk missing.	aulk bro	oken. NE ca	aulk broke	en, 1/4" tip	. SE minim	al
			Wall Deterioration	EA		1	0	0	0
		8903	HL vert. cracks						

Assessments

							Quantity in Co	ondition State	
Chk	Element	Defect	Description	UOM	Total	1	2	3	4
			Drainage - Ends of Structure	EA	4	4	0	0	0
Х	9001		Curb & gutter all 4 corners, no inlets Both underdrain pipe discharges lack rodent scree	ns on no	orth approa	ch.			
			Sidewalk	EA	2	2	0	0	0
Х	9009		Few transverse cracks. Settlement between sid NW 1 1/8", SW 1 5/8", SE 1 3/8", NE 1"	ewalk ap	oproaches	and bridge:	s at all four	corners.	
			Slope Protection- Concrete	EA	2	0	2	0	0
Х	9042		S. Slope: Wide horizontal crack with hole at botto Several medium diagonal/ transverse cracks.	m and p	othole at D	OI fiber cr	ossing SW	top corner	; N. Sloj
			Steel Diaphragm	EA	45	45	0	0	0
Х	9167		Areas of spot rust generally confined to top and b	ottom of	diaphragn	าร.			
			Approach Roadway - Concrete (non-structural)		2	1	1	0	0
х	9322		Longitudinal and transverse joints sealed, tar pu cracked and settled, patched with ac sw corner between sidewalk approaches and bridges at a	r. Plow a	abrasion S	k, north an b lanes so	d south app outh approa	proaches. (ach. Settle	Sutter ement
			Protective Screening	EA	2	2	0	0	0
х			Black vinyl coated 1" mesh beginning to fade		-	-		•	U U

NBI Ratings

	File	New
Deck	7	7
Superstructure	U U	8
Substructure	8	8
Culvert	N	N
Channel	N	N
Waterway	N	N

page 5

Structure No.: B-40-377

Structure Specific Notes

Inspection Specific Notes

Inspector Site-Specific Safety Considerations

Structure Inspection Procedures Outside and inside shoulder wide enough to park in both NB and SB directions, barrier walls between shoulders and slopes. Parking lane on 116th and sidewalks for access to top.

Special Requirements

Chk

Hours

Comments


Cost

Routine Document Comment/Description

Roadway







Routine Document Comment/Description

Typical Underside













Routine Document Comment/Description South side of pier spalls






TOTAL ESTIMATED QUANTITIES


BID ITEMS	UNIT	SUPER.	SOUTH ABUT.	NORTH ABUT.	PIER	TOTALS
REMOVING OLD STRUCTURE STA. 20+96.57	LS					1
EXCAVATION FOR STRUCTURES BRIDGES B-40-377	LS					1
BACKFILL STRUCTURE	CY		300	300		600
CONCRETE MASONRY BRIDGES	CY	306	82	82	3	473
MASONRY ANCHORS TYPE L NO.5 BARS	EACH		102	102	42	246
PROTECTIVE SURFACE TREATMENT	SY	7 60				7 60
BAR STEEL REINFORCEMENT HS BRIDGES	LB		4310	4310		8620
BAR STEEL REINFORCEMENT HS COATED BRIDGES	LB	56,500	1745	1725	240	60,210
STRUCTURAL STEEL CARBON	LB	16,340				16,340
STRUCTURAL STEEL HS	LB	202,430				202,430
BEARING PADS ELASTOMERIC NON-LAMINATED	EACH		6	6		12
WELDED STUD SHEAR CONNECTORS 7/8X5-INCH	EACH	3420				3420
BEARING ASSEMBLIES FIXED B-40-377	EACH				6	6
CONCRETE SURFACE REPAIR	SF		30	20	5	55
RUBBERIZED MEMBRANE WATERPROOFING	SY		20	20		40
PIPE UNDERDRAIN 6-INCH	LF		90	90		180
PIPE UNDERDRAIN UNPERFORATED 6-INCH	LF		40	40		80
GEOTEXTILE FABRIC TYPE DF SCHEDULE A	SY		7 5	75		150
CONDUIT RIGID NONMETALLIC SCHEDULE 40 2-INCH	LF	510				510
JUNCTION BOXES 18X6X6-INCH	EACH	2				2
RAILING TUBULAR SCREENING B-40-377	LS					1
CONCRETE STAINING B-40-377	SF	3216				3216
PAINTING EPOXY SYSTEM B-40-377	LS					1
ROADWAY NAME PANEL STRUCTURE B-40-377	LS					1
NON-BID ITEMS						
PLASTIC OR ZINC PLATE	SF	14				14
FILLER	SIZE					1/2" & 3/4"



N0.	
244A	ALUM. C

8





1090-18-70

BILI	BILL OF BARS NOTE: THE FIRST OR FIRST TWO DIGITS OF THE BAR MARK SIGNIFIES THE BAR SIZE.											
BAR MARK	COAN	NO. REQ'D.	LENGTH	BENS	BAR SERIES	LOCATION						
503		158	11-4	Х	Δ	WINGS 1 & 2- FOOTING/WALL-B.FVERT.						
404		54	15-1	Х	Δ	WINGS 1 & 2- FOOTING/WALL-F.FVERT.						
405		12	38-8			WINGS 1 & 2- FOOTING-HORIZ.						
406		158	6-5			WINGS 1 & 2- FOOTING-TOP-HORIZ.						
507		4	8-3	Х		WINGS 1 & 2- WALL-F.F. & B.FVERT						
408		20	21-0			WINGS 1 & 2-WALL-HORIZ.						
410		8	39-6			WINGS 1 & 2-TOP HORIZ.						
411		80	3-9	Х		WINGS 1 & 2-TOP VERT.						
412		80	3-6	Х		WINGS 1 & 2-TOP VERT.						
513	Х	88	9-8	Х		WINGS 1 & 2-PARAPET VERT.						
414	Х	12	39-7			WINGS 1 & 2-PARAPET HORIZ.						


 ${\bf \Delta}$ length shown for bar is an average length and should only be used for bar weight calculations. See bar series table for actual lengths.





/ 10.5°

-A513; SEE PPT. SHEET FOR REINF. DETAILS PRIOR TO PLACING WING CONCRETE.




5'-2''


A404

BAR SERIES TABLE

	MARK	NO. REQD.	LENGTH			_
	A503	2 SERIES OF 79	10'- 7 '' T 12'-0''	0		
406	A404	2 SERIES OF 27	14'-4'' T 15'-9''	C		8
1	BUNDLE AN	D TAG EACH	SERIES SEP4	RATEL	_Y.	
405 7 N	D. DATE	PEVI	SION		BY	
	DEP	STATE OF ARTMENT OF	WISCONSIN TRANSPORTAT			
		TURE B-		, 1101		
			AWN BY WWR	PLANS CK'D.	IHG	
	SO. AE	BUTMEN ⁻	T SHE	ET 4		
	WING I	DETAILS				

3.0 SCALE






1090-18-70


<u>BILI</u>	BILL OF BARS NOTE: THE FIRST OR FIRST TWO DIGITS OF THE BAR MARK SIGNIFIES THE BAR SIZE.										
BAR MARK	COAN	NO. REQ'D.	LENGTH	BENZ	BAR SERIES	LOCATION					
3503		158	11-4	Х	Δ	WINGS 3 & 4- FOOTING/WALL-B.FVERT.					
3404		54	15-1	Х	Δ	WINGS 3 & 4- FOOTING/WALL-F.FVERT.					
3405		12	38-8			WINGS 3 & 4- FOOTING-HORIZ.					
3406		158	6-5			WINGS 3 & 4- FOOTING-TOP-HORIZ.					
3507		4	8-3	Х		WINGS 3 & 4- WALL-F.F. & B.FVERT					
3408		20	21-0			WINGS 3 & 4-WALL-HORIZ.					
3410		8	39-6			WINGS 3 & 4-TOP HORIZ.					
3411		80	3-9	Х		WINGS 3 & 4-TOP VERT.					
3412		80	3-6	Х		WINGS 3 & 4-TOP VERT.					
3513	Х	88	9-8	Х		WINGS 3 & 4-PARAPET VERT.					
3414	Х	12	39-7			WINGS 3 & 4-PARAPET HORIZ.					

▲ LENGTH SHOWN FOR BAR IS AN AVERAGE LENGTH AND SHOULD ONLY BE USED FOR BAR WEIGHT CALCULATIONS. SEE BAR SERIES TABLE FOR ACTUAL LENGTHS.










5'-2''

B404



	MARK	NO. REQD.	LENGTH		
	B503	2 SERIES OF 7 9	10'-8'' TO 12'-0''		
	B404	2 SERIES OF 2 7	14'-5'' TO 15'-9''		8
В	UNDLE AN	D TAG EACH	SERIES SEPARATEI	_Y.	


NO. DATE REVISION BY STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION STRUCTURE B-40-377 DRAWN WWR PLANSJHG 3.0 NO. ABUTMENT SHEET 6 SCALE WING DETAILS




8

STATE PROJECT NUMBER


R RK	C04>	NO. REQ'D.	LENGTH	BENS	BAR SERIES	LOCATION
01	Х	42	4-9	Х		PEDESTAL ANCHOR VERT.
2	Х	12	2-8			PEDESTAL HORIZ.G2 THRU G5
)4	Х	2	3-6			PEDESTAL HORIZ. G1 AND G6
)5	Х	2	7 -3	Х		PEDESTAL HORIZ. G1 AND G6








3.0 SCALE





☆TABLE	OF	FILLET
		SIZES

+ MIN. SIZE OF FILLET WELD
3⁄16''
1/4"
△ 5/16''
∆ ¾"
∆ 1⁄2"

	PLATE "C"			PLATE "D"			PLATE		NO. OF	LOCATION
0	'X'	'Y'	'Z'	۲X	'Y'	'Z'	TYPE	SIZE	BRG'S REQ'D.	LOCATION
	5"	1 ¹⁵ / ₁₆ ''	1'-4 /2''	1'-0''	2"	2'-1 /2''	Ι	1 /4" Φ	6	PIER - GIR.1 THRU 6
FIXE BEAR										

1090-18-70

BEARING NOTES

All bearings are symmetrical about \pounds of girder and \pounds of bearing.

ALL STRUCTURAL STEEL BEARING PLATES SHALL BE FLAT ROLLED STEEL PLATES WITH ALL SURFACES SMOOTH AND FREE FROM WARP AND ALL EDGES SMOOTH, STRAIGHT AND VERTICAL.

ALL PLATE CUTS SHALL BE MACHINE OR MACHINE FLAME CUTS.

ALL FINISHED SURFACES SHALL BE MACHINE FINISHED BY AN AUTOMATIC PROCESS.

CHAMFER ANCHOR BOLTS PRIOR TO THREADING. ANCHOR BOLTS SHALL BE THREADED 3". PROVIDE ONE STANDARD WROUGHT WASHER AND ONE HEX NUT PER BOLT. BOLT LENGTH TO BE 1'-5 FOR 1 $\frac{1}{4}$ " ϕ AND 1'-10 FOR $\frac{1}{2}$ " ϕ BOLTS. PROJECT ANCHOR BOLTS "D"PLATE THICKNESS +2 $\frac{1}{4}$ " ABOVE TOP OF CONCRETE.

CHAMFER TOP OF PINTLES ${\rm V_8}".$ DRILL HOLES FOR PINTLES IN ALL "D" PLATES FOR DRIVING FIT.

ALL MATERIAL INCLUDING SHIMS BUT EXCLUDING ANCHOR BOLTS, STAINLESS STEEL, TEFLON SURFACE, PINTLES, NUTS AND WASHERS SHALL BE MADE OF ASTM A709 GRADE 50W. STEEL PINTLES SHALL BE MADE OF ASTM A449 STEEL OR MATERIAL OF EQUAL YIELD STRENGTH & ELONGATION.

ANCHOR BOLTS, NUTS & WASHERS SHALL CONFORM TO ASTM A709 GRADE 36 OR MATERIAL OF EQUIV.STRENGTH & ELONGATION.

PROVIDE ${\rm V_{8}^{\prime\prime}}$ THICK BEARING PAD SAME SIZE AS PLATE "D" FOR EACH BEARING.


ALL MATERIAL IN BEARINGS, INCLUDING BEARING PADS & SHIM PLATES SHALL BE PAID FOR AT THE UNIT PRICE BID FOR "BEARING ASSEMBLIES FIXED B-40-377".


ANCHOR BOLTS, NUTS & WASHERS SHALL BE GALVANIZED IN ACCORDANCE WITH ASTM A153 CLASS C.

FIXED BEARINGS: PLATE "C" SHALL BE SHOP PAINTED WITH A WELDABLE PRIMER. PLATE "D" SHALL BE GALVANIZED.

* FINISH THESE SURFACES ANSI 250 FINISH IF 'Y' DIM. IS GREATER THAN 2".


N0.	DATE	REVISION				BY	
STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION							
STRUCTURE B-40-377							
			DRAWN BY	WWR	PLANS CK'D.	IHG	4 2 2 2 2 0
BEARING				SHEET 10			α -
DETAILS							






ABUTMENT DIAPHRAGMS @ DECK- STIRRUP - VERT BETWEEN GIRDERS
ABUTMENT DIAPHRAGMS @ SDWK STIRRUP - VERT ENDS
ABUTMENT DIAPHRAGMS - HORIZ.
CORBEL @ DECK - ABUTMENT DIAPHRAGMS - VERT.
CORBEL @ SDWK ABUTMENT DIAPHRAGMS - VERT.
CORBEL - ABUTMENT DIAPHRAGMS - HORIZ.
CORBEL - ABUTMENT DIAPHRAGMS - HORIZ.
ABUTMENT DIAPHRAGMS - HORIZ BETWEEN GIRDERS
ABUTMENT DIAPHRAGMS - HORIZ UNDER SDWK.
DECK - TOP & BOT TRANS.
DECK - BOT LONGIT.
DECK - TOP - LONGIT SPANS 1 & 2
DECK - TOP - LONGIT ABOVE PIER
DECK & SIDEWALK - TRANS VERT.
SIDEWALK - BOT TRANS HORIZ.
SIDEWALK - TOP - TRANS VERT.
SIDEWALK - LONGIT HORIZ.
PPT.A & SIDEWALK - TRANS VERT.
PPT.A - LONGIT HORIZ.
PPT.A - JUNCTION BOX - VERT.
PPT.A - JUNCTION BOX - VERT.








SECTION A-A




PLAN AT JUNCTION BOX









SCREENING