



STATE OF WISCONSIN
DEPARTMENT OF TRANSPORTATION

Inspection Report for
B-66-110

STH 144 over IH 41
Jul 26, 2018



Type	Prior	Frequency (mos)	Performed
Routine	11-16-16	24	X
SIA Review	11-14-14	48	X
Vertical Clearance Measured	11-16-16	0	X

Start Coordinates
Latitude
Longitude

End Coordinates (optional)
Latitude
Longitude

Owner

Maintainer

Time Log

Team members

Hours	Minutes	
1	15	Leah Barsch

Name	Number	Signature	Date
Inspector			
Zemke, Jason	2016	<i>Jason Zemke</i> E-signed by Jason Zemke(dot)jrz	09-04-18

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 2

Identification & Location

Feature On: STH 144	Section Town Range: S07 T10N R19E	Structure Number: B-66-110
Feature Under: IH 41	County: WASHINGTON	
Location 0.9 MI N JCT STH 175	Municipality: POLK	Structure Name:

Geometry

measurements in feet, except where noted

Approach Roadway Width: 62	Bridge Roadway Width: 62.5	Total Length: 217.2
Approach Pavement Width: 48	Deck Width: 78.3	Deck Area (sq ft): 17006

Traffic

	Lanes	ADT	ADT year	Traffic Pattern
On	2	5100	2016	TWO WAY TRAFFIC
Under	4	35100	2016	TWO WAY TRAFFIC

Capacity

Load Rating

Inventory rating: RF1.07	Overburden depth (in): 0.0	Last rating date:	Controlling:
Operating rating: RF1.39	Deck surface material: CONCRETE	Re-rate for capacity (Y/N):	Control location:
Posting:	Re-rate notes:		

Hydraulic

Classification

Scour Critical Code(113): (N) NO WATERWAY	Q100 (ft3/sec): 0	
High water elevation (ft): 0.0	Velocity (ft/sec): 0.0	Sufficiency #: 99.8

Span(s)

Span #	Material	Configuration	Depth (in)	Length (ft)	Main
1	PREST CONCRETE	DECK GIRDER		107.0	Y
2	PREST CONCRETE	DECK GIRDER		107.0	

Expansion joint(s)

Temperature:

File:	New:
-------	------

Clearance

Item	File Measurement (ft)	File Date	New Measurement (ft)
Highway Min Vertical Under Cardinal	17.55	16-Nov-2016	
Highway Min Vertical Under Non-Cardinal	18.52	16-Nov-2016	
Horizontal Under Cardinal	72.4		
Horizontal Under Non-Cardinal	72.7		
Highway Min Vertical On Cardinal			
Horizontal On Cardinal			

Construction History

Year	Work Performed	FOS id
2014	NEW STRUCTURE	1107-02-79

Maintenance Items History

Item	Recommended by	Status	Status change	Year completed
Approach - Seal Approach to Paving Block	Zemke, Jason (2016)	COMPLETE	08/11/16	2015
Work completed per 2015 annual summary.				
Misc - Remove Vegetation (Spray)	Barsch, Leah (2021)	COMPLETE	02/13/17	2016
Deck - Seal Surface Cracks	Barsch, Leah (2021)	COMPLETE	02/14/17	2016
Used Epoxy				
Deck - Clean and Sweep Deck/Drains	Barsch, Leah (2021)	COMPLETE	03/02/17	2016

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 3

Structure No.: **B-66-110**

Deck - Clean and Sweep Deck/Drains	Barsch, Leah (2021)	COMPLETE	04/18/18	2017

Maintenance Items

Item	Priority	Recommended by	Status	Status change
IMP-Thin Epoxy Overlay	HIGH	Zemke, Jason (2016)	IDENTIFIED	01/26/17
2022- Recommend thin polymer overlay prior to 2024. Fairly extensive cracking in deck after 2 years.				
Drainage - Repair Washouts / Erosion	HIGH	Zemke, Jason (2016)	IDENTIFIED	01/26/17
Fill in undermining at SE corner and grade to top of pavement. Also - repair erosion ruts beyond flume in RT shoulder at NE wing. Pave with HMA or place compacted millings.				
IMP-Concrete Overlay	LOW	Zemke, Jason (2016)	IDENTIFIED	01/26/17
2039- Recommend concrete OL				
Slope Protection - Reseal Slope Paving	LOW	Zemke, Jason (2016)	IDENTIFIED	07/31/18
Recommend re-sealing the concrete slope paving above the retaining wall.				
Approach - Seal Approach to Paving Block	LOW	Zemke, Jason (2016)	IDENTIFIED	08/30/18
Re-seal deck joints.				

Elements

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	12		Reinforced Concrete Deck-Coated Reinforcing	SF	17,166	16,526	640	0	0
		1080	Delamination - Spall - Patched Area Small area of honeycombing patched with mortar in span 2 at bay at median.	SF		0	2	0	0
		1130	Cracking (RC) Typical HL transverse Cracks w/Efflorescence. A few HL diag. cracks near corners of deck with efflorescence.	SF		0	638	0	0
	8000		Wearing Surface (Bare) No IR data available.	SF	13,567	10,100	3,392	75	0
		3220	Crack (Wearing Surface) Many HL and narrow transverse cracks, some HL and narrow diagonal and longit cracks at deck ends, a few longit cracks over pier, extensive transverse cracking over pier, many cracks sealed with epoxy. A few medium diagonal cracks at N end of deck at NB and SB side and some transverse at pier.	SF		3,392	3,392	75	0
X	109		Prestressed Concrete Open Girder Girders numbered 1-9 from W-E.	LF	1,933	1,905	25	3	0
		1110	Cracking (PSC) N. Abut east face of girders: NRW diagonal crack at top flange, G2 2_LF (west face), Med at G5 1_LF (both sides), NRW at G6 2_LF & NRW at G9 2_LF. Horizontal NRW crack at top of web, G1 3_LF & G4 1_LF. S. Abut west face of girders: NRW diagonal crack at top flange, G6 2_LF, G7 2_LF & Med at G5 2_LF. Horizontal NRW crack at top of web, G2 1_LF, G3 2_LF, G4 2_LF, G8 2_LF, G9 4_LF.	LF		0	25	3	0
X	205		Reinforced Concrete Column	EA	6	5	1	0	0
		1080	Delamination - Spall - Patched Area Column 6 , on right looking north , has small spalls from semi truck and trailer crash on 6-8-17	EA		0	1	0	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 4

Structure No.: **B-66-110**

X	215		Reinforced Concrete Abutment	LF	198	177	18	3	0
			Some leakage through sill joints. Several mortar rubs/small patches in corners of abutment diaphragms from construction.						
		1080	Delamination - Spall - Patched Area	LF		5	15	3	0
			Small spalls at corners of beam seats (no chamfer strip) (15_LF CS2). Concrete patches at top flanges (5_LF CS1). N. abut - small spall at W end at corner of end diaph (1_LF CS3). S. Abut - CS3 spall/failed patches at top flange on the west side of G1 & G4.						
		1130	Cracking (RC)	LF		9	3	0	0
			S-few HL vertical cracks; HL vertical cracks at W end with stains and effl. N-few HL/nrw vertical and diag cracks.						
X	234		Reinforced Concrete Cap	LF	98	97	1	0	0
		1080	Delamination - Spall - Patched Area	LF		0	1	0	0
			South end of pier cap has small spall from semi truck and trailer crash on 6-8-17.						
X	331		Reinforced Concrete Bridge Rail	LF	522	452	70	0	0
		1080	Delamination - Spall - Patched Area	LF		0	2	0	0
			E: Small delams at face of barrier at middle of bridge expansion joint, small delam under fence post connection plate near middle of bridge.						
		1130	Cracking (RC)	LF		250	68	0	0
			W Rail: HL Vertical Cracks entire rail, scattered NRW vertical cracks. E Rail: HL & Narrow Vertical Cracks.						
X	8400		Integral Wingwall	EA	4	4	0	0	0
			No defects noted at all 4 wings						

Assessments

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
			Drainage - Ends of Structure	EA	4	1	2	3	4
X	9001		Riprap behind all 4 wings to bottom of slope along retaining walls. NE-concrete curb and gutter to HMA flume and riprap down slope. SE-fill low 1' at end of wing, undermining of sidewalk slab initiated. SW-small HMA flume sunk or placed 6" low, no erosion. NW-C&G to HMA flume, settled at edge of barrier max 1".						
X	9007		Median	EA	1	1	0	0	0
			A few HL & NRW transverse cracks and plow abrasion and edges.						
X	9009		Sidewalk	EA	1	1	0	0	0
			Located on East side of bridge - a few HL to NRW transverse cracks at pier sealed with epoxy; a few minor chips at curb face.						
X	9010		Aesthetic Treatments	EA	1	1	0	0	0
			Girders painted gray. Pier columns have archit. details/rustification.						
X	9030		Signs - Object Markers	EA	2	2	0	0	0
			Tiger boards installed at SE/NW.						
X	9042		Slope Protection- Concrete	EA	2	0	2	0	0
			N-dip at bay 2 from S - has settled 4" with a NRW crack at the low point. S- 1 1/2" settlement at the East end of the abutment, med size crack 1" East from middle joint of the slope paving, east side of crack starting to settle.						

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 5

Structure No.: **B-66-110**

X	9167	Steel Diaphragm Galvanized	EA	32	32	0	0	0
X	9168	Concrete Diaphragm Located at pier. No defects.	EA	8	8	0	0	0
X	9322	Approach Roadway - Concrete (non-structural) All deck joints sealed. SE- good condition, C&G at RT side cracked, settled 1/2", low spot with ponding. (CS2) SW- RT shoulder has several longit/diag cracks sealed with epoxy and tar; small shallow spall/gouge in through lane, 3rd slab from deck at RT shoulder down 1/2" at RT side. NE- HMA at roadway end of approach is low 1/2". NW- Several Rt shoulder cracks sealed with epoxy and tar, HMA at roadway end of approach is 1/2" low in the through lane.	EA	4	3	1	0	0
X	9337	Protective Screening Located on E Rail: 4'-6" Ornamental Protective Screening w/2" CL Fabric, w/Duplex Coating System. Top Coat is Black. Galvanized connection hardware.	EA	1	1	0	0	0

NBI Ratings

	File	New
Deck	8	8
Superstructure	9	7
Substructure	8	8
Culvert	N	N
Channel	N	N
Waterway	N	N

Structure Specific Notes

Cardinal VC Measured @ Lt Edge of HMA shoulder @ G9=17.55'; Non-Cardinal VC Measured @ Rt Edge of Lane 2 @ G9=18.52'.
 Note: orientation of structure elements is north and south abutments and east and west parapets.
 R-66-35 located at N abutment.
 R-66-34 located at S abutment.

Inspection Specific Notes

Inspector Site-Specific Safety Considerations

Structure Inspection Procedures

Parked on NB right shoulder for topside inspection.
Parked on both NB and SB IH 41 right shoulders for underdeck inspection.

Special Requirements

Chk Hours Cost Comments

Routine

Document Comment/Description

East elevation view looking NW along NB 41.



Routine
Document Comment/Description

Roadway looking north.



Routine**Document Comment/Description**

Extensive HL transverse cracking, with some longit. and diagonal cracks near deck ends. Many cracks sealed with epoxy. Pictured at SB lanes over pier.



7/26/18, 12:31 PM

Routine**Document Comment/Description**

Typical medium transverse crack in wearing surface at pier. Medium diagonal crks also near ends of deck.



Routine

Document Comment/Description

Ponding at curb line at SE approach.



Routine**Document Comment/Description**

SW approach - RT shoulder has several longit./diag. cracks sealed with epoxy and tar. (Unchanged 2018)



Routine

Document Comment/Description

SE corner undermining of sidewalk slab.



Routine**Document Comment/Description**

Typical riprap treatment behind all 4 wings along abutment retaining walls. Pic at NE wing.
(Unchanged 2018)



Routine

Document Comment/Description

Small spall at N abut at west end.



Routine
Document Comment/Description

Typical condition of West rail.



Routine

Document Comment/Description

North span (span 2) girders and soffit. (Unchanged 2018)



Routine

Document Comment/Description

N. Slope paving, looking at North abutment. Settled 5 inches.



Routine

Document Comment/Description

Typical mortar rub at abutment diaphragms.



Routine

Document Comment/Description

Typical CS3 diagonal crack in the top flange. Girder 5 S. abut pictured.



Routine

Document Comment/Description

S. slope paving looking west, Note medium crack just east of the joint.



Routine


Document Comment/Description

Small spalls at east column and east end of pier cap from 2017 traffic impact.




Vertical Clearance Verification
Document Comment/Description

NonCardinal Min Vc (SB 41) = 18.52' at G9 over RT edge L2.



Vertical Clearance Verification
Document Comment/Description

Cardinal Min Vc (NB 41) = 17.55' at G9 over LT edge LT shoulder.



STRUCTURE INVENTORY AND APPRAISAL FIELD REVIEW FORM

B-66-110
STH 144 over IH 41

LOCATION

(3) Municipality:
 (16) Latitude(° ' "):
 (17) Longitude(° ' "):

POLK
43°20'49.69"N
88°16'55.89"W

TRAFFIC SERVICE

(28A) Lanes On:
 (28B) Lanes Under:
 (102) Traffic Pattern On:
 (102) Traffic Pattern Under:
 (19) Detour Length(mi):

2
4
-NO TRAFFIC -ONE WAY TRAFFIC <input checked="" type="checkbox"/> TWO WAY TRAFFIC
-NO TRAFFIC -ONE WAY TRAFFIC <input checked="" type="checkbox"/> TWO WAY TRAFFIC
1

GEOMETRY

(49) Structure Length(ft):
 (50) Sidewalk Width(ft):
 (50) Curb Width(ft):
 (52) Culvert Barrel Length(ft):
 (34) Skew:
 (51) Bridge Roadway Width(ft):
 (52) Deck Width(ft):
 Right Wingwall Length(ft):
 Left Wingwall Length(ft):
 (32) Approach Roadway Width(ft):
 (47) Minimum Horizontal(ft):
 (55) Minimum Right Lateral(ft):
 (56) Minimum Left Lateral(ft):

217.2	
Left: 0.0	Right: 8.0
0.0	
Angle(°): 38	Direction: -RIGHT FORWARD <input checked="" type="checkbox"/> LEFT FORWARD
Cardinal	Non-Cardinal
62.5	62.5
78.3	78.3
20.0	20.0
23.2	24.0
62	0
Cardinal Under Clearance	Non-Cardinal Under Clearance
72.4	72.7
31.1	30.5
23.3	23.4

RAILING APPRAISAL

(36A) Bridge Rail Adequacy:
 (36B) Transition Adequacy:
 (36C) Approach Guardrail Adequacy:
 (36D) Guardrail Termination Adequacy:
 Outer Rail:

-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> STANDARD -NOT APPLICABLE		
Left	Right	Type
		TYPE F (TWO SQUARE TUBES) - STEEL(8)
		TYPE F (3 SQUARE TUBES) - STEEL(65)
		TYPE F (4 SQUARE TUBES) - STEEL(72)
		TYPE M-STEEL 3 SQUARE TUBES(93)
X		SLOPED FACE PARAPET LF(91)
		SLOPED FACE PARAPET HF(92)
	X	VERTICAL FACE PARAPET TYPE A(74)
		TYPE W-THRIE BEAM(79)
		TYPE H ON VERTICAL PARAPET(80)
		TIMBER(38)
		OTHER(99) (Please specify)
	CONT GUARD RAIL	
	NO APP GRDRL	
	NO ATTACHMENT	
5	22 MM(7/8") BOLT (Please enter quantity)	
	25 MM(1") BOLT (Please enter quantity)	
	OTHER (Please specify)	
X	(01) ENERGY ABSORBING TERMINAL/EAT	
	(02) TURN DOWN	
	(99) OTHER (Please specify)	

ROADWAY ALIGNMENT APPRAISAL

(72) Approach Alignment Appraisal:

	3 Intolerable- Substantial speed reduction
	6 Fair- Minor speed reduction
X	8 Good- No speed reduction