

## **Bridge Asbestos Inspection Report**

WisDOT Project ID: 1090-35-00 Structure Number: B-67-0113 Structure Name: CTH Y over IH 43

City/County: City of New Berlin, Waukesha County Lat/Long Coordinates: 425559.06/880931.33 TRC Project Number: 258937.0000.0000

Date Inspected: June 14, 2016

Inspected By/License Number: John Roelke, All-119523

## Findings:

The inspection to identify and collect samples of potential asbestos-containing material (ACM) was completed following WisDOT standard sampling procedure for bridge inspections found in FDM 21-35-45.

None of the materials that were identified as potentially ACM and sampled tested positive for asbestos. The overlay on the bridge can proceed as planned. Standard Special Provision (STSP) 107-125 should be included in the specifications.

Sample	Sample	Sample	Analytical Results	Friable/ Non-friable or	Quantity of ACM
Number	Description	Location	and Method	No ACM	Material
1	Green paint	Girder	PLM, non-detect	No ACM	0
2	Green paint	Girder	PLM, non-detect	No ACM	
3	Green paint	Girder	PLM, non-detect	No ACM	

Sample	Sample	Sample	Analytical Results	Friable/ Non-friable or	Quantity of ACM
Number	Description	Location	and Method	No ACM	Material
4	Caulk	Around fence attachment plates on parapet	PLM, non-detect	No ACM	0
5	Caulk	i i		No ACM	
6	Caulk	Around fence attachment plates on parapet	PLM, non-detect	No ACM	
7	Caulk	Parapet expansion joint	PLM, non-detect	No ACM	0
8	,		PLM, non-detect	No ACM	
9	Caulk	Parapet expansion joint	PLM, non-detect	No ACM	

If you have any questions, please contact me, at (608) 826-3628.

TRC Environmental Corporation

Daniel Haak Project Manager

Danul Hank

John Roelke Asbestos Inspector

John Rocke w

Attachments: Location Map, Photos, and Laboratory Report

## Report Distribution:

Recipient	Electronic (PDF) Copy	Paper Copy
BTS-ESS sharlene.tebeest@dot.wi.gov	X (via email)	Χ
REC <u>Andrew.malsom@dot.wi.gov</u>	X (via email)	
Project Manager ashley.kiepczynski@dot.wi.gov	X (via email)	
Other steven.ring@dot.wi.gov	X (via email)	



## ID 1090-35-00/70 IH 43 Bridge Rehab WASHINGTON CO. WASHINGTON CO. DODGE CO. T-8-N T-7-N T-7-N Summit, ES T-6-N|<sub>R-19-E</sub> R-18-E WALWORTH CO. RACINE CO. 2,450,000 MILES OF HIGHWAY as of Dec. 31, 2013 CIVIL TOWNS **LEGEND** OTHER ROADS.... TOTAL FOR COUNTY...... 3062 Public Hunt. or Fish. Grds. ..... REGIONS Public Camp & Picnic Grds. ........ Ranger Station \_\_\_\_\_\_\_\_ WAUKESHA CO. SECTION NUMBERING OF A TOWNSHIP **18** County Park .....With Facilities ..... DEPARTMENT OF TRANSPORTATION STATE OFFICE BUILDING 6 5 4 3 2 1 Madison, Wisconsin County Highway Letter ..... T Rest Area ......Modern Facilities ..... 🛦 For boundaries of public hunting and fishing grounds 8 9 10 11 12 2 ■ MILES 18 17 16 15 14 13

19 20 21 22 23 24

30 29 28 27 26 25

31 32 33 34 35 36

Public hunting and fishing grounds not shown

- Grid based on the state plane coordinate system south zone and the NAD 27

Corrected for

JAN. 2016

Base compiled from U.S.G.S. Quadrangles

WAUKESHA 67-SE

County Boundary ..... Ethan Allen School ..... 1

Civil Town Boundary ... \_ \_ \_ \_ Univ. of Wisconsin - Waukesha ..... 2

## B-67-0113













Paint on girder



Caulk around pedestrian fence attachment plates on parapet (did not observe any gaskets under plate)





No suspect materials under/around light/sign pole



Caulk in parapet expansion joint



Industrial Hygiene Laboratory 21 Griffin Road North Windsor, CT 06095 (860) 298-6308



## **BULK ASBESTOS ANALYSIS REPORT**

CLIENT: Wisconsin Department of Transportation

Lab Log #:

0048319

Project #:

258937.0000.0000

Date Received:

06/16/2016

Date Analyzed:

06/16/2016

Site:

DOT Bridge Inspection, B-67-113

## POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi- Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
B-67-113 (1)	Green	Yes	No			ND	None
B-67-113 (2)	Green	Yes	No			ND	None
B-67-113 (3)	Green	Yes	No			ND	None
B-67-113 (4)	Grey	Yes	No			ND	None
B-67-113 (5)	Grey	Yes	No			ND	None
B-67-113 (6)	Grey	Yes	No			ND	None
B-67-113 (7)	Grey	Yes	No			ND	None
B-67-113 (8)	Grey	Yes	No			ND	None
B-67-113 (9)	Grey	Yes	No			ND	None

Industrial Hygiene Laboratory 21 Griffin Road North Windsor, CT 06095 (860) 298-6308



## POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

			Multi-	Layer No.	Other Matrix	Asbestos	Asbestos
Sample No.	Color	Homogenous	Layered		Materials	%	Type

Reporting limit- asbestos present at 1%

ND - asbestos was not detected

Trace - asbestos was observed at level of less than 1%

NA/PS - Not Analyzed / Positive Stop

SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2016. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2016. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by:

Date Issued

een Williamson, Laboratory Manager

Reviewed by:

Margaret Flanagan, Approved Signatory

Margaret Flanagan, Approved Signatory

06/16/2016



## Inspection Report for B-67-113

## CTH Y (RACINE AVE) over IH 43 Sep 04,2018



Type	Prior	Frequency (mos)	Performed
Routine	11-28-17	12	X
Interim	08-11-08	0	
SIA Review	11-23-15	48	
Vertical Clearance Measured	11-28-17	0	X

Start Coordinates

Latitude 42°55'59.06"N

Longitude 88°09'31.33"W

Cowner STATE HIGHWAY DEPT

Time Log

Toam members

Time Log		Team members
Hours 2	Minutes 45	Leah Barsch

Nan	ne	Number	Signature	Signature Date
Inspector			Jason Zemke	
Zei	mke, Jason	2016	E-signed by Jason Zemke(dotjrz)	01-07-19

## page 2

## **Identification & Location**

Feature On: CTH Y (RACINE AVE)	Section Town Range: S32 T06N R20E	Structure Number:
Feature Under: IH 43	County: WAUKESHA	B-67-113
Location 0.2M N JCT CTH HH	Municipality: NEW BERLIN	Structure Name:

Geometry Traffic

measurements in feet, except where noted				Lanes	ADT	ADT year	Traffic Pattern
Approach Roadway Width: 79	Bridge Roadway Width: 78.5	Total Length: 214.0	On	4	17100	2015	TWO WAY TRAFFIC
Approach Pavement Width: 102	Deck Width: 106.5	Deck Area (sq ft): 22791	Under	4	62700	2018	TWO WAY TRAFFIC

Capacity Load Rating

Inventory rating: HS16	Overburden depth (in): 0.0	Last rating date: 07-08-13	Controlling: INTERIOR DECK GIRDER Moment
Operating rating: HS26	Deck surface material: CONCRETE		Control location: 6.2 SPAN 2, 66.5
Posting:	Re-rate notes:		

**Hydraulic** Classification

	Scour Critical Code(113):	Q100 (ft3/sec):	
	(N) NO WATERWAY	0	
ı	High water elevation (ft):	Velocity (ft/sec):	Sufficiency #:
	0.0	0.0	84.1

Span(s)

Span #	Material	Configuration	Depth (in)	Length (ft)	Main	
1	CONT STEEL	DECK GIRDER		101.5		
2	CONT STEEL	DECK GIRDER		108.0	Y	1

Expansion jo	oint(s)		Temperature:	File:	New:88
Joint #	Location	Type	Last inspection date	Last measure (in)	New measure (in)
1	NORTH ABUTMENT	STRIPSEAL	11-28-17	1.5	0.5
2	SOUTH ABUTMENT	STRIPSEAL	11-28-17	1.3	1.0

## Clearance

Item	File Measurement (ft)	File Date	New Measurement (ft)
Highway Min Vertical Under Cardinal	16.29	28-Nov-2017	16.3
Highway Min Vertical Under Non-Cardinal	18.51	28-Nov-2017	18.47
Horizontal Under Cardinal	65.43		
Horizontal Under Non-Cardinal	63.42		
Highway Min Vertical On Cardinal			
Horizontal On Cardinal			

**Special Components** 

Component	Year	Work Performed	Note
CONC. PROTECTIVE			APPLIED IN 2014 MAINTENANCE PROJECT
TREATMENT - TK-590-1 MS			

**Construction History** 

Year	Work Performed	FOS id
2018	REPAIR SUPERSTRUCTURE	0077-12-28
2009	PAINTING	1090-22-70
2009	RAISE STRUCTURE	1090-22-70
2009	NEW BEARINGS	1090-22-70
2009	NEW DECK	1090-22-70
1998	PAINTING	1091-01-63
1984	OVERLAY - CONCRETE	0067-34-11
1969	NEW STRUCTURE	1092-03-77

page 3 Structure No.:B-67-113

## **Maintenance Items History**

Item	Recommended by	Status	Status change	Year completed
Misc - Follow Up	Zemke, Jason (2016)	COMPLETE	06/06/18	2018
Critical findings report for damage to G1 fr shoulder closed restriction on bridge.	om vehicle impact 12/1/17. Repair/re	placement of G1 in S	Span 1 required t	o remove
Superstructure - Heat Straighten	Zemke, Jason (2016)	COMPLETE	06/27/18	2018
Work completed May 2018 from Dec 2017	vehicle damage.			
IMP-Thin Epoxy Overlay	Zippel, William J (9605)	REJECTED	11/28/17	
Recommend thin epoxy overlay 2016.	<u> </u>			
Deck - Seal w/ Concrete Sealer	Wittrock, Jon (9613)	COMPLETE		2014
UPLOADED ON 4/28/2015 FROM EXCEL SPECIFIC PRODUCT	SHEET COMPILED BY ALLAN JOH	INSON. SEE SPECI	AL COMPONEN	T TAB FOR

## **Maintenance Items**

Item	Priority	Recommended by	Status	Status change
Drainage - Repair/Replace Deck Drains	HIGH	Zemke, Jason (2016)	IDENTIFIED	01/04/19
Inlet at NE corner at outside shoulder (not deck dalso tuckpoint outside inlet at SE quad.	rain) - tuckpoint	below casting at adjustment rings.	Roadway base co	ourse visible;
Substructure - Other Work	MEDIUM	Zemke, Jason (2016)	IDENTIFIED	10/09/18
Recommend sealing vertical medium and wide cr	acks at both ab	utments.		
Misc - Other Work	MEDIUM	Zemke, Jason (2016)	IDENTIFIED	10/09/18
Recommend monitoring cracking in top cap of pie	r for growth or	widening.		
Approach - Seal Joint along Parapet/Wing	MEDIUM	Zemke, Jason (2016)	IDENTIFIED	01/04/19
Clean and seal parapet/sidewalk joints at NE and	SE quadrants.			
Expansion Joints - Clean	LOW	Zippel, William J (9605)	IDENTIFIED	01/07/16
Clean out expansion joints.				
IMP-Concrete Overlay	LOW	Zippel, William J (9605)	IDENTIFIED	01/07/16
2034-Recommend concrete overlay.				
Approach - Seal Approach to Paving Block	LOW	Zippel, William J (9605)	IDENTIFIED	01/07/16
Reseal approaches at headers.				
Misc - Remove Vegetation (Spray)	LOW	Zemke, Jason (2016)	IDENTIFIED	10/09/18
Spray slope paving to remove vines, particularly a	t W end of S sl	ope. Also kill weed overgrowth at ri	prap flumes at all	4 quadrants.

page 4 Structure No.:B-67-113

## **Elements**

							Quantity in C	ondition State	
k	Element	Defect	Description	UOM	Total	1	2	3	4
(	12		Reinforced Concrete Deck-Coated Reinforcing	SF	22,928	21,614	1,314	0	0
			Delamination - Spall - Patched Area	SF		0	3	0	Ι 0
		1080	Patch at concrete deck thickening at Bay 5 at s Mortar rubs at soffit at Bay 1 over N slope.		outment (3	SF CS2).		1 -	
-			Cracking (RC)	SF		0	1,311	0	0
		1130	Transverse HL to narrow cracks with efflorescence the west overhang, and in bay 6 between NB/SB				especially	in bay 5 ar	ıd under
ł			Wearing Surface (Bare)	SF	16,373	14,073	2,300	0	0
	8000		No IR since 2009 re-deck. Some poor finishing, with surface not closed up	at NB	side near l	N end of d		1	1
		3220	Crack (Wearing Surface) Few longitudinal narrow cracks over pier. Typica deck ends. Few scattered HL random cracks. C	SF I HL/Nrv racks a	w transver re wider at	420 se cracks outside s	2,300 at pier. Nr houlders.	0 rw longit.	0 cracks
T			Steel Open Girder	LF	2,526	2,089	436	1	0
(	107		Girders are numbered 1-12 west to east.  Note: G1 Span 1 over NB I-43 heat straightened	2018 aı	nd repainte	ed.			
1			Corrosion	LF		0	373	0	0
		1000	S Span: <b>Some areas with</b> Lt edge rust bot flange bearings. Scattered rust bottom flange over SB rdv	0-10 ft vy <b>. Som</b>	rom S. abu e heavier i	it. Some i	ignt end ru	ust over ab	utment
			N Span: Small areas of freckled rust at girder ends	ánd blu	sh rust ove	r pier bear	ings.	ND.	
			N Span: Small areas of freckled rust at girder ends  Cracking	and blu LF	sh rust ove	r pier beari 0	ings.	1	0 s includ
-		1010	N Span: Small areas of freckled rust at girder ends	LF o web a t 2nd in betwee ction - h jular ho	t several c term. diap en 2nd and oriz. crk n le with 0.5	oliaphragm h connect I 3rd internear btm fla radius co	ings.  4 s. 2018 re ion - horiz n. diaph - ange to we orners and	1 epair plans c crack ne horiz crk eb weld m d bolted o	ar btm near bt ouseho ver, sho
-		1010	N Span: Small areas of freckled rust at girder ends  Cracking  Traffic impact from 12/1/2017 resulted in tears t bolted repairs and crack arresting/grinding. G1a flange to web weld mouseholed at each end; G1 weld ground out; G1 at 3rd interm. diaph conne at each end, large tear in web cut out to rectang diagonal crack in stiffener plate through old dia clearance to web [1' CS3].	LF o web a t 2nd in betwee ction - h jular ho	t several c term. diap en 2nd and oriz. crk n le with 0.5	oliaphragm h connect I 3rd internear btm fla radius co	ings.  4 s. 2018 re ion - horiz n. diaph - ange to we orners and	1 epair plans c crack ne horiz crk eb weld m d bolted o	ar btm near bt ousehover, sho
-		1010	N Span: Small areas of freckled rust at girder ends  Cracking  Traffic impact from 12/1/2017 resulted in tears t bolted repairs and crack arresting/grinding. G1a flange to web weld mouseholed at each end; G1 weld ground out; G1 at 3rd interm. diaph conne at each end, large tear in web cut out to rectang diagonal crack in stiffener plate through old dia	LF o web a t 2nd in betwee ction - h jular ho ph bolt  LF esulted	t several c term. diap en 2nd and oriz. crk n le with 0.5 hole unab	oliaphragmh connect 1 3rd internear btm fla " radius colle to be fu	4 s. 2018 re ion - horiz n. diaph - ange to wo orners and lly drilled	1 epair plans crack ne horiz crk eb weld m d bolted or out becau	ear btm near bt ouseho ver, sho ise of d
-			N Span: Small areas of freckled rust at girder ends  Cracking  Traffic impact from 12/1/2017 resulted in tears t bolted repairs and crack arresting/grinding. G1a flange to web weld mouseholed at each end; G1 weld ground out; G1 at 3rd interm. diaph conne at each end, large tear in web cut out to rectang diagonal crack in stiffener plate through old dia clearance to web [1' CS3].  Connection  Traffic impact to G1 in span 1 from 12/1/2017 re intermediate diaphs 2-3-4; all were repaired usin	LF o web at 2nd in betwee ction - h jular ho ph bolt  LF esulted ng vario	t several conterm. diapen 2nd and oriz. crk new with 0.5 hole unabet orn web aus bolted	oliaphragmh connect lard internear btm fla radius colle to be furnament of the furnament of	4 s. 2018 re ion - horiz n. diaph - ange to wo orners and illy drilled 0 iaphragm ons.	1 epair plans c. crack ne horiz crk eb weld m d bolted or out becau	ear btm near bt ousehover, sho ise of d
-			N Span: Small areas of freckled rust at girder ends  Cracking  Traffic impact from 12/1/2017 resulted in tears t bolted repairs and crack arresting/grinding. G1a flange to web weld mouseholed at each end; G1 weld ground out; G1 at 3rd interm. diaph conne at each end, large tear in web cut out to rectang diagonal crack in stiffener plate through old dia clearance to web [1' CS3].  Connection  Traffic impact to G1 in span 1 from 12/1/2017 re intermediate diaphs 2-3-4; all were repaired using	and blu  LF o web at 2nd in betwee ction - h jular ho ph bolt  LF esulted ng vario  LF esulted eb was ng by In	t several ceterm. diapen 2nd and oriz. crk nele with 0.5 hole unabetorn web aus bolted in distortic 59 LF, 14 Lernationa	oliaphragm h connect 1 3rd internear btm fla radius colle to be fu  3 and web-d connection 0 on to the w F north an	s. 2018 reion - horizm. diaph - ange to worners andilly drilled  0 iaphragm of iaphragm of iaphragm of iaphragm of the band both dispersion of the seening Inc.	1 epair plans crack ne horiz crk eb weld m d bolted o out becau  0 connection  0 ottom flan outh of the Approxim	ar btm near bt ouseho ver, sh use of d  0 s at  0 ge. The first field ately 4
-	8516	1020	Cracking Traffic impact from 12/1/2017 resulted in tears to bolted repairs and crack arresting/grinding. G1a flange to web weld mouseholed at each end; G1 weld ground out; G1 at 3rd interm. diaph conneat each end, large tear in web cut out to rectang diagonal crack in stiffener plate through old diaclearance to web [1' CS3].  Connection Traffic impact to G1 in span 1 from 12/1/2017 reintermediate diaphs 2-3-4; all were repaired using Distortion Traffic impact to G1 in span 1 from 12/1/2017 resulted in the span 1 from 12/	and blu  LF o web a t 2nd in betwee ction - h jular ho ph bolt  LF esulted ng vario  LF esulted eb was eb was htening	t several ceterm. diapen 2nd and oriz. crk no le with 0.5 hole unabetorn web aus bolted in distortic fig. 1, 14 Leternationa but is with 36,275	oliaphragmh connect I 3rd internear btm fla "radius colle to be fue to be fue to be fue to the web-donnection on to the web-donnection I Straightchin the strai	s. 2018 reion - horizm. diaph - horizm. diaph - longer to worners and lly drilled  0 iaphragm ons.  59  /eb and book diaphragm on horizm.	1 epair plans crack ne horiz crk eb weld m d bolted or out becau  0 connection  0 ottom flans buth of the m Approxim specificat	ar btm near bt ouseho ver, she ise of d  0 s at  0 ge. The first field iately 4
-	8516	1020	Cracking Traffic impact from 12/1/2017 resulted in tears t bolted repairs and crack arresting/grinding. G1a flange to web weld mouseholed at each end; G1 weld ground out; G1 at 3rd interm. diaph conne at each end, large tear in web cut out to rectang diagonal crack in stiffener plate through old diaclearance to web [1' CS3].  Connection Traffic impact to G1 in span 1 from 12/1/2017 reintermediate diaphs 2-3-4; all were repaired usin Distortion Traffic impact to G1 in span 1 from 12/1/2017 retotal length of distortion of the bottom flange and wsplice; this was corrected using heat straightenin of distortion and gouges still visible after straig	and blu  LF o web at 2nd in betwee ction - h jular ho ph bolt  LF esulted ng vario  LF esulted en was en g by In ntening  SF d 2018	t several ceterm. diapen 2nd and oriz. crk no le with 0.5 hole unabetorn web aus bolted in distortic 59 LF, 14 Leternationabut is with 36,275 post-heat	oliaphragmh connect I 3rd internity and inte	s. 2018 re ion - horiz m. diaph - ange to we orners and lly drilled    O   iaphragm ons.   59   reb and body d 5 LF so ening Inc. alightness   181   ing (approximation)   ing (appr	1 epair plans c. crack ne horiz crk eb weld m d bolted or out becau  0 connection  0 connection  Approxim specificat  0 ox. 59').	ar btm near btm ouseho ver, sho use of d  0 s at  0 ge. The first field attely 4 ion.  0

page 5 Structure No.: **B-67-113** 

x	205		Reinforced Concrete Column	EA	6	5	0	1	0
^	203								
			Delamination - Spall - Patched Area	EA		0	0	1	0
		1080	Med. sized delam @ top of Col #3, South Face.						
+			Reinforced Concrete Abutment	LF	229	170	44	15	0
X	215		Some staining on both abutments. Vertical joint s	ealant	failing at b	oth abutm	ents.	•	•
+			Delamination - Spall - Patched Area	LF		0	16	1	1 0
		1080	South Abut: 2 small sound patched areas (2 LF);	elam a	at 2nd gird	er from the	East (1 I	F CS3).	1
		1000	North Abut: Numerous sound patched areas(13 LF)	. Small	spall in abu	ıt seat at G	1.		
			Cracking (RC)	LF		24	28	14	0
			Both abutments: HL/Nrw vert & diag cracks, some	e with e	fflorescenc	e. HL Map	cracking i	n backwall	s. Verti
		1130	Medium cracks at both abutments some with rus G4.	st stain	ling. Wide	crack on N	i. abutme	nt betwee	n G3 &
			Reinforced Concrete Cap	LF	104	77	27	0	0
	234		·			!		Į.	
+			Delamination - Spall - Patched Area	LF		0	3	0	1 0
		1000	Sm delam underside between C1 & C2, also @ NV		orner of E h				etween
		1080	C4 & C5.			,			
			Cracking (RC)	LF		16	24	0	0
			Several load induced HL and NRW cracks radiating	g diago	nally up fro	m each co	lumn on th	ne N face c	f the Pi
		1130	also several vertical cracks at top of Pier Cap above but not as bad.		column in n	egative mo	ment regio	ons, Simila	r on S ta
			Strip Seal Expansion Joint	LF	222	0	214	8	0
					NE 4 2/4	CVAL 4 4 / A			
`	300		Jts. meas'd at 88 degrees: Meas. @ parapet: NW curb between gap of steel extrusion NW 1-1/4", I	/ 1-1/2" NE 1",	, NE 1-3/4" SW 7/8", &	, SW 1-1/4 SE 1/2".	", <b>&amp;</b> SE 1-	-3/8". Meas	s. near
+	300		curb between gap of steel extrusion NW 1-1/4", I Debris Impaction	/ 1-1/2" NE 1", : LF	, NE 1-3/4" SW 7/8", &	, SW 1-1/4 SE 1/2".	", <b>&amp;</b> SE 1-	- <b>3/8". Mea</b> :	s. near
	300	2350	curb between gap of steel extrusion NW 1-1/4", I	NE 1",	, NE 1-3/4" SW 7/8", &	SE 1/2".		_	
	300	2350	Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage	LF	SW 7/8", &	0 0	214	0	0
	300		Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs	LF  LF  S3 spal	SW 7/8", &	0   0   eader in the	214 0 e SB lanes	8 s. <b>CS3 del</b> a	0 am( <b>S.</b> )
	300	2350	Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage	LF  LF  S3 spal	SW 7/8", &	0   0   eader in the	214 0 e SB lanes	8 s. <b>CS3 del</b> a	0 am( <b>S.</b> )
	300		Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er	LF  LF  S3 spal	SW 7/8", &	0   0   eader in the	214 0 e SB lanes	8 s. <b>CS3 del</b> a	0 am( <b>S.</b> )
	300		Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs	LF LF 33 spal	SW 7/8", &	0 o eader in the ng patch a	214 0 e SB lanes	8 s. CS3 dela	0 am(S.) a der 1 LI
			Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction  Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage  Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal  Longitudinal Joint in Median	LF LF 33 spal	SW 7/8", &	0 o eader in the ng patch a	214  0 e SB lanes t SW corr	8 s. CS3 dela	0 am(S.) a der 1 LI
			Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking	LF LF 33 spal	SW 7/8", &	0 o eader in the ng patch a	214 0 e SB lanes	8 s. CS3 dela	0 am(S.) a der 1 LI
		2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.	LF  S3 spal ds of b  LF	SW 7/8", &	0 oeader in the ng patch a	214  0 e SB lanes t SW corr  186	8 3. CS3 delaner of head	0 0 am(S.) adder 1 Li
		2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction	LF LF 33 spal	SW 7/8", &	0 o eader in the ng patch a	214  0 e SB lanes t SW corr	8 s. CS3 dela	0 am(S.) a der 1 Li
		2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.	LF  S3 spal ds of b  LF	SW 7/8", &	0 oeader in the ng patch a	214  0 e SB lanes t SW corr  186	8 3. CS3 delaner of head	0 0 am(S.) adder 1 Ll
		2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction	LF  S3 spal ds of b  LF	SW 7/8", &	0 oeader in the ng patch a	214  0 e SB lanes t SW corr  186	8 3. CS3 delaner of head	0 0 am(S.) adder 1 Ll
(		2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction  Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage  Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal  Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking  Few areas of no adhesion/leakage.  Debris Impaction  80% of joint with moderate debris impaction.	LF LF S3 spal ds of b LF LF LF LF	SW 7/8", &	O o eader in the ng patch a o o o o o o o o o o o o o o o o o o	214 0 e SB lanes tt SW corr 186 14	0 83. CS3 delaner of head	0 0 am(S.) adder 1 Lift 0 0
(	302	2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction  Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage  Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal  Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction  80% of joint with moderate debris impaction.  Elastomeric Bearing  Bearings resting on 10-1/2" precast concrete pads	LF LF S3 spal ds of b LF LF LF	SW 7/8", &	0   0   eader in the ng patch a   0   0   0   0   0   0   24   0	214  0 e SB lanes tt SW corr  186  14  172	0 8 s. CS3 delater of head	0 0 am(S.) adder 1 Li
(	302	2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction 80% of joint with moderate debris impaction.  Elastomeric Bearing Bearings resting on 10-1/2" precast concrete pads	LF	SW 7/8", &	O o eader in the ng patch a o o o o o o o o o o o o o o o o o o	214 0 e SB lanes tt SW corr 186 14	0 83. CS3 delaner of head	0 0 am(S.) adder 1 Lift 0 0
(	302	2360	Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cspall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction 80% of joint with moderate debris impaction.  Elastomeric Bearing Bearings resting on 10-1/2" precast concrete pads  Fixed Bearing  Bearings resting on 10-1/2" precast concrete pads	LF	SW 7/8", &	0   0   eader in the ng patch a   0   0   0   0   0   0   24   0	214  0 e SB lanes it SW corr  186  14  172  0	0 8 s. CS3 delater of head	0 0 am(S.) adder 1 LF
	302 310 313	2360	Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cspall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction 80% of joint with moderate debris impaction.  Elastomeric Bearing Bearings resting on 10-1/2" precast concrete pads  Fixed Bearing Bearings resting on 10-1/2" precast concrete pads  Reinforced Concrete Bridge Rail	LF	SW 7/8", &	0   0   eader in the ng patch a   0   0   0   0   0   0   24   0	214  0 e SB lanes tt SW corr  186  14  172	0 8 s. CS3 delater of head	0 0 am(S.) adder 1 LF
	302	2360	Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cspall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction 80% of joint with moderate debris impaction.  Elastomeric Bearing Bearings resting on 10-1/2" precast concrete pads  Fixed Bearing  Bearings resting on 10-1/2" precast concrete pads	LF LF LF LF LF LF LF LF LF	SW 7/8", &	0   0   eader in the ng patch a   181   0   24   12	214  0 e SB lanes it SW corr  186  14  172  0	0 8 8 6. <b>CS3 delater of head</b> 0 0 0	0 0 am(S.) adder 1 LF
< < < < < < < < < < < < < < < < < < <	302 310 313	2360	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction  Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage  Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal  Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction  80% of joint with moderate debris impaction.  Elastomeric Bearing Bearings resting on 10-1/2" precast concrete pads  Fixed Bearing Bearings resting on 10-1/2" precast concrete pads  Reinforced Concrete Bridge Rail  Staining at all East rail fence posts.	LF LF LF LF LF LF LF LF LF	SW 7/8", &	0   0   eader in the ng patch a   181   0   24   12	214  0 e SB lanes it SW corr  186  14  172  0	0 8 8 6. <b>CS3 delater of head</b> 0 0 0	0 0 am(S.) adder 1 LF
(	302 310 313	2360	Curb between gap of steel extrusion NW 1-1/4", I Debris Impaction Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage Longit HL and NRW cracks in all headers. 5 LF Cspall(N.) at end of compression seal joint at both er  Compression Joint Seal Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction 80% of joint with moderate debris impaction.  Elastomeric Bearing Bearings resting on 10-1/2" precast concrete pads  Fixed Bearing Bearings resting on 10-1/2" precast concrete pads  Reinforced Concrete Bridge Rail	LF L	ing in N. hrridge. Faili 367  24  12  518	0   0   eader in the ng patch a   181   0     24     12     440     0     offace near	214  0 e SB lanes t SW corr  186  14  172  0  75  1 south joi	0 8 8 8 8 CS3 dela ner of head 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
<	302 310 313	2360 2310 2350	Curb between gap of steel extrusion NW 1-1/4", I  Debris Impaction  Dirt & debris in joint, heavier packed at edges.  Adjacent Deck or Header Damage  Longit HL and NRW cracks in all headers. 5 LF Cs spall(N.) at end of compression seal joint at both er  Compression Joint Seal  Longitudinal Joint in Median  Leakage, Seal Adhesion, Damage, Cracking Few areas of no adhesion/leakage.  Debris Impaction  80% of joint with moderate debris impaction.  Elastomeric Bearing  Bearings resting on 10-1/2" precast concrete pads  Fixed Bearing  Bearings resting on 10-1/2" precast concrete pads  Reinforced Concrete Bridge Rail  Staining at all East rail fence posts.  Delamination - Spall - Patched Area  West Rail: Lg vertical spall at N expansion joint. La East Rail: Med size CS3 spall at N. expansion joint.	LF L	ing in N. hrridge. Faili 367  24  12  518	0   0   eader in the ng patch a   181   0     24     12     440     0     offace near	214  0 e SB lanes t SW corr  186  14  172  0  75  1 south joi	0 8 8 8 8 CS3 dela ner of head 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

page 6 Structure No.:B-67-113

		Integral Wingwall	EA	4	3	1	0	0
8400								
		Wall Deterioration	FA		3	1	0	0
	8400	8400	Wall Deterioration	8400	Wall Deterioration EA	Wall Deterioration EA 3	8400   Wall Deterioration   EA   3   1	Wall Deterioration

### **Assessments**

		.5				Quantity in C	Condition State	2
Chk	Element	Defect Description	UOM	Total	1	2	3	4
		Drainage - Ends of Structure	EA	10	8	1	1	0
×	9001	Qty= 6 inlets + 4 wings. Riprap flumes @ NW & w/inlets at all 4 corners.  NW: inlets at median and outside-good; riprap NE: median inlet-good; outside inlet-deteriorar base gravel visible) - CS3; riprap at end of win SE: inlet with failing adjustment rings (CS2); rierosion.  SW: inlet-good, wingtip-good.	at wingt tion at ac	ip-good. ljustment own with	rings/bloc weeds but	k below c	asting (roa	adway
		Median	EA	1	0	1	0	0
X	9007	Median: HL and NRW transv and longit cracks.	Some mi	nor plow a	brasion.			
		Sidewalk	EA	2	0	2	0	0
Х	9009	Both Walks: scattered pop outs wtih HL and N spalls at curb near middle of bridge.	IRW Tran	s cracks -	heavier ove	er pier. <b>We</b>	st walk 2-	arge
		Utilities	EA	2	2	0	0	0
×	9011	(2) Light poles. Both poles have nests under t East: BYY20 West: DYY8	he mono	tube pole.	No issues	noted.		
		Signs - Object Markers  (4) Tiger 2 NB and 2 SB attached to sign bridges	EA	4	3	1	0	0
<	9030	Signs - Other (2) "Slippery When Wet" ahead signs on light po	EA	2	om traffic i	mpact.	0	0
		Slope Protection- Crushed Aggregate with Bit	. EA	2	2	0	0	0
<	9043	Resealed 2009 South: some bleaching at SE corner, vines gro North: light bleaching at bottom and scattered	wing thr	ough at W				
$\dashv$		Steel Diaphragm	EA	130	100	30	0	0
×	9167	Some bottom corner edge rust scattered through pier, 2 at span 2, and 3 at north abutment = 30 Note: G1 in span 1 has bolted retrofit repair cotraffic impact, plus welded connection at diaple.	total CS nnections	2) s at interm	· nediate dia	phs 2 and	•	-
		Approach Roadway - Concrete (non-structural	) EA	4	1	3	0	0
<	9322	NW- good condition except large delam in money NE- Few small spalls/ravels at joints, expansion SW- exp. joint material starting to fail, a few creating security security.	n <b>joint</b> se	ealing is fa	iling			
		Luminaire Bases	EA	2	1	1	0	0
Χ	9336	West base: NRW cracks propagating from the	e utility k	oox out in	parapet.			
X	9337	Protective Screening 2" Galvanized CL Fence on both rails. East rail:	EA	2	1	1	0	0

## **NBI** Ratings

	File	New
Deck	7	7
Superstructure		6
Substructure	6	6
Culvert	N	N
Channel	N	N
Waterway	Ň	Ñ

page 7 Structure No.: **B-67-113** 

## **Structure Specific Notes**

Painted in 1998.

Need to monitor cracking in Pier Cap: No apparent change 2017 **or 2018.**The bridge was stationed south to north and the girders were labeled west to east. The diaphragm numbering increased fr**om south** to north.

12/15/17: Empty dump truck traveling full freeway speeds on I-43 NB with box up hit G1 over L2 resulting in significant damage. Repairs were completed by Zenith Tech with International Straightening Inc. as the heat straightening sub in early May 2018.

### **Inspection Specific Notes**

## **Inspector Site-Specific Safety Considerations**

## **Structure Inspection Procedures**

Top-park in very wide SB RT shoulder of Racine Ave. Bottom- park on NB or SB RT shoulder of I-43

**Special Requirements** 


Hours

Cost

Comments

page 8 Structure No.:B-67-113

# Routine Document Comment/Description Roadway looking SB



page 9 Structure No.:B-67-113


# Routine Document Comment/Description W elevation looking NB



page 10 Structure No.:B-67-113

Routine
Document Comment/Description

SB at N approach median - curb with several spalls.



page 11 Structure No.:B-67-113

Routine
Document Comment/Description

Inlet at NE quad - CABC visible below casting - tuckpoint needed.



page 12 Structure No.:B-67-113

Routine
Document Comment/Description

NE approach - typical unsealed transverse joints.



page 13 Structure No.:B-67-113

Routine
Document Comment/Description


NE- wing/sidewalk joint full of weeds and needs to be sealed.



page 14 Structure No.:B-67-113

Routine
Document Comment/Description

Strip Seal Exp Jt - CS3 spall in S header at compression seal.



page 15 Structure No.:B-67-113


Routine
Document Comment/Description

West Rail: Large vertical spall at N expansion joint.



page 16 Structure No.:B-67-113

Routine
Document Comment/Description
Typical small spall in header.



page 17 Structure No.:B-67-113

Routine
Document Comment/Description

West sidewalk - spall near middle of bridge




page 18 Structure No.:B-67-113

# Routine Document Comment/Description Debris in compression seal.



page 19 Structure No.:B-67-113

## Routine Document Comment/Description Failed patch in S header.



page 20 Structure No.:B-67-113

## Routine Document Comment/Description

G1 span 1 previous distortion heat straightened. Note some minor distortion still present but within tolerances.



page 21 Structure No.:B-67-113

### **Routine**

## **Document Comment/Description**

E face G1 in span 1 at intermediate diaph connection 4 - crack in stiffener drilled out but not fully arrested due to clearance issue between web and drill.



page 22 Structure No.:B-67-113

Routine
Document Comment/Description

Span 1 superstructure in good condition.



page 23 Structure No.:B-67-113

Routine
Document Comment/Description
G1 in span 1 repainted after heat straightening.



page 24 Structure No.:B-67-113

Routine
Document Comment/Description
G1 span 1 - some minor distortion still visible.



page 25 Structure No.:B-67-113

Routine
Document Comment/Description

Typ light rust at girder - picture at G12 at S abut.



page 26 Structure No.:B-67-113

Routine
Document Comment/Description

Example of condensation at bottom flanges at south abutment girder ends.



page 27 Structure No.:B-67-113

Routine
Document Comment/Description


Scattered peeling paint in bottom flange with light rust.



page 28 Structure No.:B-67-113

Routine
Document Comment/Description

Span 1 girders - typical edge rust on bottom rust.



page 29 Structure No.:B-67-113

Routine
Document Comment/Description
Typical condition superstructure span 2.



page 30 Structure No.:B-67-113

Routine
Document Comment/Description

Bay 1 at north abutment - mortar rubs in soffit.



page 31 Structure No.:B-67-113

# Routine Document Comment/Description Vine growth at south slope.



page 32 Structure No.:B-67-113

Routine
Document Comment/Description

RC Abut - Wide crack at Girder 4 at N abutment.



page 33 Structure No.:B-67-113

Routine
Document Comment/Description

RC Cap - Typical HL load induced cracks in cap. Photo shows north side of pier at west end.



page 34 Structure No.:B-67-113

# Routine Document Comment/Description CS3 delam on C4.



page 35 Structure No.:B-67-113

Routine
Document Comment/Description
Typical medium cracking at abutment.



page 36 Structure No.:B-67-113

Routine
Document Comment/Description
SW wing - patch with adjacent cracks.



page 37 Structure No.:B-67-113

Routine
Document Comment/Description
S abut - crack with effl and patch.



page 38 Structure No.:B-67-113

## **Vertical Clearance Verification Document Comment/Description**


Span 1 min. VC at edge of NB right shoulder, 16.30'




page 39 Structure No.:B-67-113


## Vertical Clearance Verification Document Comment/Description

Span 2 Min. VC at SB left shoulder, 18.47'



This page intentionally left blank





### SECTION THRU CTH Y

(LOOKING NORTH)

### TOTAL ESTIMATED QUANTITIES

8

BID ITEMS	UNIT	SUPER.	SOUTH ABUT.	PIER	NORTH ABUT.	TOTALS
REMOVING OLD SRUCTURE (STA. 100+03.07)	L.S.					1
EXCAVATION FOR STRUCTURES BRIDGES (B-67-113)	L.S.					1
BACKFILL STRUCTURE	C.Y.		150		148	298
CONCRETE MASONRY BRIDGES	C.Y.	1038	67	4	65	1174
COMPRESSION JOINT SEALER PREFORMED ELASTOMERIC (21/2-INCH)	L.F.	212				212
EXPANSION DEVICE (B-67-113)	L.S.					1
MASONRY ANCHORS TYPE L NO.5 BARS	EACH		282		282	564
MASONRY ANCHORS TYPE L NO.6 BARS	EACH		70		70	140
MASONRY ANCHORS TYPE S 1/2-INCH	EACH		96	96	96	288
BAR STEEL REINFORCEMENT HS COATED BRIDGES	LB.	191110	9160	300	9290	209860
STRUCTURAL CARBON STEEL	LB.		81		81	162
BEARING PADS ELASTOMERIC LAMINATED	EACH		12		12	24
WELDED STUD SHEAR CONNECTORS 7/8×6-INCH	EACH	5220				5220
BEARING ASSEMBLIES FIXED (B-67-113)	EACH			12		12
CONCRETE SURFACE REPAIR	S.F.		50		50	100
RUBBERIZED MEMBRANE WATERPROOFING	S.Y.		2 <b>7</b>		27	54
SLOPE PAVING CRUSHED AGGREGATE	S.Y.		498		660	1158
ANCHOR ASSEMBLIES FOR STEEL PLATE BEAM GUARD	EACH	4				4
FENCE CHAIN LINK 8-FT	L.F.	501				501
CONDUIT RIGID METALLIC 2-INCH	L.F.	40	170		170	380
CONDUIT RIGID NONMETALLIC SCHEDULE 40 2-INCH	L.F.	810				810
JUNCTION BOXES 18x12x6-INCH	EACH	2				2
REMOVING BEARINGS	EACH		12	12	12	36
BRIDGE JACKING, STRUCTURE B-67-113	L.S.					1
PREPARATION AND COATING OF TOP FLANGES	L.S.					1
STRUCTURE OVERCOATING CLEANING AND PRIMING STRUCTURE B-67-113	L.S.					1
CONTAINMENT AND COLLECTION OF WASTE MATERIALS STRUCTURE B-67-113	L.S.					1
ANCHOR ASSEMBLIES LIGHT POLES	EACH	2				2
TEMPORARY SHORING SPECIAL	S.F.		180		180	360
REMOVING CRUSHED AGGERGATE SLOPE PAVING	S.Y.		415		550	965
ABATEMENT OF ASBETOS CONTAINING MATERIAL (B-67-113)	L.S.					1
NON-BID ITEMS						
FILLER	SIZE					1/2" & 3/4"

<u>IN SPAN</u>

# PI 101+75.00 EL. 876.16 106+50.00 869.61 R NB CTH Y-


VERTICAL CURVE LENGTH = 950'

AT PIER


### PROFILE GRADE LINE CTH Y

### **GENERAL NOTES**


- 1. DRAWINGS SHALL NOT BE SCALED. BAR STEEL REINFORCEMENT SHALL BE EMBEDDED 2" CLEAR UNLESS OTHERWISE SHOWN OR NOTED.
- 2. DIMENSIONS SHOWN ARE BASED ON ORIGINAL STRUCTURE PLANS.
- 3. ALL STATIONS AND ALL ELEVATIONS ARE IN FEET.
- 4. ALL REINFORCEMENT BARS ARE ENGLISH AND THE FIRST OR FIRST TWO DIGITS OF THE BAR MARK SIGNIFIES THE BAR SIZE.
- 5. AT ABUTMENTS ALL SPACES EXCAVATED AND NOT OCCUPIED BY THE NEW STRUCTURE SHALL BE BACKFILLED WITH GRANULAR BACKFILL.
- 6. EXPANSION JOINT ASSEMBLY, INCLUDING ANCHOR STUDS AND HARDWARE SHALL BE PAID FOR IN LUMP SUM PRICE BID AS "EXPANSION DEVICE (B-67-113)".
- 7. VARIATIONS TO THE NEW GRADE LINE OVER  $\frac{1}{4}$ " MUST BE SUBMITTED BY THE FIELD ENGINEER TO THE STRUCTURES DESIGN SECTION FOR REVIEW.
- 8. IF NEW NAME PLATE IS REQUIRED, ORIGINAL CONSTRUCTION YEAR IS 1969.
- 9. THE GRADATION OF THE STRUCTURE BACKFILL SHALL MEET THE REQUIREMENTS OF SECTION 209.2.2 OF THE STANDARDS SPECIFICATIONS FOR GRADE 1 MATERIAL.
- 10. EXISTING STRUCTURES B-67-113 IS A 2 SPAN HAUNCHED STEEL PLATE GIRDER STRUCTURE: EXISTING DECK, OVERLAY, BACKWALL, TOP OF WING WALLS, PARAPET, MEDIAN & BEARINGS TO BE REMOVED. EXISTING STRUCTURE TO BE REMOVED IN STAGES AS SHOWN AND AS DIRECTED BY THE ENGINEER.
- 11. FIELD WELDING OF CONSTRUCTION ACCESSORIES WILL NOT BE PERMITTED TO BEAMS OR GIRDERS UNLESS PERMITTED BY THE ENGINEER.
- 12. THE HAUNCH CONCRETE QUANTITY IS BASED ON AN AVERAGE HAUNCH HEIGHT OF  $4\frac{1}{2}$ "




### PROFILE GRADE LINE EB IH 43





### PROFILE GRADE LINE WB IH 43



8








### SECTION THRU SOUTH ABUTMENT

(SIDEWALK & MEDIAN NOT SHOWN)



<u>PL AN</u>

#### NOTES:

- 1. Z CONCRETE MASONRY ANCHORS TYPE L NO.5 BAR EMBEDED 1'-3" INTO EXISTING ABUTMENT BODY, HAVING A MINIMUM PULLOUT CAPACITY OF 19 KIPS.
- 2. A CONCRETE MASONRY ANCHORS TYPE L NO.6 BAR EMBEDED 1'-6"INTO EXISTING ABUTMENT BODY. HAVING A MINIMUM PULLOUT CAPACITY OF 27 KIPS.
- 3. LINE OF BACKWALL REMOVAL. ROUGHEN SURFACE OF CONCRETE '/4" DEEP MIN. ALL AREAS OF NEW TO EXISTING CONCRETE CONTACT.
- 4. POUR CONCRETE ABOVE THIS JOINT AFTER SUPERSTRUCTURE CONCRETE IS IN PLACE, STRIKE OFF AND LEAVE ROUGH.
- 5. 18"(RMW) RUBBERIZED MEMBRANE WATERPROOFING SEAL ALL HORIZONTAL AND VERTICAL JOINTS AT BACKFACE.


8


- 6. ROUGHEN SURFACE OF CONCRETE 1/4" DEEP MIN. ALL AREAS OF NEW TO EXIST. CONCRETE CONTACT.
- 7.  $\triangle$  CONCRETE MASONRY ANCHORS TYPE S 1/2-INCH. EMBED 5" INTO EXISTING CONCRETE.

NO.	DATE	F	REVISION BY					
	STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION							
	STRUCTURE B-67-113							
С	ONST.	PLANS CK'D.	PGC					
		SOUTH	SHE	ET 4	OF 21			
	ΑΙ	BUTMEN	Т					

### PEDESTAL HEIGHTS


LOCATION	GIRDER 1	GIRDER 2	GIRDER 3	GIRDER 4	GIRDER 5	GIRDER 6	GIRDER 7	GIRDER 8	GIRDER 9	GIRDER 10	GIRDER 11	GIRDER 12
"A"	11''	11''	11"	11''	11"	11"	111/4''	11"	111/4"	11"	113/8"	11"







SOUTH ABUTMENT


DETAILS









8




DETAIL C



DETAIL B



<u>A523</u>



MARK

☑ A501 X

A502 X

A503 X

A504 X

A505 X

A506 X

A507 X

A508 X

A509 X

A510 X

A511 X

A512 X

A515 X

A416 X

A517 X

A619 X

A620 X

A521 X

A523 X

A524 X

\* A425 X


A522

▲ A618 X


☑ A513 X


A514

<u>A512</u>





DETAIL A







A502, A504, A507, A514, A515, A619 & A620







(SIDEWALK & MEDIAN NOT SHOWN)



#### NOTES:

- 1. 🗖 CONCRETE MASONRY ANCHORS TYPE L, NO.5 BAR EMBEDED 1'-3" INTO EXISTING ABUTMENT BODY. HAVING A MINIMUM PULLOUT CAPACITY OF 19 KIPS.
- 2. A CONCRETE MASONRY ANCHORS TYPE L, NO. 6 BAR EMBEDED 1'-6"INTO EXISTING ABUTMENT BODY, HAVING A MINIMUM PULLOUT CAPACITY OF 27 KIPS.
- 3. LINE OF BACKWALL REMOVAL. ROUGHEN SURFACE OF CONCRETE 1/4" DEEP MIN. ALL AREAS OF NEW TO EXISTING CONCRETE CONTACT.
- 4. POUR CONCRETE ABOVE THIS JOINT AFTER SUPERSTRUCTURE CONCRETE IS IN PLACE, STRIKE OFF AND LEAVE ROUGH.
- 5. 18" (RMW) RUBBERIZED MEMBRANE WATERPROOFING SEAL ALL HORIZONTAL AND VERTICAL JOINTS AT BACKFACE.


  6. ROUGHEN SUBFACE OF CONCRETE!/-" DEEP
- 6. ROUGHEN SURFACE OF CONCRETE!/4" DEEP MIN. ALL AREAS OF NEW TO EXIST. CONCRETE CONTACT.
- 7.  ${}^{\triangle}$  concrete masonry anchors type s  ${}^{/}_2\text{-inch}$  embed 5" into existing concrete.


NO.	DATE	REVISION E							
STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION									
STRUCTURE B-67-113									
С	ONST.	SPEC. 2008	DRAWN BY MJB		PLANS CK'D.	PGC			
		NORTH	SHEE	T 7	OF 21				
	Αl	BUTMEN							

#### <u>PL AN</u>

### PEDESTAL HEIGHTS

LOCATION	GIRDER 1	GIRDER 2	GIRDER 3	GIRDER 4	GIRDER 5	GIRDER 6	GIRDER 7	GIRDER 8	GIRDER 9	GIRDER 10	GIRDER 11	GIRDER 12
"A"	11"	11"	11"	11"	11''	11"	11"	11"	11''	11"	11"	11"





BAR

MARK

■ B501 X

B502

B503 X

B505 X

B506 X

B509 X


B510

▲ B618 X

B620

B523 X

B511



B507

4'-41/8"

DETAIL A

1'-45/8''

17 SPA.@ 113/4" B507

17'-43/8"

DETAIL C

B509-

B508-

& BRG. N. ABUT

1'-4<u>5/8</u>"

2 SPA 2 SPA B507

B510 —

6'-6'/4"

DETAIL B

BAR

MARK

B502

B504

B507

B514

B515

B619

**U-BAR DIMENSIONS** 

1-4 4-11

0-8 1-6

0-8 2-4

1-2 6-9

1-2 6-8

1-2 5-3

B620 1-2 5-2

" A "

,— € BRG. N. ABUT

10''

B521

B512


B524


B517 -B620 -

8

SECTION E-E

€ BRG. N. ABUT





ELEVATION (LOOKING NORTH)

-INT. PEDISTAL TYP.

- SEE NOTE 2 (TYP.)

- SEE NOTE 1(TYP.)

-EXT. PEDISTAL TYP.

-EL. 856.67

SEE NOTE 2 (TYP.) SEE NOTE 1(TYP.) —

GIRDERS 1, 6, 7 & 12

P403 —

P401 —

GIRDERS 2-5 & 8-11

P402

BILL OF BARS

P403 X 20 3-1

BAR MARK

■ P401 X

P402 X


NO. REQ'D. LENGTH

40 2-8


96 2-11 X

NO.	DATE	F	REVISION			BY	
		STATE	OF WISCONS	IN			ı
		DEPARTMENT	OF TRANSPO	ORTAT	ION		
	ST	RUCTURES	DESIGN	SEC	CTION		
	- TO:		D 67 4	4 7			ı
`	SIKL	JCTURE	R-01-1	13			
С	ONST.	SPEC. 2008	DRAWN BY MJB		PLANS CK'D.	PGC	
							ı
			SHE	ET 10	OF 21		
		PIFR				1	
		1 1	1			l	
1						l	

8




END VIEW



### PLAN VIEW

### BEARING PLATE THICKNESS

LOCATION	А	В
N. ABUT	11/2"	11/2"
S. ABUT	13/8"	15/8"



- & OF BEARING END OF GIRDER → EXISTING GIRDER -BOTTOM FLANGE REMOVE EXISTING SOLE PLATE WELDS

#### SECTION THRU ELASTOMERIC BEARING

#### TAPERED TOP PLATE DETAIL

#### <u>NOTES</u>


- 1. BEARINGS SHALL NOT BE PLACED AT A TEMPERATURE GREATER THAN 85°F.
- 2. ALL MATERIALS USED FOR BEARINGS SHALL BE PAID FOR AT THE UNIT PRICE BID FOR "BEARINGS PADS ELASTOMERIC LAMINATED", EACH.
- 3. ALL STRUCTURAL STEEL BEARING PLATES SHALL BE FLAT ROLLED WITH ALL SURFACES SMOOTH AND FREE FROM WARP AND ALL EDGES SMOOTH, STRAIGHT AND
- 4. ALL PLATE CUTS SHALL BE MACHINE OR MACHINE FLAME CUTS.

#### \* TABLE OF FILLET WELD SIZES

MATERIAL THICKNESS OF THICKER PART JOINED	# MIN. SIZE OF FILLET WELD
TO 1/2" INCLUSIVE	3/16 "
OVER 1/2" TO 3/4"	1/4"
OVER 3/4" TO 11/2"	△ 5//6 "
OVER 11/2" TO 21/4"	△ 3/8"
OVER 21/4" TO 6"	△ 1/2"

† EXCEPT THAT THE WELD SIZE SHALL NOT EXCEED THE THICKNESS OF THE THINNER PART JOINED.

△ MIN. PASS SIZE IS 1/6"



#### TEMPORARY HOLD DOWN

PLACE ONE TEMP.HOLD DOWN PER GIRDER AT ABUTMENT WHERE SLAB POUR TERMINATES, LOCATE 3"
PERPENDICULAR OFF \$\mathcal{C}\$ of girder, rod, hex nut, washer & Drilled Hole in Girder Flg. to be Paid for as "STRUCTURAL STEEL CARBON".

- \*CONCRETE MASONARY ANCHOR TYPE L.NO.6 BAR EMBEDED 1'-6"
- \*\*AFTER REMOVING TEMPORARY HOLD DOWN, HOLE IN FLANGE SHALL BE FILLED WITH A GALVINIZED HS BOLT. BOLT SHALL BE TORQUED.

BY STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION


STRUCTURE B-67-113

MJB PLANS CK'D. PGC CONST. SPEC. 2008 DRAWN

**ELASTOMERIC** ABUT. BEARINGS 8

SHEET 11 OF 21

8



**ASSEMBLY** 

#### PLATE "C"

#### FIXED BEARING

EXISTING ANCHOR BOLTS TO REMAIN IN PLACE.
DRILL FOR NEW ANCHOR BOLTS AND EPOXY IN PLACE.

1.4 1.4 1.A	2 <sup>1</sup> / <sub>4</sub> "
	÷
DRILLED HOLES FOR ANCHOR BOLTS—(HOLE DIA. = BOLT DIA. + 1/8")	1/2" PINTLES

#### PLATE "D"

\* FINISH THESE SURFACES ANSI 250 FINISH IF 'Y' DIM. IS GREATER THAN 2"

		PLATE "(	2"	F	PLATE "E	)"	PLATE	ANCHOR	NO. OF	LOCATION	
	Х	Y	Z	Х	Y	Z	"D" TYPE	BOL T SIZE	BRG'S REO'D		
_ Q	5''	23/8"	1'-4''	1'-4''	2 1/8"	2'-2"	SHOWN	1 / 2 '' Φ	12	PIER	
TXED EARIN											
B B											

### BOTTOM FLANGE 11:1 ili 111 -111111 -NEW FIXED PLATE "C"

#### BEARING REPLACEMENT DETAILS

REMOVE EXISTING FIXED BEARINGS AND EXISTING TOP PLATE AND REPLACE WITH NEW PLATE "C" PAID FOR AS BID ITEM "REMOVING BEARINGS".

#### \* TABLE OF FILLET WELD SIZES

MATERIAL THICKNESS OF THICKER PART JOINED	# MIN. SIZE OF FILLET WELD
TO 1/2" INCLUSIVE	3/16 ''
OVER 1/2" TO 3/4"	1/4"
OVER 3/4" TO 11/2"	△ 5/16 ''
OVER 11/2" TO 21/4"	△ 3/8"
OVER 21/4" TO 6"	△ 1/2"

# EXCEPT THAT THE WELD SIZE SHALL NOT EXCEED THE THICKNESS OF THE THINNER PART JOINED.

△ MIN. PASS SIZE IS 1/6"

#### **BEARING NOTES**

ALL BEARINGS ARE SYMMETRICAL ABOUT  $\mathbb Q$  OF GIRDER AND  $\mathbb Q$  OF BEARING.

ALL STRUCTURAL STEEL BEARING PLATES SHALL BE FLAT ROLLED STEEL PLATES WITH ALL SURFACES SMOOTH AND FREE FROM WARP AND ALL EDGES SMOOTH, STRAIGHT AND VERTICAL

ALL PLATE CUTS SHALL BE MACHINE OR MACHINE FLAME CUT.

ALL FINISHED SURFACES SHALL BE MACHINE FINISHED BY AN

CHAMFER ANCHOR BOLTS PRIOR TO THREADING.

LOCATE ANCHOR BOLTS AS INDICTED FOR PLATE "D". SEE TABLE FOR SIZE. PROJECT ANCHOR BOLTS "D" PLATE THICKNESS +21/4" ABOVE TOP OF CONCRETE.

ANCHOR BOLTS SHALL BE THREADED 3". PROVIDE ONE STANDARD WROUGHT WASHER AND ONE HEXNUT PER BOLT. BOLT LENGTH TO BE 1'-10".

FOR UNPAINTED STRUCTURES THE UPPER 6"OF THE ANCHOR BOLTS, NUTS AND WASHER ASHALL BE GALVANIZED AS REQUIRED BY ASTM DESIGNATION A153, CLASS C OR A164, TYPE GS.

ALL MATERIALS FOR BEARING INCLUDING SHIMS BUT EXCLUDING ANCHORS BOLTS, STAINLESS STEEL, TELFLON SURFACES, PINTLES, NUTS AND WASHERS SHALL BE MADE

STEEL PINTLES SHALL BE MADE OF ASTM A449 STEEL OR MATERIAL OF EQUIVALENT YIELD STRENGTH AND ELONGATION.

ALL ANCHOR BOLTS, NUTS AND WASHERS SHALL CONFORM TO ASTM A709 GRADE 36 OR MATERIAL OF EQUIVALENT YELD STRENGTH AND ELONGATION.

PROVIDE  $\slash\hspace{-0.6em}/g"$  Thick bearing PAD same size as plate "D" for each bearing.

ALL MATERIALS IN BEARINGS, INCLUDING BEARING PADS, ANCHOR BOLTS, WASHERS, NUTS, CORING, GROUTING & SHIM PLATES SHALL BE PAID FOR AT THE UNIT PRICE BID FOR AS "BEARING ASSEMBLIES FIXED B-66-39".

ANCHOR BOLTS, NUTS & WASHERS SHALL BE GALVANIZED IN ACCORDANCE WITH ASTM A153 CLASS L.

PLATE "C" SHALL NOT BE GALVANIZED. SHOP PAINT PLATE "C" A WELDABLE PRIMER. GALVANIZE PLATE "D".

EXISTING FIXED BEARINGS INCLUDING MASONARY PLATE, ROCKER PLATE, ANCHOR BOLTS & BEARING PAD TO BE REMOVED. GRIND BTM FLANGE REMOVAL AREAS SMOOTH. CLEAN CONCRETE SURFACE.

MATERIAL THICKNESS OF THICKER PART JOINED	# MIN, SIZE OF FILLET WELD
TO 1/2" INCLUSIVE	3/16 ''
OVER 1/2" TO 3/4"	1/4"
OVER 3/4" TO 11/2"	△ 5/6"
OVER $1^{1}/_{2}$ " TO $2^{1}/_{4}$ "	△ 3/8"
OVER 21/4" TO 6"	△ 1/2"

STRUCTURE B-67-113 CONST. SPEC. 2008


MJB PLANS CK'D. PGC HEET 12 OF 21 FIXED BEARING DETAILS


STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION


STRUCTURES DESIGN SECTION


8

BY









### BILL OF BARS

NOTE: THE FIRST OR FIRST TWO DIGITS OF THE BAR MARK SIGNIFIES THE BAR SIZE.

BAR MARK	C047	NO. REQ'D.	LENGTH	SKIN,	BAR SERIES	LOCATION	
S401	Х	52	4-0	Х		SLAB DIAPH.G1-G3 & G10-G12 ST	IRRUP
S402	Х	78	4-3	Х		SLAB DIAPH. G3-G10 ST	IRRUP
S503	Х	324	21-6			SLAB OVERHANG T	RANS.
S704	Х	120	9-9			SLAB DIAPH. T	RANS.
S605	Х	39	9-10			SLAB TOP	LONG.
S406	Х	4	5-7	Х		PARAPET	HORIZ.
S50 <b>7</b>	Х	1218	50-8			SLAB TOP & BOTTOM T	RANS.
S508	Х	33	26-4		Δ	SLAB BOTTOM T	RANS.
S509	Х	33	24-8		Δ	SLAB BOTTOM T	RANS.
S510	Х	33	25-6		Δ	SLAB BOTTOM T	RANS.
S511	Х	34	26-1		Δ	SLAB BOTTOM T	RANS.
S412	Х	1032	36-8			SLAB BOTTOM	LONG.
S413	Х	324	34-0			SLAB TOP	LONG.
S614	Х	487	28-4			SLAB TOP	LONG.
S415	Х	324	37-3			SLAB TOP	LONG.
S516	Х	34	26-2		Δ	SLAB TOP T	RANS.
S517	Х	33	25-5		Δ	SLAB TOP T	RANS.
S518	Х	33	24-9		Δ	SLAB TOP T	RANS.
S519	Х	33	26-1		Δ	SLAB TOP T	RANS.
S520	Х	331	12-2			SLAB OVERHANG T	RANS.
S621	Х	332	15-5	Х		WEST SIDEWALK DO	OWELL
S622	Х	351	19-11	Х		EAST SIDEWALK DO	OWELL
S623	Х	426	4-1	Х		MEDIAN D	DWELL
S624	Х	14	8-4	Х		WEST SIDEWALK DO	OWELL
S425	Х	143	6-8			WEST SIDEWALK BOTTOM T	RANS.
S526	Х	427	7-3	Х		WEST SIDEWALK TOP T	RANS.
S42 <b>7</b>	Х	146	16-8			EAST SIDEWALK BOTTOM T	RANS.
S428	Х	78	35-8			MEDIAN, WEST SIDEWALK & PARAPET	LONG.
S429	Х	78	38-3			MEDIAN, WEST SIDEWALK & PARAPET	LONG.
S430	Х	270	37-5			EAST SIDEWALK & PARAPET	LONG.
S531	Х	430	6-8	Х		PARAPET VEF	RTICAL
S432	Х	420	2-10	Х		GIRDER 3 & 10 HA	T BAR
S433	Х	420	2-11	Х		GIRDER 4 & 9 HA	T BAR
S434	Х	420	3-0	Х		GIRDER 5 & 8 HA	T BAR
S435	Х	420	3-2	Χ		GIRDER 6 & 7 HA	T BAR

#### TOP OF DECK ELEVATIONS

TOP OF STEEL ELEVATIONS

GIRDER 1 866.31

GIRDER 2 866.50 GIRDER 3 866.66

GIRDER 4 866.82 GIRDER 5 866.97

GIRDER 6 867.14

GIRDER 7 867.16

GIRDER 8 867.16

GIRDER 9 867.14

GIRDER 10 867.12

GIRDER 11 867.09

GIRDER 12 867.06

S. ABUT. 1/10 2/10 3/10 4/10 5/10 6/10 7/10 8/10 9/10 PIER

	S. ABUT.	1/10	2/10	3/10	4/10	5/10	6/10	7/10	8/10	9/10	PIER	1/10	2/10	3/10	4/10	5/10	6/10	7/10	8/10	9/10	N. ABUT.
GIRDER 1	867.21	867.40	86 <b>7.</b> 58	867.76	86 <b>7.</b> 94	868.11	868.28	868.45	868.61	868.76	868.91	869.07	869.22	869.36	869.51	869.64	869.77	869.90	870.02	870.14	870.25
GIRDER 2	867.47	867.66	867.84	868.02	868.20	868.37	868.53	868.70	868.85	869.01	869.16	869.31	869.46	869.60	869.74	869.88	870.01	870.13	870.25	870.36	870.47
GIRDER 3	867.73	867.91	868.10	868.27	868.45	868.62	868.78	868.94	869.10	869.25	869.40	869.55	869 <b>.7</b> 0	869.84	869.98	870.11	870.24	870.36	870.48	870.59	870.70
GIRDER 4	867.99	868.17	868.35	868.53	868.70	868.87	869.03	869.19	869.35	869.50	869.64	869.79	869.94	870.08	870.21	870.34	870.47	870.59	870.71	870.82	870.92
GIRDER 5	868.25	868.43	868.61	868.78	868.95	869.12	869.28	869.44	869.59	869.74	869.88	870.03	870.18	870.32	870.45	870.58	870.70	870.82	870.93	871.04	871.15
GIRDER 6	868.50	868.69	868.86	869.04	869.21	869.37	869.53	869.69	869.84	869.98	870.13	870.27	870.41	870.55	870.68	870.81	870.93	871.05	871.16	871.27	871.37
GIRDER 7	868.55	868.73	868.90	869.08	869.24	869.41	869.57	869.72	869.87	870.02	870.16	870.30	870.45	870.58	870.71	870.84	870.96	871.07	871.19	871.29	871.39
GIRDER 8	868.43	868.61	868.79	868.96	869.12	869.28	869.44	869.59	869.74	869.89	870.03	870.17	870.31	870.44	870.57	870.70	870.81	870.93	871.04	871.14	871.24
GIRDER 9	868.31	868.49	868.67	868.83	869.00	869.16	869.31	869.47	869.61	869.75	869.89	870.03	870.17	870.30	870.43	870.55	870.67	870.78	870.89	870.99	871.09
GIRDER 10	868.20	868.37	868.54	868.71	868.87	869.03	869.19	869.34	869.48	869.62	869.76	869.90	870.03	870.16	870.29	870.41	870.52	870.64	870.74	870.84	870.94
GIRDER 11	868.08	868.25	868.42	868.59	868.75	868.91	869.06	869.21	869.35	869.49	869.62	869.76	869.90	870.02	870.15	870.27	870.38	870.49	870.59	870.69	870.78
GIRDER 12	867.96	868.13	868.30	868.47	868.62	868.78	868.93	869.08	869.22	869.35	869.49	869.62	869.76	869.88	870.00	870.12	870.23	870.34	870.44	870.54	870.63

868.03 868.20

868.36

868.50

868.66

868.78

868.81

868.78

868**.7**2

868.70

868.66

1/10 2/10 3/10 4/10 5/10 6/10 7/10 8/10 9/10 N. ABUT.

#### BAR SERIES TABLE

NO. REQD.	LENG <sup>-</sup>	ГН
1 SERIES OF 33	2-5 49-10	TO
1 SERIES OF 33	1-0 48-4	ТО
1 SERIES OF 33	1-9 49-2	TO
1 SERIES OF 34	1-8 50-6	TO
1 SERIES OF 34	1-9 50-7	ТО
1 SERIES OF 33	1-8 49-1	TO
1 SERIES OF 33	1-0 48-5	то
1 SERIES OF 33	2-4 49-9	T0
	REOD.  1 SERIES OF 33  1 SERIES OF 33  1 SERIES OF 34  1 SERIES OF 34  1 SERIES OF 34  1 SERIES OF 34  1 SERIES OF 33  1 SERIES OF 33	REOD.  1 SERIES 2-5 49-10  1 SERIES 49-10  1 SERIES 1-0 48-4  1 SERIES 1-9 49-2  1 SERIES 0F 34 50-6  1 SERIES 1-9 50-7  1 SERIES 0F 34 49-1  1 SERIES 1-8 49-1  1 SERIES 1-8 49-1  1 SERIES 2-4

869.36

869.52

869.63

869.79

869.91 870.06

870.07

870.03

869.96

869.92

869.85

869.76


3		1 SE OF	ERIES 33	2-4 49-	T0	
	ΔND	TΔG	ΕΛCΗ	SERIES	SEPARATEL	Υ

NO.	NO. DATE REVISION								
	STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION								
,	STRUCTURE B-67-113								
CONST. SPEC. 2008 DRAWN BY MJB CK'D.									
٠	CURERCIPIETURE SHEET 16 OF 21								

### BUNDLE AND TAG EACH SERIES SEPARATELY.


## 8

| SUPERSTRUCTURE | SHEET DETAILS




### TYPICAL SECTION THRU JOINT AT ABUTMENT


NORMAL TO & SUBSTRUCTURE



### PART PLAN



ALTERNATE STRIP SEAL ANCHOR




#### SECTION THRU JOINT

EXTERIOR GIRDER TO EDGE OF SLAB & AT PARAPETS, MEDIANS & SIDEWALKS

#### LEGEND

- 1. NEOPRENE STRIP SEAL (4-INCH) & STEEL EXTRUSIONS.
- 2. STUDS  $5\!\!/\!\!\!/ ($   $\!\!\!/ v$   $\times$   $63\!\!/\!\!\!/\!\!\!/ ($  LONG AT 6" ALTERNATE CENTERS. WELD TO EXTRUSIONS & BEND AS SHOWN AFTER WELDING.
- 2A. 1/2" THICK ANCHOR PLATE WITH 1/8"  $\phi$  ROD (OR ALTERNATE STRIP SEAL ANCHOR). WELD ROD TO ANCHOR PLATE, WELD ANCHOR PLATE TO NO.1 AT 1'-6" CENTERS BETWEEN GIRDERS.
- 3. ¾" \* THREADED ROD WITH 2 NUTS AND WASHERS. WELD THREADED ROD TO TOP FLANGE OR ATTACH BY BOLTING THRU FLANGE ON ABUTMENT SIDE GROUT THREADED ROD INTO FIELD DRILLED HOLES IN ABUTMENT BACKWALL AS SHOWN.
- 4. 3/4" \$ THREADED ROD WITH NUT. TACK WELD NUT TO NO.5.
- FABRICATE SUPPORT FROM 3" x ½" BAR AS SHOWN OR EOUIVALENT.
   ONE PER GIRDER PER SIDE. SHOP OR FIELD WELDTO NO.1. IF FIELD
   WELDED, COVER WELDED AREAS WITH EPOXY-COATING MATERIAL.
   PROVIDE 1½" ≠ HOLE FOR NO.3 & 1" ≠ HOLE FOR NO.4.
- 6. GALVANIZED PLATE  $\frac{3}{8}$ " ×  $10^{1}/2$ " × (2'-0" LONG FOR SKEWS TO 45° & 3'-0" LONG FOR SKEWS > 45°) WITH HOLES FOR NO. 7. BEND AS SHOWN.
- 7.  $3\!\!/_4$ "  $\phi$  x  $1\,\!/_2$ " stainless steel socket flat head screws with anti-seize Lubricant. Recess  $/_{16}$ " below plate surface.
- 8.  $\frac{3}{4}$ "  $\phi$  × 4" GALVANIZED HEX HEAD BOLT. BEND 45°.
- 9.  $\frac{3}{4}$ "  $\phi \times 2\frac{1}{4}$ " GALVANIZED THREADED COUPLING.
- 10. GALVANIZED SIDEWALK PLATE  $\frac{7}{9}$ " × 2'-0" × LIMITS SHOWN, BEND DOWN FACE OF SIDEWALK WITH HOLES FOR NO. 7.
- 11. 1" x 5" SLOTTED CSK.HOLE FOR NO. 7. SLOT PARALLEL TO DIRECTION OF MOVEMENT.



#### SECTION THRU JOINT

ROADWAY TRAFFIC AREA BETWEEN EXTERIOR GIRDERS.

#### GENERAL NOTES

ONE FIELD SPLICE PERMITTED IN STEEL EXTRUSIONS. IF USED, DETAILS SHALL BE SUBMITTED FOR APPROVAL, NO SPLICING PERMITTED IN NEOPRENE STRIP SEAL.

AFTER FABRICATION, BUT BEFORE SHIPMENT, STRAIGHTEN STEEL EXTRUSIONS SUCH THAT THEY SHALL BE FREE FROM WARP, TWIST & SWEEP.

FABRICATOR SHALL PROVIDE MEANS OF KEEPING GALVANIZED EXTRUSIONS CLEAN & SMOOTH DURING SHIPMENT AND PRIOR TO APPLYING LUBRICANT ADHESIVE FOR NEOPRENE GLAND INSTALLATION.

SANDBLAST PLATES & EXTRUSIONS AFTER FABRICATION IN ACCORDANCE WITH SSPC SP. #6 "COMMERCIAL BLAST CLEANING". AFTER BLAST CLEANING, THE PLATES & EXTRUSIONS SHALL BE HOT DIPPED GALVANIZED.

ANCHOR SYSTEM NO. 8 & NO. 9 SHALL CONFORM TO ASTM A307 & SHALL BE GALVANIZED IN ACCORDANCE WITH ASTM A153 CLASS C & D.

FOR DETAILS SEE SHEET 18

STRIP SEAL EXPANSION JOINT ASSEMBLY, INCLUDING ANCHOR STUDS & HARDWARE WILL BE PAID FOR AT THE LUMP SUM PRICE BID FOR "EXPANSION DEVICE B-67-113".

NO.	NO. DATE REVISION							
	STATE OF WISCONSIN DEPARTMENT OF TRANSPORTATION STRUCTURES DESIGN SECTION							
(	STRUCTURE B-67-113							
С	ONST.	SPEC. 2008	DRAWN BY	MJB	PLANS CK'D.	PGC		
	EXPANSION SHEET 17 OF 21							
DEVICE								

8

