



STATE OF WISCONSIN
DEPARTMENT OF TRANSPORTATION

Inspection Report for B-29-038 (COLFAX ST. MAUSTON)

STH 58 over IH 90-IH 94
May 11,2017



Type	Prior	Frequency (mos)	Performed
Routine	05-27-15	24	X
Interim	03-21-16	0	
SIA Review	05-08-13	48	X

Latitude 43°48'42.01"N
Longitude 90°04'20.60"W

Owner STATE HIGHWAY DEPT
Maintainer STATE HIGHWAY DEPT

Time Log

Team members

Hours	Minutes	
2	53	

Name	Number	Signature	Date
Inspector Olson, Michael A	5024	Michael A Olson E-signed by Michael A Olson(ole110174)	05-16-17

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 2

Identification & Location

Feature On: STH 58	Section Town Range: S01 T15N R03E	Structure Number: B-29-038
Feature Under: IH 90-IH 94	County: JUNEAU	
Location 1.0M N JCT STH 82 TO E	Municipality: MAUSTON	Structure Name: COLFAX ST. MAUSTON

Geometry

measurements in feet, except where noted

Approach Roadway Width: 30	Bridge Roadway Width: 36.0	Total Length: 297.8
Approach Pavement Width: 22	Deck Width: 38.5	Deck Area (sq ft): 11465

Traffic

	Lanes	ADT	ADT year	Traffic Pattern
On	2	6700	2016	TWO WAY TRAFFIC
Under	4	35300	2016	TWO WAY TRAFFIC

Capacity

Load Rating

Inventory rating: HS16	Overburden depth (in): 0.0	Last rating date: 06-14-08	Controlling: INTERIOR DECK GIRDER Moment
Operating rating: HS26	Deck surface material: CONCRETE	Re-rate for capacity (Y/N):	Control location: 4.7 SPAN 2, 44.9
Posting:	Re-rate notes:		

Hydraulic

Classification

Scour Critical Code(113): (N) NO WATERWAY	Q100 (ft3/sec): 0	
High water elevation (ft): 0.0	Velocity (ft/sec): 0.0	Sufficiency #:

Span(s)

Span #	Material	Configuration	Depth (in)	Length (ft)	Main
1	CONT STEEL	DECK GIRDER		52.5	
2	CONT STEEL	DECK GIRDER		95.5	Y
3	CONT STEEL	DECK GIRDER		95.5	
4	CONT STEEL	DECK GIRDER		46.5	

Expansion joint(s)

Temperature:

Joint #	Location	Type	Last inspection date	Last measure (in)	New measure (in)
2	NORTH ABUTMENT	STRIPSEAL	05-27-15	0.9	1.4

Clearance

Item	File Measurement (ft)	File Date	New Measurement (ft)
Highway Min Vertical Under Cardinal	17.1	09-Mar-2017	
Highway Min Vertical Under Non-Cardinal	16.06	09-Mar-2017	
Horizontal Under Cardinal	57.6		
Horizontal Under Non-Cardinal	57.8		
Highway Min Vertical On Cardinal			
Horizontal On Cardinal			

Special Components

Component	Year	Work Performed	Note
DECK CRACK SEALER - TK-9030	2015	MISCELLANEOUS PREVENTATIVE MAINTENANCE	
CONC. PROTECTIVE TREATMENT - TK-590-1 MS	2015	MISCELLANEOUS PREVENTATIVE MAINTENANCE	

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 3

Structure No.: **B-29-038**

Construction History

Year	Work Performed	FOS id
2015	MISCELLANEOUS PREVENTATIVE MAINTENANCE	0549-29-61
2013	ADD PIER CRASH WALL	1016-00-72
2008	NEW DECK	1016-08-72
2000	PAINTING	5882-02-70
1999	REPAIR SUBSTRUCTURE	1010-00-60
1985	PAINTING	
1985	OVERLAY - CONCRETE	0029-44-21
1964	NEW STRUCTURE	

Maintenance Items History

Item	Recommended by	Status	Status change	Year completed
Deck - Seal Surface Cracks		COMPLETE		2015
Deck - Seal w/ Concrete Sealer		COMPLETE		2015

Elements

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	12		Reinforced Concrete Deck-Coated Reinforcing	SF	11,544	10,349	1,195	0	0
		1080	Delamination - Spall - Patched Area	SF		0	0	0	0
		1130	Cracking (RC) Hairline cracking with efflorescence throughout. Span 1 (south): ~ 60 sf of hairline cracking with lite efflorescence. Span2: ~530 sf of hairline cracking with lite efflorescence. Span 3: ~ 540 sf of hairline cracking with lite efflorescence. Span 4: ~ 65 sf of hairline cracking with lite efflorescence.	SF		0	1,195	0	0
		8000	Wearing Surface (Bare) (15) Visual insp. Hairline cracking throughout.	SF	10,721	10,719	2	0	0
		3210	Debonding/Spall/Patched Area/Pothole Small spall at pier 2 on the west shoulder, and a small spall in span 2 in the south bound driving lane.	SF		0	2	0	0
		3220	Crack (Wearing Surface)	SF		0	0	0	0
X	107		Steel Open Girder (11) Bottom flanges over roadway and haunch showing active corrosion.	LF	1,478	368	1,060	50	0
		1000	Corrosion (15) Visual. Corrosion affecting 75% of girder length - areas of light speckle rust and active corrosion - mostly over roadway.	LF		0	1,060	50	0
		8516	Painted Steel GRAY, RPNTD '00, CLASS A, 13900SF	SF	14,375	11,495	0	0	2,880
		3440	Effectiveness (Steel Protective Coatings) Approximately 20% of the area has rusting.	SF		0	0	0	2,880

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 4

Structure No.: **B-29-038**

X	205		Reinforced Concrete Column	EA	12	4	6	2	0
			Col 1, P1= many cracks @ salt spray area & spalls at ground line the spalls have been patched and are sound.						
	1080		Delamination - Spall - Patched Area	EA		0	3	2	0
			Pier 1: Col 1: spalls at ground line the spalls have been patched and are sound. (CS2=1) Pier 2: C2 spall with exposed rebar. (CS3= 1) Pier 3: 1 Small spall near top C3 with rust staining (CS2) and a spall near top of C2 with exposed rebar (CS3) Surface repair areas on P2 & P3.						
	1130		Cracking (RC)	EA		0	3	0	0
			Pier 1: Col 1, many cracks @ salt spray area. Pier 2: Pier 3: Hairline cracking C2 east side, and C1 east side.						
X	215		Reinforced Concrete Abutment	LF	94	81	13	0	0
			SCAT. HL CRKS						
	1080		Delamination - Spall - Patched Area	LF		0	4	0	0
			North abutment: 2' of sound patch under G1, 2' of delamination under G2, South:						
	1130		Cracking (RC)	LF		0	9	0	0
			North Abutment: hairline crack with efflorescence behind G1, under G3, and 2 narrow vertical cracks between G3 and G4 in the back wall. (CS 2= 4') South Abutment: hairline cracks with efflorescence behind G2, between G3&G4 (2'), between G4&G5, and behind G5. (CS2=5')						
X	234		Reinforced Concrete Cap	LF	130	97	29	4	0
			Rebar chair bottoms rusting and popped thru bottom of cap at all piers. P1: horiz HL crks under B1. P3: HLV crks @ ends and under G's. (13) P3 HLH crks above C4 caused by rebar corrosion from former leaking deck drain. P2 - Closed spalls on north face.						
	1080		Delamination - Spall - Patched Area	LF		0	8	4	0
			P1: Small patched area on east end. Delamination on west end 4'. (CS 2= 5') P2 : Delamination below G5, G4 and between G1 and G2. Spalls with exposed rebar between G1 and G2. (CS2=3' CS3=4') P3:						
	1130		Cracking (RC)	LF		0	21	0	0
			P3: Narrow map cracking between C3 &C4(11'). A narrow horizontal crack between C2&C3 (4'), and above C4. P2: Narrow horizontal crack between C3&C4						
X	300		Strip Seal Expansion Joint	LF	125	125	0	0	0
	2310		Leakage, Seal Adhesion, Damage, Cracking	LF		0	0	0	0
			North: Multiple hairline cracks most have been sealed. South: Multiple hairline cracks most have been sealed.						
X	311		Moveable Bearing	EA	20	0	15	5	0
			Includes 2 hold down bearings @ N.A. most "keeper" bars pushed or breaking welds from bridge skew movement. (13) Active corrosion on ext bearings. SA: B1 - sole plt cupped significantly (photo). Girders slid +1/2" east (photo of B2). NA: girders slid +/-1/4" west.						
	1000		Corrosion	EA		0	15	5	0
			North Abutment: Bearings 2-4 CS2 corrosion has started. Bearing 1 active corrosion. Bearing 5 active corrosion and the keeper is broke off. Pier 1: Corrosion has started on all 5. Pier 3: Corrosion has started on B1-B4, and B5 has active corrosion. South Abutment: B2-B4 corrosion has started, and B1 and B5 have active corrosion.						
	2210		Movement	EA		0	0	0	0
	2220		Alignment	EA		0	0	0	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 5

Structure No.: **B-29-038**

X	313		Fixed Bearing PIER 2; REPAINTED 2000.	EA	5	0	5	0	0
		1000	Corrosion Corrosion has started on all 5.	EA		0	5	0	0
X	331		Reinforced Concrete Bridge Rail HL vert cracks spaced +/-5 ft across bridge.	LF	656	574	82	0	0
		1080	Delamination - Spall - Patched Area Two minor spalls.	LF		0	2	0	0
		1130	Cracking (RC) Both rails have hl to narrow vertical cracks about every 5' approx. 80 of them have efflorescence on the back side.	LF		0	80	0	0
X	8400		Integral Wingwall NW: NE: SW: SE:	EA	4	3	1	0	0
		8902	Wall Movement	EA		0	0	0	0
		8903	Wall Deterioration South East wing has 1 small spall.	EA		0	1	0	0
X	8801		Jacketing	EA	3	1	2	0	0
		1080	Delamination - Spall - Patched Area P1C4 delamination near the bottom, and hairline to narrow map cracking throughout. P1C3 hairline to narrow cracking throughout. P1C2 delamination just above the crash wall, and hairline to narrow cracking throughout.	EA		1	2	0	0

Assessments

Chk	Element	Defect	Description	UOM	Total	Quantity in Condition State			
						1	2	3	4
X	9001		Drainage - Approach 4 Concrete Flumes NW: NE: small spall at the end of the parapet. SE: SW:	EA	4	4	0	0	0
X	9004		Drainage - Drainage Along Structure (Deck Drains) 6 deck drains.	EA	6	6	0	0	0
X	9030		Signs - Object Markers NW: NE: SE: SW:	EA	4	4	0	0	0
X	9042		Slope Protection- Concrete Some vegetation growing in the concrete joints.	EA	2	2	0	0	0
X	9167		Steel Diaphragm Span 1: No corrosion on 3 of 4 at the south abutment, but corrosion is starting on the remaining 8. Span 2: No corrosion on 3, but corrosion is starting on 10 and is active on another 7. Span 3: No corrosion on 2, but corrosion is starting on 16 and is active on another 6. Span 4: No corrosion on 4 at the north abutment, but corrosion is starting on the remaining 8.	EA	68	12	43	13	0

BRIDGE INSPECTION REPORT
Wisconsin Department of Transportation
DT2007 2003 s.84.17 Wis. Stats.

page 6

Structure No.: **B-29-038**

X	9322		Approach Roadway - Concrete (non-structural)	EA	2	1	1	0	0
South Approach has a small spall at the centerline.									

NBI Ratings

	File	New
Deck	7	7
Superstructure	6	6
Substructure	6	6
Culvert	N	N
Channel	N	N
Waterway	N	N

Structure Specific Notes

ALL BEAMGUARD REPLACED & UPGRADED IN 1996. PAINT INDEX = 13900 SF (2000).
 205)1999 COL RPR PROJ; CONC ENCPSTLTD PIER 1- COLS 2,3,&4; SURF RPRD PIER 1-COL AND PIER 3 COL'S 1&2; L-MOD
 TIGHT VER & HOR CRKS IN EA ENCPSTLTD COL; P1 COLS 2,3&4 OPEN VER CRKS; P2 COLS 1&2 VER CRKS W/SPL IN COL2
 107) 2000 PAINT PROJECT: CLASS A W/ 2 YR WARENTY AS OF 6/ 2000.
 PAINT SYSTEM USED: SHERWIN WILLIAMS: CORATHANE PRIMER, IRONOX A & B. EPA # USED: WIR 00047688.
 359 MOD AREAS OF DISCOLORATION/EFFLOR NEAR PIER 3 OVER G3, APPROX. 10'X20'.

Inspection Specific Notes

P3 Crash wall at Pier 3, no problems found.
 P1 Crash wall at Pier 1, 2" of delamination at C2, and a medium crack at C2, and a narrow Crack at C1.

Inspector Site-Specific Safety Considerations

Structure Inspection Procedures

Special Requirements

Chk	Hours	Cost	Comments
-----	-------	------	----------

Routine

Document Comment/Description

Elevation view looking east.



Routine
Document Comment/Description

Typical of bearings with active corrosion.



Routine

Document Comment/Description

Typical of the underside of deck and girders in spans one and four.



Routine

Document Comment/Description

Typical of underside and girders in spans two and three.



Routine

Document Comment/Description

Cupped sole plate on pairing one N. abutment.



5/11/17, 2:26 PM

Routine

Document Comment/Description

Spall with exposed rebar in P2C2.



Routine

Document Comment/Description

Spall with exposed rebar in P3C2.



Routine

Document Comment/Description

Roadway view looking south.



STRUCTURE INVENTORY AND APPRAISAL FIELD REVIEW FORM

B-29-038
STH 58 over IH 90-IH 94

LOCATION

(3) Municipality:
 (16) Latitude(° ' "):
 (17) Longitude(° ' "):

MAUSTON
43°48'42.01"N
90°04'20.60"W

TRAFFIC SERVICE

(28A) Lanes On:
 (28B) Lanes Under:
 (102) Traffic Pattern On:
 (102) Traffic Pattern Under:
 (19) Detour Length(mi):

2
4
-NO TRAFFIC -ONE WAY TRAFFIC <input checked="" type="checkbox"/> -TWO WAY TRAFFIC
-NO TRAFFIC -ONE WAY TRAFFIC <input checked="" type="checkbox"/> -TWO WAY TRAFFIC
5

GEOMETRY

(49) Structure Length(ft):
 (50) Sidewalk Width(ft):
 (50) Curb Width(ft):
 (52) Culvert Barrel Length(ft):
 (34) Skew:

 (51) Bridge Roadway Width(ft):
 (52) Deck Width(ft):
 Right Wingwall Length(ft):
 Left Wingwall Length(ft):
 (32) Approach Roadway Width(ft):

 (47) Minimum Horizontal(ft):
 (55) Minimum Right Lateral(ft):
 (56) Minimum Left Lateral(ft):

297.8	
Left: 0.0	Right: 0.0
Angle(°): 45	Direction: -RIGHT FORWARD <input checked="" type="checkbox"/> -LEFT FORWARD
Cardinal	Non-Cardinal
36.0	36.0
38.5	38.5
10.8	9.0
9.0	10.8
30	0
Cardinal Under Clearance	Non-Cardinal Under Clearance
57.6	57.8
12.0	11.9
28.4	28.9

RAILING APPRAISAL

(36A) Bridge Rail Adequacy:
 (36B) Transition Adequacy:
 (36C) Approach Guardrail Adequacy:
 (36D) Guardrail Termination Adequacy:
 Outer Rail:

-SUB-STANDARD <input checked="" type="checkbox"/> -STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> -STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> -STANDARD -NOT APPLICABLE		
-SUB-STANDARD <input checked="" type="checkbox"/> -STANDARD -NOT APPLICABLE		
Left	Right	Type
		TYPE F (TWO SQUARE TUBES) - STEEL(8)
		TYPE F (3 SQUARE TUBES) - STEEL(65)
		TYPE F (4 SQUARE TUBES) - STEEL(72)
		TYPE M-STEEL 3 SQUARE TUBES(93)
X	X	SLOPED FACE PARAPET LF(91)
		SLOPED FACE PARAPET HF(92)
		VERTICAL FACE PARAPET TYPE A(74)
		TYPE W-THREE BEAM(79)
		TYPE H ON VERTICAL PARAPET(80)
		TIMBER(38)
		OTHER(99) (Please specify)
	CONT GUARD RAIL	
	NO APP GRDRL	
	NO ATTACHMENT	
5	22 MM(7/8") BOLT (Please enter quantity)	
	25 MM(1") BOLT (Please enter quantity)	
	OTHER (Please specify)	
X	(01) ENERGY ABSORBING TERMINAL/EAT	
	(02) TURN DOWN	
	(99) OTHER (Please specify)	

ROADWAY ALIGNMENT APPRAISAL

(72) Approach Alignment Appraisal:

	3 Intolerable- Substantial speed reduction
	6 Fair- Minor speed reduction
X	8 Good- No speed reduction

This page intentionally left blank