

Wisconsin Department of Transportation Salt Shed Facilities Asset Management Condition Inspection Report



| Region: | <u>Northwest</u> |
|----------------|----------------------------|
| County: | <u>Eau Claire</u> |
| Site ID: | <u>6-18-1-1</u> |
| Facility Type: | <u>Shed</u> |
| Site Address: | 2000 Spooner Ave., Altoona |
| Date: | <u>February 23, 2016</u> |
| Inspector: | Marcus Hopkins |

| Asset | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 - Bad |
|------------------|---|---------------|----------|----------|----------|---------|
| Apron and Pad | None | | Х | | | |
| Ceiling and Roof | Ceiling trusses are damaged and unrepaired. Shingles are very weathered. | | | | х | |
| Walls | Walls are moderately bowed out. Salt is seeping through the weathered wood. | | | | х | |
| Doors | None | | Х | | | |







Ceiling and Roof





Walls