

Region: North Central

County: Iron
Site ID: 7-26-24-3
Facility Type: Dome

Site Address: N5308 USH 51, Mercer

Date: March 9, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		Χ			
Ceiling and Roof	Roof repair made, roof still functioning as intended.			Х		
Walls	None		Χ			
Doors	None		Х			

