

October 30, 2009

Ms. Sharlene TeBeest
Wisconsin Department of Transportation
4802 Sheboygan Avenue
P.O. Box 7965
Madison, WI 53707

Subject: Asbestos Survey
Structure Name/Location: USH 12 over Como Creek, Walworth County
Structure Number: B-64-37
WisDOT ID Number: 1080-12-00

Dear Ms. TeBeest:

Executive Summary

RMT, Inc., conducted an asbestos survey of the above-referenced bridge on October 7, 2009 to determine if there was any potentially asbestos-containing material (ACM) located on the structure. No materials were identified as potentially ACM; therefore, the wingwall replacement of the existing bridge can proceed as planned. Standard Special Provision (STSP) 107-125 should be included in the plans.

Discussion

RMT, Inc., conducted an asbestos survey of the above-referenced bridge on October 7, 2009. The asbestos survey was conducted by John Roelke, WDHFS Asbestos Inspector Number AII-119523.

This bridge is located on USH 12 over Como Creek, Walworth County (see attached site location map).

The existing bridge is scheduled for wingwall replacement during April 2011.

Traffic control required to perform the inspection was provided by Quality Contracting.

A visual walkover of the surface and underside of the bridge was performed, at which time no potentially asbestos-containing materials were identified. Since no material was identified as potentially contained asbestos, no samples were collected.

Photographs of the bridge are attached.

P:\10944\38\B-64-37\1080-12-00_B-64-37.DOCX

Ms. Sharlene TeBeest
Wisconsin Department of Transportation
October 30, 2009
Page 2

No ACM is present on the structure; therefore, the wingwall replacement of the existing bridge can proceed as planned. Standard Special Provision (STSP) 107-125 should be included into the plans.

If you should have any questions, please call us, at (608) 831-4444.

Sincerely,

RMT, Inc.

Handwritten signature of Richard P. Fish in black ink.

Richard P. Fish
Vice President, Midwest Region


Handwritten signature of John Roelke in black ink.

John Roelke
Project Engineer

Attachments: Site Locator Map
Asbestos Survey Log and Bulk Asbestos Analytical Results
Photographs

cc: Allen Gilbertson, WisDOT
Olubunmi Olapo, WisDOT
Mike Cape, WisDOT

Map Created on Oct 30, 2009




Legend

- County Boundaries
- ✕ Railroads
- Major Highways
- Interstate
- US Highway
- State Highway
- Local Roads
- Civil Towns
- 24K Open Water
- 24K Rivers and Shorelines
- Cities and Villages
- Village
- City
- DNR Managed Lands
- Fee



Scale: 1:15,473



0 1500 3000 4500 ft.

This map is a user generated static output from an Internet mapping site and is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. THIS MAP IS NOT TO BE USED FOR NAVIGATION.

Asbestos Survey Log and Bulk Asbestos Analytical Results

Client: WisDOT

RMT Project #: 10944.38

Structure Name: USH 12
 Location: over Como Creek, Walworth County
 WisDOT Region: SE
 New Structure #: B-64-37
 WisDOT ID #: 1080-12-00

Date of Sample Collection: October 7, 2009
 Sample Collected By: John Roelke
 Asbestos Inspector #: AIL-119523
 Traffic Control By: RMT

Sample Number	Sample Location	Sample Description	Color	Condition	Quantity	Asbestos Content (%)	Friable/ Non-friable
1							
2	No suspect materials identified.						
3	No samples collected.						
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							

Notes:

ND = None Detected

IM = Insufficient Material

Condition Descriptions:

Good: The material shows no visible damage or deterioration, or shows only limited damage or deterioration.

Damaged: The material is friable that has deteriorated or sustained physical damage.

Significantly damaged: The material is friable that has sustained extensive or severe damage.



B-64-37

