

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 10738

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____


725(S)

726(S)



Rim Elevation 677.99 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.15</u>	Pipe 1 Elev. <u>673.84</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 27956

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#727(s)
#728(s)



Rim Elevation 675.85 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.8</u>	Pipe 1 Elev. <u>671.05</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 28143


☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

#729 (s)
#730 (s)



Rim Elevation 673.40 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-3.7</u>	Pipe 1 Elev. <u>669.7</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 28273

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
731 (S)
732 (S)



Rim Elevation 669.87 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.1</u>	Pipe 1 Elev. <u>665.77</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 28875

☐ Sanitary ☐ Storm ☐ Combined ☐ _____ Pic(s) _____
#733 (S)



Rim Elevation 663.30 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>u/k</u>	Pipe 1 Elev. _____	Size and Type <u>u/k</u>
Pipe 2 Depth <u>-2.7</u>	Pipe 2 Elev. <u>660.60</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open / North pipe unable to measure

Structure

Condition: ☐ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 29034

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
734 (s)
735 (s)



Rim Elevation 663.63 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-3.7</u>	Pipe 1 Elev. <u>659.93</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-3.7</u>	Pipe 2 Elev. <u>659.93</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____


STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 30222

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#735 (N)
#736 (N)

Rim Elevation 665.82 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>$5.7 \times 2 = 5.34$</u>	Pipe 1 Elev. <u>660.48</u>	Size and Type <u>± 36 in RCP</u>
Pipe 2 Depth <u>-4.6</u>	Pipe 2 Elev. <u>661.22</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth <u>$-5.8 \times 2.5 = 5.23$</u>	Pipe 3 Elev. <u>660.59</u>	Size and Type <u>± 36 in RCP</u>
Pipe 4 Depth <u>N/K</u>	Pipe 4 Elev. _____	Size and Type <u>12 in RCP</u>
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes # 4 12 in RCP / unable to measure

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31015

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#689 (N)
#690 (W)



Rim Elevation 663.49 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.05</u>	Pipe 1 Elev. <u>659.44</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.0</u>	Pipe 2 Elev. <u>659.49</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31017


☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

704 (s)
705 (s)



Rim Elevation 663.50 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.35</u>	Pipe 1 Elev. <u>659.15</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.35</u>	Pipe 2 Elev. <u>659.15</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31019

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s) _____


702 (s)

703 (s)



Rim Elevation 663.93 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.75</u>	Pipe 1 Elev. <u>659.18</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.75</u>	Pipe 2 Elev. <u>659.18</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31020

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#693(N)
#694(N)



Rim Elevation 664.35 Sump Depth _____ Sump Elevation _____
4.91

Pipe 1 Depth <u>-5.3 x 2 = 4.90</u>	Pipe 1 Elev. <u>659.45</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.9</u>	Pipe 2 Elev. <u>659.45</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth <u>-5.2 x 2 = 4.80</u>	Pipe 3 Elev. <u>659.55</u>	Size and Type <u>12 in RCP</u>
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31022

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

#691(N)

#692(N)



Rim Elevation 663.99 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.6</u>	Pipe 1 Elev. <u>659.39</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.5</u>	Pipe 2 Elev. <u>659.49</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31033

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#739 (N)
#740 (N)



Rim Elevation 665.68 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>u/k</u>	Pipe 1 Elev. _____	Size and Type _____
Pipe 2 Depth <u>u/k</u>	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth <u>-8.6</u>	Pipe 3 Elev. <u>657.08</u>	Size and Type <u>66 in RCP</u>
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes South pipe / unable to measure

Structure

East pipe / unable to measure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31050

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
695 (N)
696 (N)



Rim Elevation 665.35 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.4</u>	Pipe 1 Elev. <u>658.95</u>	Size and Type <u>36 in RCP</u>
Pipe 2 Depth <u>-4.3</u>	Pipe 2 Elev. <u>661.05</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth <u>-5.7 x (5.6)</u>	Pipe 3 Elev. <u>659.94</u>	Size and Type <u>36 in RCP</u>
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31052

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
701 (s)



Rim Elevation 665.50 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.7</u>	Pipe 1 Elev. <u>658.80</u>	Size and Type <u>36in RCP</u>
Pipe 2 Depth <u>-6.6</u>	Pipe 2 Elev. <u>658.90</u>	Size and Type <u>36in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31053

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____


737 (N)

738 (W)



Rim Elevation 671.05 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.35</u>	Pipe 1 Elev. <u>664.7</u>	Size and Type <u>24 in RCP</u>
Pipe 2 Depth <u>-4.6 x 2 = 4.14</u>	Pipe 2 Elev. <u>666.91</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth <u>-6.35</u>	Pipe 3 Elev. <u>664.7</u>	Size and Type <u>24 in RCP</u>
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31063


☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

#699 (N)
#700 (N)



Rim Elevation 671.21 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.1</u>	Pipe 1 Elev. <u>667.11</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4</u>	Pipe 2 Elev. <u>667.01</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31064

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s) _____

#697 (N)

#698 (N)

Rim Elevation 670.18

Sump Depth _____

Sump Elevation _____

Pipe 1 Depth -2.8

Pipe 1 Elev. 667.38

Size and Type 12 in RCP

Pipe 2 Depth -2.8

Pipe 2 Elev. 667.38

Size and Type 12 in RCP

Pipe 3 Depth _____

Pipe 3 Elev. _____

Size and Type _____

Pipe 4 Depth _____

Pipe 4 Elev. _____

Size and Type _____

Pipe 5 Depth _____

Pipe 5 Elev. _____

Size and Type _____

Pipe 6 Depth _____

Pipe 6 Elev. _____

Size and Type _____

Pipe 7 Depth _____

Pipe 7 Elev. _____

Size and Type _____

Pipe 8 Depth _____

Pipe 8 Elev. _____


Size and Type _____

Pipe 9 Depth _____



Pipe 9 Elev. _____

Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31430

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s)


#687 (N)

#688 (N)



Rim Elevation 666.52 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4</u>	Pipe 1 Elev. <u>662.52</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-3.9</u>	Pipe 2 Elev. <u>662.62</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31432

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____


706 (S)

707 (S)



Rim Elevation 666.54 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.3</u>	Pipe 1 Elev. <u>662.24</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.2</u>	Pipe 2 Elev. <u>662.34</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 1/24/2019 Crew WFF/SAS Point # 31435

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#685 (N)
#686 (N)



Rim Elevation 670.59 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-5.5</u>	Pipe 1 Elev. <u>665.09</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-5.4</u>	Pipe 2 Elev. <u>665.19</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31436

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#683 (N)
#684 (W)



Rim Elevation 670.72 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-5.5</u>	Pipe 1 Elev. <u>665.22</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-5.4</u>	Pipe 2 Elev. <u>665.32</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2130-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31439

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#708(s)



Rim Elevation 671.44 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.7</u>	Pipe 1 Elev. <u>664.74</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-6.6</u>	Pipe 2 Elev. <u>664.84</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31447

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#681(M)
#682(M)



Rim Elevation 673.45 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.1</u>	Pipe 1 Elev. <u>669.35</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.1</u>	Pipe 2 Elev. <u>669.35</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31448

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#709(s)



Rim Elevation 674.99 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.1</u>	Pipe 1 Elev. <u>668.89</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-6</u>	Pipe 2 Elev. <u>668.99</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes couldn't open

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31460

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
 #744 (N)
 #745 (N)



Rim Elevation 674.59 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.3</u>	Pipe 1 Elev. <u>668.29</u>	Size and Type <u>24in RCP</u>
Pipe 2 Depth <u>-6.95</u>	Pipe 2 Elev. <u>667.64</u>	Size and Type <u>24in RCP</u>
Pipe 3 Depth <u>-6.3 x 2.5^{ft}</u>	Pipe 3 Elev. <u>668.62</u>	Size and Type <u>12in RCP</u>
Pipe 4 Depth <u>-6.75 x 1.5</u>	Pipe 4 Elev. <u>668.01</u>	Size and Type <u>12in RCP</u>
Pipe 5 Depth <u>6.58</u>	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
 Quantity _____ Size _____ Condition _____

☐ Riser
 Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31463

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#742 (N)
#743 (N)



Rim Elevation 670.61 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-8.2</u>	Pipe 1 Elev. <u>662.41</u>	Size and Type <u>36 in RCP</u>
Pipe 2 Depth <u>-8.75 x 1.5 = 8.62</u>	Pipe 2 Elev. <u>661.99</u>	Size and Type <u>36 in RCP</u>
Pipe 3 Depth <u>-7.3 x 2 = 7.02</u>	Pipe 3 Elev. <u>663.59</u>	Size and Type <u>12 in RCP</u>
Pipe 4 Depth <u>-7.6 x 2 = 7.33</u>	Pipe 4 Elev. <u>663.28</u>	Size and Type <u>24 in RCP</u>
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31469

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
741 (N)



Rim Elevation 666.53 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth _____	Pipe 1 Elev. _____	Size and Type _____
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open

Structure

Condition: ☐ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2014 Crew WFF/SAS Point # 31496


☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

#675



Rim Elevation 678.14 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth $\pm$ <u>4.6</u>	Pipe 1 Elev. <u>673.54</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>4.6</u>	Pipe 2 Elev. <u>673.54</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes Unable to remove cover.

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring

Quantity _____ Size _____ Condition _____

☐ Riser

Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31497

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s)

712 (s)

713 (s)



Rim Elevation 679.67 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.2</u>	Pipe 1 Elev. <u>673.47</u>	Size and Type <u>12in RCP</u>
Pipe 2 Depth <u>-6.1</u>	Pipe 2 Elev. <u>673.57</u>	Size and Type <u>12in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31501

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

#679 (N)

#680 (N)



Rim Elevation 676.13 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.5</u>	Pipe 1 Elev. <u>671.63</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-4.5</u>	Pipe 2 Elev. <u>671.63</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31502

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____


710 (s)

711 (s)



Rim Elevation 677.67 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6</u>	Pipe 1 Elev. <u>671.67</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-6</u>	Pipe 2 Elev. <u>671.67</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31503

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s)


746 (N)

747 (N)



Rim Elevation 677.64 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-6.55</u>	Pipe 1 Elev. <u>671.09</u>	Size and Type <u>12" RCP</u>
Pipe 2 Depth <u>-6.55</u>	Pipe 2 Elev. <u>671.09</u>	Size and Type <u>12" RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring

Quantity _____ Size _____ Condition _____

☐ Riser

Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFP/SAS Point # 31523

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#748 (N)
#749 (N)



Rim Elevation 680.87 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-5</u>	Pipe 1 Elev. <u>675.87</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-6.2 x 1 6.12</u>	Pipe 2 Elev. <u>674.75</u>	Size and Type <u>24 in RCP</u>
Pipe 3 Depth <u>-5.3 x 2 4.91</u>	Pipe 3 Elev. <u>675.96</u>	Size and Type <u>12 in RCP</u>
Pipe 4 Depth <u>-6 x 1 5.91</u>	Pipe 4 Elev. <u>674.96</u>	Size and Type <u>18 in RCP</u>
Pipe 5 Depth <u>-5</u>	Pipe 5 Elev. <u>675.87</u>	Size and Type <u>12 in RCP</u>
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31526

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
7/4 (s)



Rim Elevation 681.00 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.35</u>	Pipe 1 Elev. <u>676.65</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31533

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
672 (N) 674 (N)
673 (N)



Rim Elevation 690.12 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>2.7</u>	Pipe 1 Elev. <u>687.42</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>2.6</u>	Pipe 2 Elev. <u>687.57</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open.

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring

Quantity _____ Size _____ Condition _____

☐ Riser

Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31535

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s)


715 (S)

716 (S)



Rim Elevation 692.74 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.25</u>	Pipe 1 Elev. <u>688.49</u>	Size and Type <u>12 in. RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew W/FF/SAS Point # 31885


☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

723 (S)
724 (S)



Rim Elevation 732.33 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>5.7 x 2.5 = 5.12</u>	Pipe 1 Elev. <u>727.21</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>9.35</u>	Pipe 2 Elev. <u>722.98</u>	Size and Type <u>36 in RCP</u>
Pipe 3 Depth <u>7.55 x 1 = 7.48</u>	Pipe 3 Elev. <u>724.85</u>	Size and Type <u>36 in RCP</u>
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31913

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
670 (N)
671 (N)



Rim Elevation 732.40 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.4</u>	Pipe 1 Elev. <u>728.00</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring

Quantity _____ Size _____ Condition _____

☐ Riser

Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31914

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
717 (S)
718 (S)



Rim Elevation 732.46 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-4.4</u>	Pipe 1 Elev. <u>728.06</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31972

☐ Sanitary ☒ Storm ☐ Combined ☐ _____

Pic(s) _____


721 (s)

722 (s)



Rim Elevation 752.15 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-3.4</u>	Pipe 1 Elev. <u>748.75</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth <u>-3.3</u>	Pipe 2 Elev. <u>748.85</u>	Size and Type <u>12 in PVC</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☒ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31978

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s)
750 (N)
751 (N)



Rim Elevation 752.29 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-2.7</u>	Pipe 1 Elev. <u>749.59</u>	Size and Type <u>12 in RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☐ Good ☐ Fair ☒ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31983

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____

719 (S)
720 (S)



Rim Elevation 746.74 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>- 4.9</u>	Pipe 1 Elev. <u>741.84</u>	Size and Type <u>18 in RCP</u>
Pipe 2 Depth <u>- 3.3</u>	Pipe 2 Elev. <u>743.44</u>	Size and Type <u>12 in RCP</u>
Pipe 3 Depth <u>- 3.4</u>	Pipe 3 Elev. <u>743.34</u>	Size and Type <u>12 in RCP</u>
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☒ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4/24/2019 Crew WFF/SAS Point # 31987

☐ Sanitary ☐ Storm ☐ Combined ☐ _____ Pic(s) 666 (w)
666 667 (w)



Rim Elevation 752.98 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>4.20</u>	Pipe 1 Elev. <u>748.78</u>	Size and Type <u>12" RCP</u>
Pipe 2 Depth <u>4.20</u>	Pipe 2 Elev. <u>748.78</u>	Size and Type <u>12" RCP</u>
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 4-23-19 Crew WFF/SAS Point # 42423

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) 667 (w)



Rim Elevation 753.12 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>$4.9 \times 1.0 = 4.79$</u>	Pipe 1 Elev. <u>748.33</u>	Size and Type <u>12" RCP</u>
Pipe 2 Depth <u>$5.1 \times 2.5 = 4.44$</u>	Pipe 2 Elev. <u>748.68</u>	Size and Type <u>12" RCP</u>
Pipe 3 Depth <u>$5.0 \times 1.5 = 4.76$</u>	Pipe 3 Elev. <u>748.36</u>	Size and Type <u>12" RCP</u>
Pipe 4 Depth <u>5.4</u>	Pipe 4 Elev. <u>747.72</u>	Size and Type <u>12" RCP</u>
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring

Quantity _____ Size _____ Condition _____

☐ Riser

Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT

Project 2150-00-01 Date 4-23-19 Crew WFF/SAS Point # 42424

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____
#676(N)



Rim Elevation 1676.70 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth _____	Pipe 1 Elev. _____	Size and Type _____
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☒ Manhole ☐ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes unable to open.

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☐ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 5-6-19 Crew WFF/SAS Point # 30229

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____



Rim Elevation 663.28 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>-2.4</u>	Pipe 1 Elev. <u>661.28</u>	Size and Type <u>12" RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☒ Field Inlet ☐ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____

STRUCTURE INVENTORY REPORT


Project 2150-00-01 Date 5-06-19 Crew LOFF/SAS Point # 30230

☐ Sanitary ☒ Storm ☐ Combined ☐ _____ Pic(s) _____



Rim Elevation 664.75 Sump Depth _____ Sump Elevation _____

Pipe 1 Depth <u>3.60 / 2' 9" = 2.99</u>	Pipe 1 Elev. <u>661.76</u>	Size and Type <u>12" RCP</u>
Pipe 2 Depth _____	Pipe 2 Elev. _____	Size and Type _____
Pipe 3 Depth _____	Pipe 3 Elev. _____	Size and Type _____
Pipe 4 Depth _____	Pipe 4 Elev. _____	Size and Type _____
Pipe 5 Depth _____	Pipe 5 Elev. _____	Size and Type _____
Pipe 6 Depth _____	Pipe 6 Elev. _____	Size and Type _____
Pipe 7 Depth _____	Pipe 7 Elev. _____	Size and Type _____
Pipe 8 Depth _____	Pipe 8 Elev. _____	Size and Type _____
Pipe 9 Depth _____	Pipe 9 Elev. _____	Size and Type _____

Detail Sketch



Cover Pos. and Structure Dim.



Cover Type

☐ Manhole ☐ Field Inlet ☒ Curb Inlet ☐ Catch Basin ☐ Other _____

Condition / Notes _____

Structure

Condition: ☒ Good ☐ Fair ☐ Poor

Type/Material: ☒ Conc. Precast ☐ Block ☐ Brick ☐ Other _____

Condition / Notes _____

Adjustment

☐ Ring
Quantity _____ Size _____ Condition _____

☐ Riser
Quantity _____ Size _____ Condition _____