

Date : December 18, 2018

Time: 12:00 P.M.

Description:

View from CTH AA looking east at B-3-16.



Date : December 18, 2018

Time: 12:00 P.M.

Description:

View of concrete spalling at the underside of deck at east end of north abutment of bridge B-3-16.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH AA
B-3-16
TOWN OF DOVRE, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 12:00 P.M.

Description:

Typical view of upper wing on B-3-16. Upper wings to be replaced during rehabilitation.



Date : December 18, 2018

Time: 12:00 P.M.

Description:

Damaged girder in span 2 on B-3-16. Girder to be replaced.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH AA
B-3-16
TOWN OF DOVRE, WI
BARRON COUNTY**

**SA
STRAND
ASSOCIATES®**

Date : December 18, 2018

Time: 12:00 P.M.

Description:

Typical view of bearing on B-3-16. All north abutment bearings to be replaced in rehabilitation.



Date : December 18, 2018

Time: 12:00 P.M.

Description:

View of wing on B-3-16 with spalling on deck section at abutment.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH AA
B-3-16
TOWN OF DOVRE, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 12:00 P.M.

Description:

Upper wing on B-3-16
missing a railing section.



Date : December 18, 2018

Time: 12:00 P.M.

Description:

View from roadway
looking south at B-3-16.
Bridge deck, parapets,
and railings to be
removed during rehab.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH AA
B-3-16
TOWN OF DOVRE, WI
BARRON COUNTY**

