

Date : December 18, 2018

Time: 1:00 P.M.

Description:

View from CTH A looking west at B-3-18.



Date : December 18, 2018

Time: 1:00 P.M.

Description:

View looking at girder end and bearing of B-3-18. All bearings will be replaced during rehabilitation with either steel or elastomeric bearing pads. The top flanges of the girders will be repainted prior to the placement of the new concrete deck.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH A
B-3-18
TOWN OF DOVRE, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 1:00 P.M.

Description:

View of the north abutment backwall of B-3-18 with concrete spalls.



Date : December 18, 2018

Time: 1:00 P.M.

Description:

Typical view of upper wing on B-3-18 to be replaced during rehabilitation.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH A
B-3-18
TOWN OF DOVRE, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 1:00 P.M.

Description:

View from roadway looking south at B-3-18. Concrete deck and parapets to be replaced during rehabilitation.



Date : December 18, 2018

Time: 1:00 P.M.

Description:

View from roadway looking north at B-3-18. Concrete deck, railing and parapets to be removed during rehabilitation.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH A
B-3-18
TOWN OF DOVRE, WI
BARRON COUNTY**

**SA
STRAND
ASSOCIATES®**

Date : December 18, 2018

Time: 1:00 P.M.

Description:

View of bridge deck on B-3-18. Concrete deck, railing, and parapets to be removed during rehab.



Date : December 18, 2018

Time: 1:00 P.M.

Description:

Typical cracking and spalling at concrete parapets on B-3-18.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH A
B-3-18
TOWN OF DOVRE, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®