

Date : December 18, 2018

Time: 4:00 P.M.

Description:

View from USH 53 SB
looking north at B-3-20.
Approaches to be replaced
during rehabilitation.



Date : December 18, 2018

Time: 4:00 P.M.

Description:

View looking west at
substructure of B-3-20.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over Chetek River
B-3-20
TOWN OF CHETEK, WI
BARRON COUNTY**



Date : December 18, 2018

Time: 4:00 P.M.

Description:

Typical view of chloride attack at ends of prestressed girders. Ends of all girders to be cleaned and epoxy coated during rehabilitation.



Date : December 18, 2018

Time: 2:00 P.M.

Description:

View of concrete parapet and abutment concrete spalling at B-3-20. End 1-foot of abutment diaphragms to be replaced.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over Chetek River
B-3-20
TOWN OF CHETEK, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 4:00 P.M.

Description:

Typical spalling on concrete parapet of B-3-20. Concrete parapet to be repaired during rehabilitation.



Date : December 18, 2018

Time: 4:00 P.M.

Description:

Typical view of wing and parapet at B-3-20. Entire wings and abutment end diaphragms to be replaced during rehab.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over Chetek River
B-3-20
TOWN OF CHETEK, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 4:00 P.M.

Description:

Typical existing concrete overlay cracking and popouts at overlay joints.



Date : December 18, 2018

Time: 4:00 P.M.

Description:

Spalling at abutment backwall.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over Chetek River
B-3-20
TOWN OF CHETEK, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®