

Date : December 18, 2018

Time: 2:00 P.M.

Description:

View from CTH I looking east at B-3-24.



Date : December 18, 2018

Time: 2:00 P.M.

Description:

View from CTH I looking at damaged and previously repaired girder locations in span 1 of B-3-24. Girder to be repaired during rehab.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH I
B-3-24
TOWN OF CHETEK, WI
BARRON COUNTY**



Date : December 18, 2018

Time: 2:00 P.M.

Description:

View of northwest wing on B-3-24. All wings for the structure will be removed to the footings and replaced during rehabilitation. End 1-foot of abutment diaphragms to be removed and replaced.



Date : December 18, 2018

Time: 2:00 P.M.

Description:

Wing movement at the northwest wing of B-3-24.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH I
B-3-24
TOWN OF CHETEK, WI
BARRON COUNTY**



Date : December 18, 2018

Time: 2:00 P.M.

Description:

Typical chloride attack at girders of B-3-24. Girders will be cleaned and epoxy coated during rehab.



Date : December 18, 2018

Time: 2:00 P.M.

Description:

Concrete spalling and chloride attack at the north abutment.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH I
B-3-24
TOWN OF CHETEK, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 18, 2018

Time: 2:00 P.M.

Description:

Wing movement and concrete spalling at southwest wing of B-3-24.



Date : December 18, 2018

Time: 2:00 P.M.

Description:

Concrete spalling of parapet on B-3-24.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH I
B-3-24
TOWN OF CHETEK, WI
BARRON COUNTY**



Date : December 18, 2018

Time: 2:00 P.M.

Description:

View from USH 53 SB
looking north at B-3-24.



Date : December 18, 2018

Time: 2:00 P.M.

Description:

Typical cracking and
popouts at joints in
existing concrete overlay.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over CTH I
B-3-24
TOWN OF CHETEK, WI
BARRON COUNTY**

