

Date : December 19, 2018

Time: 10:00 A.M.

Description:

View from USH 8 looking east at B-3-37.



Date : December 19, 2018

Time: 10:00 A.M.

Description:

Typical view of wing on B-3-37. Upper wings to be removed and replaced during rehabilitation.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over USH 8
B-3-37
TOWN OF STANLEY, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®

Date : December 19, 2018

Time: 10:00 A.M.

Description:

View from USH 53 SB
looking north at B-3-37.
Approaches to be
replaced during rehab.



Date : December 19, 2018

Time: 10:00 A.M.

Description:

View of south expansion
joint on B-3-37.
Expansion joints at both
abutments to be replaced
during rehabilitation.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over USH 8
B-3-37
TOWN OF STANLEY, WI
BARRON COUNTY**



Date : December 19, 2018

Time: 10:00 A.M.

Description:

Typical map cracking in existing concrete overlay.



Date : December 19, 2018

Time: 10:00 A.M.

Description:

Spalling at concrete parapet on B-3-37.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over USH 8
B-3-37
TOWN OF STANLEY, WI
BARRON COUNTY**



Date : December 19, 2018

Time: 10:00 A.M.

Description:

Vertical cracks in abutment with rust stains, typical at north and south abutments.



Date : December 19, 2018

Time: 10:00 A.M.

Description:

Spalling south abutment backwall.



**SITE PHOTOGRAPHS
FOR
STRUCTURE
SURVEY REPORT**

**USH 53 SB Over USH 8
B-3-37
TOWN OF STANLEY, WI
BARRON COUNTY**

SA
STRAND
ASSOCIATES®