

B-38-15 USH 8/141 over Crain Lane

Photos of Existing Structure



Elevation of existing bridge, looking West



Spalling at West corner of South abutment

B-38-15 USH 8/141 over Crain Lane

Photos of Existing Structure



Spalling at East corner of South abutment



Spalling in Girder 2 at South abutment

B-38-15 USH 8/141 over Crain Lane

Photos of Existing Structure



Spalling in Girder 5 at South abutment



Spalling at West corner of North abutment

B-38-15 USH 8/141 over Crain Lane
Photos of Existing Structure



Spalling at West parapet at North end of bridge



Deck cracking over piers