

ATTACHMENT C

PHOTOS OF DEFICIENT AREAS



Looking East at B-52-35



Looking West at B-52-35





NW Corner - Guardrail to Parapet Connection, Deteriorated curb (Looking East)



Spalling/Cracking in North Curb





Wing 3 (NE Wing), Shoulder Erosion (Looking West)