

ATTACHMENT C

PHOTOS OF DEFICIENT AREAS



Looking West at B-52-84



Looking East at B-52-84



Rotten guardrail posts on bridge approach



Rusted 'W' Rail



Looking South at channel from B-52-84



Looking North at channel from B-52-84



Spalling Concrete along north edge of deck



Spalling Concrete along north edge of deck