

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



East elevation

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



Top of deck, looking north

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



South expansion joint, looking east. Paving block higher than deck slab. Evidence of drainage issues.

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



North expansion joint, looking east. Portions of paving block higher than deck.

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



Underside of deck over SB lanes

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



North abutment and slope paving

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



South pier, north face

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



Exposed rebar at failed column repair. Typical several columns at the shoulder piers.

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



Center pier, north face.

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



North pier, south face

Project ID 3839-03-73 USH 12 Bridge Rehabilitation
B-64-22 CTH U over USH 12
Photos of Existing Structure



Utility (abandoned?) attached to east girder