Photos of Existing Structure



East elevation

Photos of Existing Structure



Looking north along west face

Photos of Existing Structure




Underside of deck, south span

**Photos of Existing Structure** 



South abutment and heaved slope paving. Note daylight shining through gap in backwall.

**Photos of Existing Structure** 



North abutment, east end. Deteriorated backwall, girder and, and bearing.

Photos of Existing Structure



North slope paving, cracked and heaved

Photos of Existing Structure



South pier, north face

Photos of Existing Structure



North pier, south face. North slope paving.