

ATTACHMENT C
PHOTOS OF DEFICIENT AREAS

1050-01-11
Chippewa Falls – Abbotsford
Stillson Creek to Cardinal Ave
STH 29
Chippewa and Clark Counties
Structure Photos

B-09-175



Top of Deck



Top of deck near south rail over pier 2 - Spalling



SE Corner of Structure – Streambank Erosion



SE Corner of Structure – Streambank Erosion



SE Corner of Structure – Streambank Erosion



SE Corner of Structure – Streambank Erosion