

Site Numer	Location Number	County	ROUTE	LOCATION	DESCRIPTION OF ISSUE	DESCRIPTION OF REPAIRS	Estimated Eligible Costs	Repair Complete (Y/N)	Repair Costs To Date
	B-1	Buffalo	35	By R X R underpass by high school	Culvert endwalls and 2 sections of pipe and loss of slope.	Relay pipe, endwalls and fill	\$10,000.00		
	B-2	Buffalo	35	Markee Valley Dugway	Shoulder erosion	Fill with base course	\$5,000.00		
	B-3	Buffalo	35	Dairyland offsite area	slope sluff	cleanup and ditch	\$5,000.00		
	B-4	Buffalo	35	C060011,0.208 MI N CTH N	Debris, Erosion		\$10,000.00		
	B-5	Buffalo	37	D to KK	Slope failures, shoulders washouts	Ditching, slope repair and base course	\$200,000.00		
	B-6	Buffalo	37	C060014,1.537 MI N CTH F	Debris		\$10,000.00		
	B-7	Buffalo	37	C060040,0.08 MI N CTH H	Debris		\$10,000.00		
	B-8	Buffalo	37	C060117,0.004 MI N GOSS RD	Debris, Erosion		\$10,000.00		
	B-9	Buffalo	37	C060119, 0.443 MI N GOSS RD	Debris		\$10,000.00		
	B-10	Buffalo	37	C060218,0.655 MI N CTH D	Debris		\$10,000.00		
	B-11	Buffalo	37	C060219,0.341 MI N CTH D	Debris		\$10,000.00		
	B-12	Buffalo	37	C064588,1.716 MI N STH 88	Scour Hole, Erosion		\$10,000.00		
	B-13	Buffalo	37	C064597,Cattle Pass,0.119 MI N STH 88	Scour Hole, Erosion		\$5,000.00		
	B-14	Buffalo	37	B-06-179: STH 37 over Hutchinson Creek (0.1 miles north of jct. CTH NN)	o West bank has washed out o Replace fill and rip rap		\$10,000.00		
	B-15	Buffalo	88	All of from 35 to U	Loss of culverts, slopes, washouts, debris	Repair of culverts, filling of washouts, ditching of slopes, cleaning of debris	\$500,000.00		
	B-16	Buffalo	88	C060044, LITTLE WAUMANDEE DR TRIB, 1.2 MI N CTH T	Debris, Scour Hole		\$5,000.00		
	B-17	Buffalo	88	C060002, 1.36 MI N CTH NN	Debris, Scour Hole, Erosion		\$12,000.00		
	B-18	Buffalo	88	C065705,0.97 MI N BADE RD	Scour Hole, Erosion		\$7,500.00		
	B-19	Buffalo	88	B-06-103: STH 88 over Tributary to Waumandee Creek (1.5 miles north jct. CTH O)	o West side of road is clogged with debris o Clean out inlet		\$10,000.00		
	B-20	Buffalo	95	south of E and curves to north	Shoulder erosion, sluffing @ culvert on dugway, sluffing of millings	6 loads of rock for shoulders, fill ditch and clean, add millings behind guardrail	\$15,000.00		
	B-21	Buffalo	95	By Ratz Quarry and Jacob Kiel Rd	slope washouts	clean and fill	\$5,000.00		
	B-22	Buffalo	121	West of Trempealeau County line	Loss of lane and undermined pavement	bituminous repair, ditching, fill and base course	\$15,000.00		
	B-23	Buffalo	121	Lookout bridge	washed out road around bridge, exposed foodings	60 loads of fill, 25 loads of rock, 12 loads of rip rap.	\$30,000.00		
	B-24	Buffalo	121	west of Lookout bridge	slope failures	fill slopes and ditch	\$8,000.00		
	B-25	Buffalo	121	east of CTH H	loss of one lane shoulder, blacktop	extend pipe, fill, shoulder and blacktop	\$5,000.00		
	B-26	Buffalo	121	B-06-050: STH 121 over South Fork of Elk Creek (1.3 miles east of CTH H)	o Washouts with exposed piles at the west abutment along with loss of most of the rip rap o Fill in washouts and add rip rap		\$15,000.00		
	B-27	Buffalo	121	B-06-051: STH 121 over Three Mile Creek (2.5 miles east of STH 88)	o Very large scour hole on the north side of road o Fill in Scour hole		\$15,000.00		
	B-28	Buffalo	B	West of Gilmanton	Loss of roadway lane & shoulders	50 loads, 2 trucks, 1 grader to open to traffic.	\$50,000.00		
	B-29	Buffalo	B	Sand Road	approx. 100' section loss, debris	clear, fill, base course bituminous	\$100,000.00		
	B-30	Buffalo	C	North of 95 South of CC	Shoulders and slope sluffs	clean, ditch, add base course	\$5,000.00		
	B-31	Buffalo	D	East of Modena Town line Bridge	Erosion	Need fill	\$100,000.00		
	B-32	Buffalo	E	North of 88	Shoulder erosion	Base course	\$10,000.00		
	B-33	Buffalo	E	South of 88 by Little Waumundee Creek Bridge B-6-38 and east of bridge	Loss of surface, fill and shouldrdering	fill, add, base course, and bituminous	\$18,000.00		
	B-34	Buffalo	H	1/2 mi. north of 121	Washouted bridge	138 loads fill so far	\$30,000.00		
	B-35	Buffalo	H	North Branch Elk Creek	Broken rail/deck, sediment and rip rap washed out	repair railing, clean and add rip rap	\$50,000.00		
	B-36	Buffalo	N	1/4 mile to T	Section loss, both lanes	fill 500+ loads, base course and bituminous	\$100,000.00		
	B-37	Buffalo	T	SE of CTH N	Bridge near 88, scour hole, missing rip rap, shoulders, sluffing	Add rip rap at the bridge, ditching add base course	\$5,000.00		
	B-38	Buffalo	U	South of CTH C	Erosion around bridge footing	Add slurry, fill and base course	\$10,000.00		
	B-39	Buffalo	X	North of CTH U	Erosion of bridge footings, shoulders and slopes	repair two bridges with slurry, rip rap and base course	\$30,000.00		
	T-1	Trempealeau	10	C610073, BRANCH BUFFALO R, 0.095 MI E WILLIAMS RD	Washout at NW Wing, Scour Hole		\$12,000.00		
	T-2	Trempealeau	53	C612231, Branch Trempealeau River, 0.061 MI N CTH D	Slope Erosion and Scour Hoel		\$6,000.00		
	T-3	Trempealeau	93	A (STH 93 @Deetz Rd)			\$8,000.00		
	T-4	Trempealeau	93	B (STH 93 @ Baumgarten Ln)			\$13,000.00		
	T-5	Trempealeau	93	C610042, Branch Elk Creek,1.388 MI N N JCT STH 121	Scour Holes		\$5,000.00		
	T-6	Trempealeau	93	C610051,Branch Chimney Rock Creek, 1.622 MI N CTH E	Scour Holes		\$5,000.00		
	T-7	Trempealeau	93	C610052,Branch Chimney Rock Creek, 0.037 MI N CTH VV	Scour Hole, Inlet and Outlet Slope Erosion		\$6,000.00		
	T-8	Trempealeau	93	B-61-546: STH 93-Main St. over the Buffalo River (0.3 miles north of Jct. CTH Y to the west)	o Minor washout around the Southwest Corner of the bridge. o Fill in washed out area		\$5,000.00		
	T-9	Trempealeau	93	B-61-053: STH 93 over Chimney Rock Creek (1.5 miles north of jct. CTH VV)	o Major washout at the south abutment with most of the piles exposed o Fill back in south abutment washout and use flowable fill to fill in void under the pier		\$15,000.00		
	T-10	Trempealeau	93	B-61-052: STH 93 over Chimney Rock Creek (0.3 miles north of jct. CTH VV)	o Washout around southwest wing and all rip gone at south abutment of pier o Fill in washouts and replace rip rap		\$10,000.00		
	T-11	Trempealeau	93	B-61-072: STH 93 over New City Creek (2.5 miles north of jct. CTH XX)	o South abutment rip rap wash away o Replace south abutment rip rap		\$10,000.00		
	T-12	Trempealeau	121	A (.65 mi East of CTH V)			45,800		
	T-13	Trempealeau	121	B (1.6 mi West of CTH V)			\$7,000.00		
	T-14	Trempealeau	121	C (2.2 mi West of CTH V)			\$37,000.00		
	T-15	Trempealeau	121	D (1.7mi West of CTH V)			\$15,000.00		
	T-16	Trempealeau	121	B-61-059: STH 121 over Sport Valley Creek (0.1 miles east of CTH V)	o Northeast wing has fallen over along with minor washouts on the west side and scour o Replace wing, fill in washouts and rip rap scour areas		\$20,000.00		
	T-17	Trempealeau	B	A (.5 mi West of Golden Valley Rd)			\$7,500.00		
	T-18	Trempealeau	D	A (.4 mi South of Halvorson Rd)			\$8,000.00		
	T-19	Trempealeau	E	A (Intersection of CTH E & Laurel Rd)			\$18,500.00		
	T-20	Trempealeau	H	A (.10 mi East of Sth 93)			\$20,000.00		
	T-21	Trempealeau	H	B (Intersection of CTH H & Moe Valley Rd)			\$9,000.00		
	T-22	Trempealeau	H	C (.30 mi West of CTH O)			\$18,000.00		
	T-23	Trempealeau	X	A (5.6 mi West of STH 93)			\$57,000.00		
							\$1,823,300.00		