

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 North Side (Looking South) on Crowbar Drive



Bridge B-67-114 Northwest Side (Looking Southeast) on Crowbar Drive

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 Northeast Side (Looking South) on Crowbar Drive



Bridge B-67-114 North Side (Looking South) on Crowbar Drive

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 South Approach (Looking East) on Crowbar Drive



Bridge B-67-114 South Side (Looking North) on Crowbar Drive

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 South Side (Looking North) on Crowbar Drive



Bridge B-67-114 Southwest Approach on Crowbar Drive

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 Top of Deck



Bridge B-67-114 Top of Deck

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 Top of Deck



Bridge B-67-114 Top of Deck

Design Project I.D. 1090-35-00 Rock Freeway IH 43 Rehabilitation
Bridge Crowbar Drive Over IH 43
Conditions Near Bridge B-67-114



Bridge B-67-114 Top of Deck



Bridge B-67-114 Top of Deck