

# Mettler-Toledo, LLC

Date & Time 12/9/2015 3:06:02PM  
Customer Ship-To 300467359  
Assignment Number 0330759471-003  
Terms & Conditions [www.mt.com/legal](http://www.mt.com/legal)  
Page 1 of 2

Address 1900 Polaris Parkway, Columbus, OH 43240-4035  
Phone (800) METTLER  
(800) 638-8537  
Fax (614) 438-4900

[www.mt.com](http://www.mt.com)

## Customer Ship - To Location

Wisconsin DOT

I94 & Hwy MI, Kenosha Weigh Station  
Pleasant Prairie, WI 53158

## Contact Information

Robert Spoerl

+16082668665  
[devin.mcfadden@mt.com](mailto:devin.mcfadden@mt.com)

Assignment Date	Service Assignment ID	Order Number	Customer Reference
12/9/2015	0330759471-003	0330759471	TRF 3544789

## Description of Work

Provide DMR to Devin McFadden to invoice. Flat rate \$4970 SCHEDULED FOR DEC 9

## Service Details

**Job Complete**

Labor

Date	Start
12/9/2015	08:30

Notes

LED display board is going out. Had to move lettering down. Top is burned out.  
Calibrate 3 truck scales tri-axel.

## Additional Parts and Charges

Part Number	Description	Qty	Serial Number of Device
-------------	-------------	-----	-------------------------

Additional Wait Time 0.00 hr

## Scheduled Services

Calibrate Local

3 Device(s) Completed

T.Konecny 2623

12/9/2015 3:05:36PM

Customer Signature

Date & Time



12/9/2015 3:05:07PM

Technician Signature

Date & Time

Inspector T.Konecny2623

Customer Name

Mark Alsip

Technician Name

**Devices & Services**

---

Calibrate Local

	Serial Number	Description	Asset Number(s)
1	1116999-1LD	7541	
2	11169911LD	7541	
3	11169901LD	7541AC311122_7541A,15'3-22'11-42'11X1 2ST	Drive Axel Scale