



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Adams
Site ID: 4-01-217-1
Facility Type: Shed
Site Address: 1342 County Rd. F, Adams
Date: March 28, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	See photo.			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad