



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Barron
Site ID: 8-3-10-2
Facility Type: Shed
Site Address: Augusta Street & 19th Street, Rice Lake
Date: March 21, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large cracks and potholes in pad and apron.				X	
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Apron and Pad