



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Brown
Site ID: 3-05-86-4
Facility Type: Shed
Site Address: 2198 Glendale Ave., Green Bay
Date: March 16, 2016
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	None		X			
Doors	None	X				