



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Brown  
Site ID: 3-05-86-7  
Facility Type: Hi-Arch  
Site Address: 2198 Glendale Ave., Green Bay  
Date: March 16, 2016  
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
<b>Apron and Pad</b>	None	X				
<b>Ceiling and Roof</b>	None	X				
<b>Walls</b>	None	X				
<b>Doors</b>	None	X				