



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Brown
Site ID: 3-05-87-1
Facility Type: Shed
Site Address: 5347 Steve's Cheese Rd, Denmark
Date: March 17, 2016
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	Small hole in left hand door.			X		



Doors