



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Brown
Site ID: 3-05-88-4
Facility Type: Hi-Arch
Site Address: 6756 State Rd. 57, Greenleaf
Date: March 17, 2016
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Cracking near door, some cracks sealed.				X	
Ceiling and Roof	A few shingles have tabs broken off.			X		
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof