



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Buffalo
Site ID: 5-06-500-2
Facility Type: Shed
Site Address: 360 South Eau Claire Street, Mondovi
Date: March 21, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	Some damaged ceiling trusses; temporary repairs made.			X		
Walls	None		X			
Doors	None		X			



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof