



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Buffalo
Site ID: 5-06-502-6
Facility Type: Shed
Site Address: S1672 State Rd. 37, Alma
Date: March 22, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None	X				
Doors	None		X			