



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Calumet
Site ID: 3-08-74-5
Facility Type: Shed
Site Address: N205 Military Road, Sherwood
Date: March 21, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None	X				