



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Chippewa
Site ID: 6-09-5-2
Facility Type: Shed
Site Address: 20250 County Rd. K, Cornell
Date: February 8, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None	X				
Ceiling and Roof	Roof was not visible due to snow.		X			
Walls	None	X				
Doors	Doors do not close easily due to dents in door guide rails.			X		



Doors