



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Chippewa  
Site ID: 6-09-7-1  
Facility Type: Shed  
Site Address: 8837 200<sup>th</sup> Ave., Bloomer  
Date: February 8, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	Walls on south side of shed are bowed with some cracking.			X		
Doors	None		X			



Walls