



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
 County: Chippewa
 Site ID: 6-09-7-4
 Facility Type: Shed
 Site Address: 8837 200th Ave., Bloomer
 Date: February 8, 2016
 Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Majority of pad was not visible.	X				
Ceiling and Roof	Damaged trusses throughout; all but one has been temporarily repaired.				X	
Walls	Walls are cracked along the east side of building. Pictures were taken of cracked east wall.				X	
Doors	None		X			



Ceiling and Roof



Walls



Walls