



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Clark
Site ID: 6-10-1-1
Facility Type: Shed
Site Address: 3627 Fairgrounds Ave., Neillsville
Date: February 22, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	Walls are bowed and there are several cracks. Salt is seeping through south wall.				X	
Doors	Large cracks in the doors.				X	



Walls



Walls



Walls



Doors