



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Columbia
Site ID: 1-11-346-1
Facility Type: Dome
Site Address: N3242 County Rd. J, Poynette
Date: February 9, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Slight weathering on south side shingles.			X		
Walls	None		X			
Doors	No door.		X			



Ceiling and Roof