



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Crawford
Site ID: 5-12-550-2
Facility Type: Shed
Site Address: 118 North Railroad Street, Gays Mills
Date: February 29, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Apron on east side of shed poor, but that portion of shed is empty. Apron on west end (subsite 4) is new.				X	
Ceiling and Roof	Portion of metal roof is bent.			X		
Walls	None		X			
Doors	None		X			



Apron and Pad – East End (empty)



Apron and Pad – West End (full)



Ceiling and Roof