



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Crawford
Site ID: 5-12-553-1
Facility Type: Shed
Site Address: 12335 State Rd. 131, Soldiers Grove
Date: February 29, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracking in concrete apron.			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad