



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Dane
Site ID: 1-13-1-1
Facility Type: Shed
Site Address: 2520 CTH B, Stoughton
Date: February 17, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large cracks and potholes in apron.				X	
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad