

Wisconsin Department of Transportation Salt Shed Facilities Asset Management Condition Inspection Report



Region:SouthwestCounty:DaneSite ID:1-13-12-2Facility Type:ShedSite Address:9932 STH 78, Mount Horeb (east, small shed)Date:February 16, 2016Inspector:Todd Laska

| Asset                   | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 - Bad |
|-------------------------|----------|---------------|----------|----------|----------|---------|
| Apron and Pad           | None     |               | Х        |          |          |         |
| <b>Ceiling and Roof</b> | None     |               | Х        |          |          |         |
| Walls                   | None     |               | Х        |          |          |         |
| Doors                   | None     |               | Х        |          |          |         |