



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Dodge
Site ID: 1-14-33-1
Facility Type: Shed
Site Address: 271 West Lehman, Neosho
Date: March 15, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Apron has approximately 80% alligator patterned cracking.					X
Ceiling and Roof	None		X			
Walls	Back wall bowed out.				X	
Doors	None		X			



Apron and Pad



Walls



Walls