



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Dodge
Site ID: 1-14-34-1
Facility Type: Shed
Site Address: 404 North Main, Reeseville
Date: March 15, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	See photo			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad