



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: Dodge  
Site ID: 1-14-488-1  
Facility Type: Dome  
Site Address: N8856 County Rd. A, Beaver Dam  
Date: March 14, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Apron approximately 80% alligatored, large cracks					X
Ceiling and Roof	None		X			
Walls	None	X				
Doors	None		X			



Apron and Pad



Apron and Pad



Apron and Pad