



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Door
Site ID: 3-15-355-1
Facility Type: Shed
Site Address: 1729 CTH DK/Old STH 57, Brussels
Date: February 14, 2016
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None	X				