



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Door  
Site ID: 3-15-370-1  
Facility Type: Hi-Arch  
Site Address: 1001 S. Duluth Ave., Sturgeon Bay  
Date: February 14, 2016  
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Some cracking. A few small potholes.			X		
Ceiling and Roof	Missing a few shingles on back side. Roof functioning as intended.			X		
Walls	None	X				
Doors	No door.					X



Apron and Pad



Apron and Pad



Ceiling and Roof



Doors